

# Multi-Point Inspection Checklist

RO# 6032459

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Customer Name INVENTORY: 1288712B

Advisor Name AMANDA KEPHART

Technician Name Jeremy Turner

Created on 9/18/2025 7:50 AM

Printed on 9/18/2025


 Checked and OK at this time  May Require Future Attention  Requires immediate attention

## Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only) N/A
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 2 TIRES MEASURE AT 7/32, 2 TIRES MEASURE AT 9/32
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required N/A
-   Under hood labels and decals
-   Air filter and In -Cabin Air Filter equipped ENGINE AIR FILTER DIRTY 
-   Battery cables and mount
-   Coolant level and test -40
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition

- ☒ Glass free of cracks, starts and large chips
- ☒ Dome , courtesy, map and sun visor lights and lighters and power ports
- ☒ Window operation
- ☒ Sunroof or convertible top operation
- ☒ Audio system and clock (set if required)
- ☒ Factory -installed alarm system functional
- ☒ Cigarette lighter operation, replace element if used
- ☒ Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- ☒ Truck bed, bed liner, tailgate, rear bumper
- ☒ Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
- ☒ Seats and seat belt operation for every position
- ☒ Rear defogger, check with test lights
- ☒ Headlight aim
- ☒ Trunk light and trunk trim appearance
- ☒ Hood, trunk, and fuel filler door latch
- ☒ Spare tire pressure, jack and tire wrench match vehicle and work properly
- ☒ Wheel covers and caps
- ☒ Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness **ALL BRAKES MEASURE AT 9/32**
- ☒ Differential oil level
- ☒ Engine oil and filter changed using genuine replacement parts **OIL AND FILTER CHANGED THIS VISIT**
- ☒ CHECK AND COMPLETE ALL OPEN RECALL **O OPEN RECALLS AT THIS TIME**
- ☒ OTHER
- ☒ Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- ☒ With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- ☒ Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- ☒ Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- ☒ Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager  Date 9.18.25

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	9/18/25	6032459/1
Home Phone	R/O Close Date	Receipt No.
	9/19/25	Original
Body	Mileage In	Mileage Out
	30675	30675

Year	Make	Model	License Number	Service Advisor	
2020	FORD	MUSTANG		AMANDA KEPHART	
Vehicle Identification Number		Color	Account No.	Delivery Date	In-Service Date
1FATP8UH7L5138493					

INVENTORY: 1288712B

<b>#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS</b> Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work performed by Tech 493/7      0.40hrs @ 184.25      73.70 19419537 : N-OIL (08800-BOPCKT)      6@7.10      42.60 R85348 : FILTER      1@9.58      9.58 OIL AND FILTER CHANGED.			I	
<b>#2 - 4: 56 POINT INSPECTION</b> Corrected by 4: 56 POINT INSPECTION Work performed by Tech 493/7      1.00hrs @ 169.95      169.95 56 POINT INSPECTION COMPLETED.			I	
<b>#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE</b> Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Work performed by Tech 493/7 *      0.90hrs      59.95 ROATED AND BALANCED WHEELS. SET TIRE PRESSURE TO 33 PSI.			I	
<b>#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT .</b> Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work performed by Tech 493/7 *      1.50hrs      159.95			I	
<b>#5 - RECALL: CHECK FOR OPEN RECALLS</b> Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. Work performed by Tech 493/7      0.00hrs @ NO OPEN RECALLS AT THIS TIME.			I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Year	Make	Model	License Number	Service Advisor
2020	FORD	MUSTANG		AMANDA KEPHART
Vehicle Identification Number		Color	Account No.	Delivery Date
1FATP8UH7L5138493				

INVENTORY: 1288712B

#6 \* AF: REPLACED ENGINE AIR FILTER \*ENGINE AIR FILTER  
REPLACEMENT

Corrected by AF: REPLACED ENGINE AIR FILTER

Work performed by Tech 493/7 \* 0.10hrs

FA1918 : ENGINE AIR FILTER

REPLACED ENGINE AIR FILTER.

1@29.95

10.00

29.95

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	473.55				
PARTS	82.13				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	585.67				





This report provided free of charge by:

**Deery Brothers**

200 S Gear Ave  
West Burlington, IA 52655

319-271-8758

★ **4.6 / 5.0**  
142 Verified Reviews

♥ **102**  
Customer Favorites



## Vehicle History Report™

US \$44.99

### 2020 FORD MUSTANG ECOBOOST

VIN: 1FATP8UH7L5138493

CONVERTIBLE

2.3L I4 F DOHC 16V

GASOLINE

REAR WHEEL DRIVE

[Original Window Sticker](#)

This CARFAX Report Provided  
by:

**Deery Brothers**

★ **4.6 / 5.0**

142 Verified Reviews

♥ **102** Customer Favorites



Branded Titles: Rebuilt, Salvage



**11** Service history records



**3** Previous owners



Types of owners: Rental, Personal



Last owned in Iowa



**30,675** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/23/25 at 6:50:46 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



### Accident / Damage History


Not all accidents / issues are reported to CARFAX

#### Event 1

12/14/2022

#### Accident reported

- Vehicle involved in a side impact collision with another motor vehicle
- Disabling damage reported
- Vehicle towed
- Airbags did not deploy



#### Event 2

12/14/2022

TOTAL LOSS VEHICLE



- Vehicle declared a total loss by an insurance company
- Collision damage reported

Event 3

11/14/2024


Accident reported:  
minor damage

- Vehicle involved in a side impact collision with another motor vehicle
- Functional damage reported
- Vehicle drivable
- Vehicle towed



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	09/19/2025
Tires	✓ Tires rotated	09/19/2025
 <div>This car has been recently serviced. That's a good thing!</div>		



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Owner 2

Owner 3

Total Loss

Total Loss Reported: 12/14/2022.

✓ No Issues Reported

Total Loss Reported

No New Issues Reported

Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

✓ No Issues Reported

✓ No Issues Reported

✓ No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

✓ No Issues Reported

✓ No Issues Reported

✓ No Issues Reported

<b>Odometer Check</b> No indication of an odometer rollback.	No Issues Indicated	No Issues Indicated	No Issues Indicated
<b>Accident / Damage</b> DMV title problems reported. Accidents reported: 12/14/2022 and 11/14/2024.	No Issues Reported	Severe Damage	Severe Damage
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. A current list of recalls is available at Ford Motor Company.	No Recalls Reported	No Recalls Reported	No Recalls Reported
<b>Basic Warranty</b> Original manufacturer warranty likely voided by manufacturer.	Warranty Active	<b>Warranty Voided</b>	<b>Warranty Voided</b>

<b>Title History</b>	Owner 1	Owner 2	Owner 3
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	No Problem	<b>Alert!</b> Problem Found	<b>Alert!</b> Problem Found
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	No Problem	No Problem	No Problem



**ALERT!** - Severe problems were reported by a state Department of Motor Vehicles (DMV). This vehicle does not qualify for the CARFAX Buyback Guarantee.

<b>Ownership History</b> The number of owners is estimated	Owner 1	Owner 2	Owner 3
Year purchased	2020	2021	2023
Type of owner	Rental	Personal	Personal
Estimated length of ownership	1 yr. 1 mo.	1 yr. 2 mo.	2 yrs. 1 mo.
Owned in the following states/provinces	See Details	Illinois, Iowa	Iowa
Estimated miles driven per year	10,212/yr	---	7,146/yr
Last reported odometer reading	11,287	15,062	30,675

CARFAX

Detailed History

Owner 1

Purchased: 2020

Rental Vehicle

10,212 mi/yr