

# Multi-Point Inspection Checklist

RO# 6040276

Customer Name INVENTORY: 969900

Advisor Name Jim Smith

Technician Name TYLER MCWILLIAMS

Created on 5/28/2026 7:51 AM

Printed on 5/28/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?



Checked and OK at this time



May Require Future Attention



Requires immediate attention

## Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 5/32 FRONT 8/32 REAR
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped N/A
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
  
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 8mm front and back
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER N/A
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician

Date

Service Manager

*[Handwritten Signature]*

Date

*5-28-26*

Used Car Manager

*[Handwritten Signature]*

Date

Customer

Date

<b>REPAIR ORDER - AUDIT</b>			Work Phone	R/O Open Date	R/O Number
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655				05/28/26	6040276/1
			Home Phone	R/O Close Date	Receipt No
				05/28/26	Original
			Body	Mileage In	Mileage Out
			T-350 148 <sup>th</sup> LO	40175	40177
			License Number	Service Advisor	
				Jim Smith	131
YEAR	MAKE	Model			
2024	FORD	TRANSIT PASSE			
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
1FBAX2Y87RKA80151		WHITE			

INVENTORY: 969900

#1 - MR 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FI ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work by Tech 649/4925 0.40hrs @ 195.58 19419537 : N-OIL (08800-BOPCKT) 12@9.60 12737081 : SL-N-FILTER (01836-BOPCKT) 1@12.20 CHANGED OIL AND FILTER AND TOPPED OFF ALL FLUIDS.	LL	I	78.23 115.20 12.20	8.80 51.12 5.03
#2 - MR 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 649/4925 1.00hrs @ 178.95 56 POINT INSPECTION.		I	178.95	22.00
#3 - MR GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTAT Work by Tech 649/4925* 0.90hrs BALANCED AND ROTATED TIRES.	E	I	99.00	19.80
#4 - MR ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTE COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work by Tech 649/4925* 1.50hrs ALIGNMENT PERFORMED.	D	I	159.95	33.00
#5 - MR 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS REINSTALL REAR SEAT Corrected by 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS Work by Tech 649/4925 0.50hrs @ 192.46 PUT BACK SEAT BACK IN.		I	96.23	11.00

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	05/28/26	6040276/2
Home Phone	R/O Close Date	Receipt No
	05/28/26	Original
Body	Mileage In	Mileage Out
T-350 148" LO	40175	40177

YEAR	MAKE	Model	License Number	Service Advisor	
2024	FORD	TRANSIT PASSE		Jim Smith	131
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
1FBAX2Y87RKA80151		WHITE			

INVENTORY: 969900

#6 - MR RECALL: CHECK FOR OPEN RECALLS  
CHECKED FOR RECALLS.

Account	Description	Control	Re	ference	Amount
46350	SLS-SRV-INTERNAL LABOR - OTHE	6040276		6040276	-612.36
24700	INV-WORK IN PROCESS SERVICE	964925		6040276	-94.60
66350	CST-SRV-INTERNAL LABOR - OTHE	6040276		6040276	94.60
48100	SLS-PTS-INTERNAL RO - GM	6040276		6040276	-12.20
68100	CST-PTS-INTERNAL RO - GM	6040276		6040276	5.03
24200	INVENTORY-PTS/ACC-GM	6040276		6040276	-5.03
49100	SLS-PTS-GAS OIL & GREASE	6040276		6040276	-115.20
69100	CST-PTS-GAS OIL & GREASE	6040276		6040276	51.12
24200	INVENTORY-PTS/ACC-GM	6040276		6040276	-51.12
66900	CST-SRV-MECH SHOP SUPPLIES	6040276		6040276	-29.99
24100	INVENTORY - USED TRUCKS	969900		6040276	769.75

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR	612.36				94.60
PARTS	127.40				56.15
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	769.75				150.75

This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

**2025 TOP-RATED DEALER**

★ **4.6 / 5.0**  
175 Verified Reviews

♥ **1,528**

Customer Favorites



# Report

US \$44.99

## 2024 Ford Transit 350 XLT

30,117 mi | VIN: 1FBAX2Y87RKA80151 |

Van | 3.5L V6 F DOHC 24V | Gasoline | Rear wheel drive

CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION



✂ 3 Service History Records

1 CARFAX 1-Owner Vehicle

🚗 Rental Vehicle

🌍 Last Owned in Texas

📁 8 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/28/26 at 5:33:59 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Accident / Damage History


Not all accidents / issues are reported to CARFAX

#### Event 1

10/13/2024

**Damage reported: minor damage**

#### Damage Severity Scale



### CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	01/05/2026

This car has been recently serviced. That's a good thing!

<b>CARFAX Additional History</b> Not all accidents / issues are reported to CARFAX		Owner 1
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/>	No Issues Reported
<b>Structural Damage</b> CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/>	No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/>	No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/>	No Issues Indicated
<b>Accident / Damage</b> Damage reported: 10/13/2024.		Minor Damage
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. A current list of recalls is available at Ford Motor Company.	<input checked="" type="checkbox"/>	No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have 13 months or 5,883 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/>	Warranty Active

<b>CARFAX Title History</b> CARFAX guarantees the information in this section		Owner 1
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/>	<b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/>	<b>Guaranteed</b> No Problem








**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

<b>CARFAX Ownership History</b> The number of owners is estimated		Owner 1
Year purchased		2024
Type of owner		Rental
Estimated length of ownership		1 yr. 7 mo.
Owned in the following states/provinces		Texas
Estimated miles driven per year		22,479/yr
Last reported odometer reading		30,117

<b>CARFAX Detailed History</b>			
<b>Owner 1</b> Purchased: 2024		Rental Vehicle 22,479 mi/yr	
Date	Mileage	Source	Comments
05/22/2024		Ford Motor Company	<b>Vehicle manufactured and shipped to original dealer</b> Original Window Sticker



06/05/2024		Texas Inspection Station		<b>Passed safety inspection</b>
09/03/2024	15	Texas Motor Vehicle Dept. Dallas, TX Title #01564145526084501		<b>Title issued or updated</b> - First owner reported - Loan or lien reported - Titled or registered as rental vehicle - Vehicle color noted as White
Avoid financial headaches. Make sure the loan has been paid off if you're buying from a private seller. <a href="#">Learn More</a>				
10/13/2024		Damage Report		<b>Damage reported: minor damage</b> - Damage to left front - Damage to left side
<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p><b>CARFAX HAS THE MOST ACCIDENT &amp; DAMAGE INFORMATION</b></p> </div> <div style="width: 50%;"> <div style="border: 1px solid #ccc; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;"><b>Damage Severity Scale</b></p> <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  <p><b>Minor</b></p> </div> <div style="text-align: center;"> <p>Moderate</p> </div> <div style="text-align: center;"> <p>Severe</p> </div> </div> </div> <div style="border: 1px solid #ccc; padding: 5px;"> <p style="text-align: center;"><b>Damage Location</b></p> <div style="text-align: center; margin-bottom: 5px;">FRONT</div> <div style="text-align: center; margin-bottom: 5px;">REAR</div> <div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">LEFT</div>  <div style="text-align: center;">RIGHT</div> </div> </div> <div style="border: 1px solid #ccc; padding: 5px; margin-top: 10px;"> <p>Minor damage is usually cosmetic, including dents or scratches to the vehicle body.</p> </div> </div> </div>				
12/10/2024	13,705	Caliber Auto Glass Lewisville, TX 888-461-0010 caliber.com/services/auto-glass ★ 4.7 / 5.0 3,396 Verified Reviews		<b>Vehicle serviced</b> - Glass repaired
10/13/2025	23,501	AutoNation Ford Arlington Arlington, TX 817-200-4503 autonation.com ★ 4.6 / 5.0 441 Verified Reviews ❤️ 213 Customer Favorites		<b>Vehicle serviced</b> - Battery/charging system checked - Brakes checked - Safety inspection performed - Tire condition and pressure checked
01/05/2026	30,117	Choice Quick Lube Ann Arbor, MI 313-304-0000 ★ 5.0 / 5.0 18 Verified Reviews		<b>Vehicle serviced</b> - Oil and filter changed
05/01/2026		Online Listing		<b>Vehicle offered for sale</b>

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at