

Multi-Point Inspection Checklist

RO# 6038504

Customer Name INVENTORY: 1009761

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 4/3/2026 4:16 PM

Printed on 4/27/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time May Require Future Attention Requires immediate attention

Maintenance Service

- Cold Engine start-up Pass
- Engine operation warm-up Pass
- Engine at normal operating temperature Pass
- Brake and parking operation Pass
- Active seat belt test Pass
- Clutch and transmission operations Pass
- Overdrive operation Pass
- Transfer case operation (4-wheel drive only) Pass
- Steering operation and off center Pass
- Front end alignment Pass
- Tilt steering wheel operation Pass
- Windshield wiper and washer operation at all speeds, wiper blade condition Pass
- Speedometer and odometer operation Pass
- Cruise Control operation, including resume Pass
- Heater and air condition operation Pass
- Abnormal noises and vibrations Pass
- Squeaks and rattles Pass
- Frame Check Pass
- Body surface, lower body, and upper body damage requiring body shop repair Pass
- Tire defects and damage, 5/32 7/32 all
- Drive shaft, joints, CV's and boots Pass
- Struts/shock absorbers, leaks and wear Pass
- Exhaust system leaks and damage, including catalytic converter Pass
- Fuel, oil, coolant, or other fluid leaks Pass
- Perform emissions test and/or state inspection if required Pass
- Under hood labels and decals Pass
- Air filter and In -Cabin Air Filter equipped Fail
- Battery cables and mount Pass
- Coolant level and test Pass
- Under hood fluid levels, including transmission and transfer case fluids Pass
- Drive belts and hoses Pass
- Air conditioning levels, check at sight glass Pass
- Warning lights (including air bag) gauges & horn Caution check engine light
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
- Inside and outside rearview mirror operation, adjustment, and condition Pass
- Glass free of cracks, starts and large chips Pass
- Dome , courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation Pass
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6mm all
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Year	Make	Model
2018	FORD	ESCAPE
Vehicle Identification Number		Color
1FMCU9HD9JUB31141		BLACK

Work Phone	R/O Open Date	R/O Number
	4/03/26	6038504/1
Home Phone	R/O Close Date	Receipt No.
	4/06/26	Original
Body	Mileage In	Mileage Out
SUV	101834	101834
License Number	Service Advisor	
	AMANDA KEPHART	
Account No.	Delivery Date	In-Service Date
	3/24/25	

INVENTORY: 1009761

<p>#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 256/ 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 5@9.60 48.00 P0241 : OIL FILTER 1@6.87 6.87 new oil and filter</p>	I
<p>#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95 inspection complete</p>	I
<p>#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 256/ * 1.50hrs 159.95 alینگment complete</p>	I
<p>#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 256/ * 0.90hrs 99.00 balance and rotate complete</p>	I
<p>#5 - RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:172.39 Work performed by Tech 256/ 0.00hrs @</p>	C

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	502.60				
PARTS	54.87				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	587.46				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
159 Verified Reviews

♥ **101**
Customer Favorites



Report

US \$44.99

2018 Ford Escape Sel

101,834 mi | VIN: 1FMCU9HD9JUB31141 |

4 Door Wagon/Sport Utility | 1.5L I4 F DOHC 16V | Gasoline | Front wheel drive w/ 4X4

CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION



ACCIDENT

! Accident Reported

🔧 6 Service history records

👤 2 Previous owners

🏠 Types of owners: Personal lease, Personal

🌍 Last owned in Iowa

📄 26 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/7/26 at 5:55:51 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Accident / Damage History


Not all accidents / issues are reported to CARFAX

Event 1

03/23/2022

Accident reported

- Vehicle involved in a sideswipe collision with another motor vehicle
- Airbags did not deploy



Event 2

09/20/2023

Accident reported: minor damage


Damage Severity Scale



Minor

Moderate

Severe



CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	Oil and filter changed	04/06/2026

This car has been recently serviced. That's a good thing!

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage Accidents reported: 03/23/2022 and 09/20/2023.	Accident Reported	No New Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. A current list of recalls is available at Ford Motor Company.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

CARFAX Title History

CARFAX guarantees the information in this section

	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)


CARFAX Ownership History

The number of owners is estimated

	Owner 1	Owner 2
Year purchased	2018	2025
Type of owner	Personal lease	Personal

Estimated length of ownership	3 yrs. 2 mo.	11 months
Owned in the following states/provinces	Michigan, Florida	Iowa
Estimated miles driven per year	10,745/yr	12,848/yr
Last reported odometer reading	67,714	101,834



CARFAX Detailed History








 **Owner 1**
Purchased: 2018



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Lease Vehicle
10,745 mi/yr

Date	Mileage	Source	Comments
01/11/2018		Ford Motor Company	Vehicle manufactured and shipped to original dealer Original Window Sticker 
01/18/2018	1	Friendly Ford Lot 2 Monroe, MI 734-243-6900 friendlyfordmonroe.com ★ 4.4 / 5.0 65 Verified Reviews	Vehicle offered for sale
02/26/2018	12	Friendly Ford Lincoln Inc. Monroe, MI 734-243-6000 yourfriendlyford.com/ ★ 4.6 / 5.0 172 Verified Reviews ❤️ 3,331 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed
02/27/2018	17	Friendly Ford Lot 2 Monroe, MI 734-243-6900 friendlyfordmonroe.com ★ 4.4 / 5.0 65 Verified Reviews	Vehicle sold
03/06/2018		Michigan Motor Vehicle Dept. Carleton, MI	Registration issued or renewed
03/07/2018		Michigan Motor Vehicle Dept. Carleton, MI	Titled or registered as personal lease vehicle - Loan or lien reported
03/07/2018		Michigan Motor Vehicle Dept. Carleton, MI Title #115G0650460	Title issued or updated - First owner reported
12/17/2018		Michigan Motor Vehicle Dept. Carleton, MI	Registration issued or renewed
12/04/2019		Michigan Motor Vehicle Dept. Carleton, MI	Registration issued or renewed
12/11/2020		Michigan Motor Vehicle Dept. Carleton, MI	Registration issued or renewed

03/09/2021 30,887	Friendly Ford Lincoln Inc. Monroe, MI 734-243-6000 yourfriendlyford.com/ ★ 4.6 / 5.0 172 Verified Reviews ❤️ 3,331 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Battery replaced - Brakes checked - Fluids checked - Oil and filter changed - PCM reprogrammed - Tire condition and pressure checked - Tire repaired - Tires rotated
06/01/2021 34,826	Auto Auction 	Vehicle sold <div style="border: 1px solid blue; padding: 5px;"> Millions of used vehicles are bought and sold at auction every year. </div>
06/10/2021	Florida Motor Vehicle Dept.	Vehicle purchase reported
06/24/2021	Florida Motor Vehicle Dept. Oklahoma City, OK Title #0143036563	Registration issued or renewed - Loan or lien reported - Vehicle color noted as Black
03/17/2022	Florida Motor Vehicle Dept. Oklahoma City, OK Title #0143036563	Registration issued or renewed - Loan or lien reported - Vehicle color noted as Black
03/23/2022	Damage Report 	 Accident reported - Vehicle involved in a sideswipe collision with another motor vehicle - Damage to left rear - Airbags did not deploy <div style="border: 1px solid gray; padding: 10px;"> <p style="text-align: center;">Damage Location</p> <p style="text-align: center;">FRONT</p> <div style="display: flex; justify-content: space-between; align-items: center;"> LEFT  RIGHT </div> <p style="text-align: center;">REAR</p> </div>
03/15/2023 56,022	KISSELBACK FORD Saint Cloud, FL 407-891-3246 kisselbackford.com/ ★ 4.8 / 5.0 389 Verified Reviews ❤️ 5,466 Customer Favorites	 Vehicle serviced - Maintenance inspection completed
03/22/2023	Florida Motor Vehicle Dept. Oklahoma City, OK Title #0143036563	Registration issued or renewed - Loan or lien reported - Vehicle color noted as Black
08/23/2023 67,714	Tire Choice Auto Service Centers Miami, FL 305-759-6357 https://locations.thetirechoice.com/	 Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Battery/charging system checked - Oil and filter changed

CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION