

Multi-Point Inspection Checklist

RO# 6039559

Customer Name INVENTORY: 969810

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 5/6/2026 1:23 PM

Printed on 5/20/2026












































































Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-    Cold Engine start-up Pass
-    Engine operation warm-up Pass
-    Engine at normal operating temperature Pass
-    Brake and parking operation Pass
-    Active seat belt test Pass

-    Clutch and transmission operations Pass
-    Overdrive operation Pass
-    Transfer case operation (4-wheel drive only) Pass
-    Steering operation and off center Pass
-    Front end alignment Pass
-    Tilt steering wheel operation Pass
-    Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-    Speedometer and odometer operation Pass
-    Cruise Control operation, including resume Pass
-    Heater and air condition operation Pass
-    Abnormal noises and vibrations Pass
-    Squeaks and rattles Pass
-    Frame Check Pass
-    Body surface, lower body, and upper body damage requiring body shop repair Pass
-    Tire defects and damage, 5/32 10/32 all
-    Drive shaft, joints, CV's and boots Pass
-    Struts/shock absorbers, leaks and wear Pass
-    Exhaust system leaks and damage, including catalytic converter Pass
-    Fuel, oil, coolant, or other fluid leaks Pass
-    Perform emissions test and/or state inspection if required Pass
-    Under hood labels and decals Pass
-    Air filter and In-Cabin Air Filter equipped Pass
-    Battery cables and mount Pass
-    Coolant level and test Pass
-    Under hood fluid levels, including transmission and transfer case fluids Pass
-    Drive belts and hoses Pass
-    Air conditioning levels, check at sight glass Pass
-    Warning lights (including air bag) gauges & horn Pass
-    Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-    Inside and outside rearview mirror operation, adjustment, and condition Pass
-    Glass free of cracks, starts and large chips Pass
-    Dome, courtesy, map and sun visor lights and lighters and power ports Pass

-    Window operation Pass
-    Sunroof or convertible top operation N/A
-    Audio system and clock (set if required) Pass
-    Factory -installed alarm system functional Pass
-    Cigarette lighter operation, replace element if used Pass
-    Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
-    Truck bed, bed liner, tailgate, rear bumper Pass
-    Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
-    Seats and seat belt operation for every position Pass
-    Rear defogger, check with test lights Pass
-    Headlight aim Pass
-    Trunk light and trunk trim appearance Pass
-    Hood, trunk, and fuel filler door latch Pass
-    Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
-    Wheel covers and caps Pass
-    Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 8mm front 9mm rear
-    Differential oil level Pass
-    Engine oil and filter changed using genuine replacement parts Pass
-    CHECK AND COMPLETE ALL OPEN RECALL Pass
-    OTHER
-    Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
-    With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
-    Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
-    Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
-    Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2019	FORD	F-250
Vehicle Identification Number		Color
1FT7W2BT8KED53754		WHITE

PU	87118	87118
AMANDA KEPHART	9/26/23	

INVENTORY: 969810

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 256/ 0.40hrs @ 195.57 78.23 88864038 : N-OIL (08800-BOPCKT) 13@10.79 140.27 PO6128 : OIL FILTER 1@21.75 21.75 new oil and filter installed	I	
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 256/ 1.00hrs @ 178.95 178.95 inspection complete	I	
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 256/ * 0.90hrs 99.00 wheel service complete	I	
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 256/ * 1.50hrs 159.95 alingment complete	I	
#5 - RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:184.59 Work performed by Tech 256/ 0.00hrs @	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	516.13				
PARTS	162.02				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	708.14				

This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**
 165 Verified Reviews

❤️ **1,102**
 Customer Favorites



Report

US \$44.99

2019 Ford F-250 Super Duty XL

87,125 mi | VIN: 1FT7W2BT8KED53754 |
 Crew Pickup | 6.7L V8 F OHV 32V | Diesel | Rear wheel drive w/ 4X4



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

FAIR VALUE

\$38,370 CARFAX Value



🔧 8 Service History Records

📄 At Least 1 Open Recall

👤 3 Previous Owners

🚗 Types of Owners: Commercial, Personal

🌍 Last Owned in Iowa

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/12/26 at 6:10:31 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	05/08/2026
🛞 Tires	✓ Tires rotated	05/08/2026

This car has been recently serviced. That's a good thing!

CARFAX History-Based Value Report

\$38,370

CARFAX Value

FAIR VALUE



What makes this vehicle a fair value?

- ↑ ✓ No Accidents Reported
- ↑ 🛠️ Service History

Fair Value	Good Value	Great Value	Open Recall
------------	------------	-------------	-------------

Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2	Owner 3
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.	<input checked="" type="checkbox"/> No Recalls Reported	Recall Reported	No New Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired

Title History CARFAX guarantees the information in this section	Owner 1	Owner 2	Owner 3
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

Ownership History The number of owners is estimated	Owner 1	Owner 2	Owner 3
Year purchased	2018	2020	2023
Type of owner	Commercial	Personal	Personal
Estimated length of ownership	1 yr. 2 mo.	3 yrs. 5 mo.	2 yrs. 6 mo.
Owned in the following states/provinces	See Details	Illinois	Iowa
Estimated miles driven per year	30,444/yr	—	932/yr
Last reported odometer reading	36,146	84,247	87,125

Detailed History			
Owner 1 Purchased: 2018		Commercial Vehicle 30,444 mi/yr	
Date	Mileage	Source	Comments
12/10/2018		Ford Motor Company	Vehicle manufactured and shipped to original dealer Original Window Sticker



12/27/2018		Michigan Motor Vehicle Dept.		Registration issued or renewed - Titled or registered as commercial vehicle
12/27/2018		Missouri Motor Vehicle Dept. - Saint Louis, MO		Titled or registered as commercial vehicle
12/28/2018	5	Michigan Motor Vehicle Dept. Saint Louis, MO Title #298G3610210		Title issued or updated - First owner reported
12/06/2019	36,109	Southgate Ford Southgate, MI 734-282-3636 southgateford.com ★ 4.6 / 5.0 715 Verified Reviews ❤️ 12,833 Customer Favorites		Vehicle serviced
03/04/2020	36,116	Fleet/Lease Company		Vehicle sold
03/04/2020	36,123	Auto Auction		Vehicle sold
Millions of used vehicles are bought and sold at auction every year.				
03/04/2020		Mike Murphy Ford Morton, IL 309-263-2311 mikemurphyford.com ★ 4.7 / 5.0 360 Verified Reviews ❤️ 4,154 Customer Favorites		Vehicle offered for sale
03/10/2020	36,132	Mike Murphy Ford Morton, IL 309-263-2311 mikemurphyford.com ★ 4.7 / 5.0 360 Verified Reviews ❤️ 4,154 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Key(s) (re) programmed - New key(s) cut - Oil and filter changed - Tire(s) replaced - Wiper(s) replaced
04/13/2020	36,146	Mike Murphy Ford Morton, IL 309-263-2311 mikemurphyford.com ★ 4.7 / 5.0 360 Verified Reviews ❤️ 4,154 Customer Favorites		Vehicle sold
04/13/2020		Illinois Motor Vehicle Dept.		Vehicle purchase reported
04/17/2020		Illinois Motor Vehicle Dept. Kilbourne, IL		Registration issued or renewed
04/30/2020		Ford Motor Company		Manufacturer Customer Satisfaction issued - Program #20N04 STEERING LINKAGE DAMPER Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

Owner 2
Purchased: 2020

Personal Vehicle

Date	Mileage	Source	Comments
------	---------	--------	----------