

# Multi-Point Inspection Checklist

RO# 6040073

Customer Name INVENTORY: 969830

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 5/21/2026 9:25 AM

Printed on 6/2/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation fb 10/32 rb 10/32 found the rotors to be warped causing a brake pulsation
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 ft 3/32 and extremely cupped, rear tires 9/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped Found the engine air filter to be dirty
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	5/21/26	6040073/1
Home Phone	R/O Close Date	Receipt No.
	5/27/26	Original
Body	Mileage In	Mileage Out
RWD 3500 135"	66763	66763

Year	Make	Model	License Number	Service Advisor
2023	CHEVROLET	EXPRESS PASSE		JAKE BACHTELL
Vehicle Identification Number		Color	Account No.	Delivery Date
1GAZGLFP2P1128990		WHITE		
				In-Service Date

INVENTORY: 969830

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 329/9 1.00hrs @ 178.95 Performed a 56 point inspection.				I	178.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 329/9 0.40hrs @ 195.57 78.23 19419537: N-OIL (08800-BOPCKT) 6@9.60 57.60 12737081 : SL-N-FILTER (01836-BOPCKT) 1@12.20 12.20				I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.				I	
#5 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 12.00 84612001 : SL-N-ELEMENT (03410-CT) 1@29.95 29.95 Replaced the engine air filter.				I	
#6 * 2T: 2 TIRES REPLACED - MOUNT & BALANCE 2 TIRES *TIRES - 2: LT 245/75R16 IRONMAN ALL COUNTRY Corrected by 2T: 2 TIRES REPLACED - MOUNT & BALANCE 2 TIRES LRATE:.00 Work performed by Tech 329/9 * 0.60hrs 50.00				I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

**2025 TOP-RATED DEALER**

★ **4.6 / 5.0**  
177 Verified Reviews

♥ **1,545**  
Customer Favorites




## Report

US \$44.99

### 2023 Chevrolet Express LS 3500

66,763 mi | VIN: 1GAZGLFP2P1128990 |

Van | 4.3L V6 F OHV 12V | Gasoline | Rear wheel drive



**NO ACCIDENTS REPORTED**

✓ No Accidents or Damage Reported to CARFAX

🔧 1 Service History Record

1 CARFAX 1-Owner Vehicle

🚗 Rental Vehicle

🌍 Last Owned in California

📁 5 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/30/26 at 9:03:09 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



### Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	05/27/2026
🛞 Tires	✓ Tire(s) replaced ✓ Two tires replaced	05/27/2026
🛞 Brakes	✓ Rear brake rotor(s) resurfaced	05/27/2026

This car has been recently serviced. That's a good thing!



### Additional History

Not all accidents / issues are reported to CARFAX

👤 Owner 1

#### Total Loss

No total loss reported to CARFAX.

✓ No Issues Reported

<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	<b>Warranty Expired</b>

**Title History**  
 CARFAX guarantees the information in this section

**Owner 1**

---

**Damage Brands**  
 Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

**Guaranteed**  
No Problem

---

**Odometer Brands**  
 Not Actual Mileage | Exceeds Mechanical Limits

**Guaranteed**  
No Problem

---

**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.

[View Terms](#) | [View Certificate](#)

**Ownership History**  
 The number of owners is estimated

**Owner 1**

---

Year purchased	2023
Type of owner	Rental
Estimated length of ownership	3 yrs. 2 mo.
Owned in the following states/provinces	California
Estimated miles driven per year	21,221/yr
Last reported odometer reading	66,763


**Detailed History**

---

**Owner 1**  
 Purchased: 2023

Rental Vehicle  
 21,221 mi/yr

Date	Mileage	Source	Comments
Not Reported		General Motors	<b>Original Window Sticker</b> 
03/20/2023	10	California Motor Vehicle Dept. San Diego, CA	<b>Odometer reading reported</b>
03/30/2023		California Motor Vehicle Dept. San Diego, CA	<b>Title issued or updated</b> - First owner reported - Loan or lien reported - Titled or registered as rental vehicle

05/21/2026	66,745	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 177 Verified Reviews ❤️ 1,545 Customer Favorites	<b>Vehicle offered for sale</b>
05/27/2026	66,763	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 177 Verified Reviews ❤️ 1,545 Customer Favorites	 <b>Vehicle serviced</b> - Maintenance inspection completed - Air filter replaced - Battery charged - Battery replaced - Brake rotor(s) resurfaced - Fluids checked - Oil and filter changed - Rear brake rotor(s) resurfaced - Tire(s) replaced - Two tires replaced

Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).

**CARFAX** Glossary

**First Owner**

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

**Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

**Rental**

Vehicle was registered by a rental agency.

**Title Issued**

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  [facebook.com/CARFAX](https://facebook.com/CARFAX)  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.  
5/30/26 9:03:09 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2023 CHEVROLET EXPRESS vehicle (VIN: 1GAZGLFP2P1128990), which is based on information supplied to CARFAX and available as of 5/30/26 at 10:03 AM (EDT).

Customer Signature

Date

Dealer Signature

Date

**CARFAX** Warranty Check™

CARFAX has estimated the remaining original manufacturer warranty coverage based on information reported to us on this **2023 CHEVROLET EXPRESS LS 3500 (1GAZGLFP2P1128990)**.

<b>2023 CHEVROLET EXPRESS LS 3500</b>	
VIN:	1GAZGLFP2P1128990
Estimated start date of warranty:	03/30/2023
Last CARFAX reading reported on 05/27/2026:	66,763 miles
Today's date:	05/30/2026

Type of Coverage	Original Warranty	Estimated Remaining Coverage
Basic	36 months or 36,000 miles	Coverage Expired
Drivetrain	60 months or 60,000 miles	Coverage Expired
Emissions	No data reported to CARFAX	
Corrosion	36 months or 36,000 miles	Coverage Expired
Transferable	No data reported to CARFAX	
Roadside	60 months or 60,000 miles	Coverage Expired
Safety belt & inflatable restraint	No data reported to CARFAX	
Specific Components	No data reported to CARFAX	
Notes	Corrosion Perforation coverage: 6/100,000. Courtesy Transportation coverage: 5/60,000. First Scheduled Maintenance coverage: 1/Unlimited.	

**i** CARFAX Warranty Check provides an **estimate** of this vehicle's remaining warranty coverage. It does not take into account some vehicle history events such as some title brands that may void the original manufacturer warranty or ownership transfers that may decrease warranty coverage. This warranty information is only valid for vehicles manufactured for the United States. Complete warranty coverage information is available for this vehicle at the CHEVROLET website.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.  
5/30/26 9:03:09 AM (CDT)