

# Multi-Point Inspection Checklist

RO# 6037947

Customer Name INVENTORY: 684751

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 3/16/2026 1:33 PM

Printed on 3/24/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

-  Cold Engine start-up Pass
-  Engine operation warm-up Pass
-  Engine at normal operating temperature Pass
-  Brake and parking operation Pass
-  Active seat belt test Pass
-  Clutch and transmission operations Pass
-  Overdrive operation Pass
-  Transfer case operation (4-wheel drive only) Pass
-  Steering operation and off center Pass
-  Front end alignment Pass
-  Tilt steering wheel operation Pass
-  Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-  Speedometer and odometer operation Pass
-  Cruise Control operation, including resume Pass
-  Heater and air condition operation Pass
-  Abnormal noises and vibrations Pass
-  Squeaks and rattles Pass
-  Frame Check Pass
-  Body surface, lower body, and upper body damage requiring body shop repair Pass
-  Tire defects and damage, 5/32 Fail 6/32 very choppy
-  Drive shaft, joints, CV's and boots Pass
-  Struts/shock absorbers, leaks and wear Pass
-  Exhaust system leaks and damage, including catalytic converter Pass
-  Fuel, oil, coolant, or other fluid leaks Pass
-  Perform emissions test and/or state inspection if required Pass
-  Under hood labels and decals
-  Air filter and In-Cabin Air Filter equipped Fail cabin and air
-  Battery cables and mount Pass
-  Coolant level and test Pass
-  Under hood fluid levels, including transmission and transfer case fluids Pass
-  Drive belts and hoses Pass
-  Air conditioning levels, check at sight glass Pass
-  Warning lights (including air bag) gauges & horn Pass
-  Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-  Inside and outside rearview mirror operation, adjustment, and condition Pass
-  Glass free of cracks, starts and large chips Pass
-  Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation Pass
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper Pass
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance N/A
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6mm front 8mm rear
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2022	CHEVROLET	SILVERADO 350
Vehicle Identification Number	Color	
1GC3YTE74NF149416	WHITE	

TRUCK	83734	83734
AMANDA KEPHART		

INVENTORY: 684751

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 428/8 0.40hrs @ 184.25 73.70 19432357 : N-OIL (08800-BOPCK) 8@9.60 76.80 12735811 : SL-N-FILTER (01836-BOPCKT) 1@11.23 11.23	I	
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95 inspection complete	I	
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 256/ * 0.90hrs 99.00 balanced and rotated	I	
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 256/ * 1.50hrs 159.95 alignment complete	I	
#5 - RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:180.14 Work performed by Tech 256/ 0.00hrs @	I	
#6 * AF: REPLACED ENGINE AIR FILTER	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage in	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2022	CHEVROLET	SILVERADO 350
Vehicle Identification Number		Color
1GC3YTE74NF149416		WHITE

TRUCK	83734	83734
AMANDA KEPHART		

INVENTORY: 684751

Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 256/ * 0.10hrs 19338054 : SL-N-FILTER (09786-BOPCKT) 1@29.95 new filter installed	12.00 29.95		
#7 * ICF: REPLACED IN CABIN AIR FILTER Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 256/ * 0.10hrs 84121219 : SL-N-ELEMENT (03410-CT) 1@49.95 new filter installed	12.00 49.95	I	
#8 * BRACKET: INSTALL LICENSE PLATE BRACKET Corrected by SOP: PARTS TO REPAIR YOUR VEHICLE HAD TO BE SPECIAL ORDERED. WE WILL CONTACT YOU AS SOON AS WE RECEIVE THE REQUIRED PARTS TO REPAIR YOUR VEHICLE. IF YOU HAVE ANY FURTHER QUESTIONS PLEASE CONTACT THE SERVICE LRATE:180.14 Work performed by Tech 256/ 0.00hrs @ 84186106 : N-BRACKET (07800-C) 1@43.65	Ordered	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	526.60				
PARTS	167.93				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	724.52				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
155 Verified Reviews

♥ **101**  
Customer Favorites




## Report

US \$44.99

### 2022 Chevrolet Silverado 3500HD LT

83,734 mi | VIN: 1GC3YTE74NF149416 |

Pickup | 6.6L V8 F OHV 16V | Gasoline | Rear wheel drive w/ 4X4



#### NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

#### GREAT RELIABILITY



🔧 2 Service history records

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

🌍 Last owned in Iowa

📁 12 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/19/26 at 6:17:45 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



### Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	03/18/2026
🛞 Tires	✓ Tires rotated	03/18/2026

This car has been recently serviced. That's a good thing!



### Reliability Forecast

Based on 2022 Chevrolet Silverado 3500HD LT with similar mileage

#### 3-Year Reliability Forecast



#### What makes this vehicle have great reliability?

- 🏆 Top 50% compared to similar vehicles
- Average Repair Cost

Good news! This vehicle is expected to have low risk of repair and average repair costs.



\$\$\$ \$250 avg per year

Low Likelihood of Repair

**CARFAX** Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

**Total Loss**

No total loss reported to CARFAX.

No Issues Reported

**Structural Damage**

No structural damage reported to CARFAX.

No Issues Reported

**Airbag Deployment**

No airbag deployment reported to CARFAX.

No Issues Reported

**Odometer Check**

No indication of an odometer rollback.

No Issues Indicated

**Accident / Damage**

No accidents or damage reported to CARFAX.

No Issues Reported

**Manufacturer Recall**

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

No Recalls Reported

**Basic Warranty**

Original warranty estimated to have expired.

Warranty Expired

**CARFAX** Title History

CARFAX guarantees the information in this section

Owner 1

**Damage Brands**

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

Guaranteed No Problem

**Odometer Brands**

Not Actual Mileage | Exceeds Mechanical Limits

Guaranteed No Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

**CARFAX** Ownership History

The number of owners is estimated

Owner 1

Year purchased

2021

Type of owner

Personal

Estimated length of ownership

4 yrs. 5 mo.

Owned in the following states/provinces

Iowa

Estimated miles driven per year

18,859/yr

Last reported odometer reading

83,734



**CARFAX** Detailed History

Owner 1 Purchased: 2021 Personal Vehicle  
18,859 mi/yr

Date	Mileage	Source	Comments
------	---------	--------	----------