

Multi-Point Inspection Checklist

RO# 6039345

Customer Name INVENTORY: 1009721

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 4/30/2026 11:17 AM

Printed on 5/11/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

















































 Checked and OK at this time  May Require Future Attention  Requires immediate attention




























Maintenance Service

-    Cold Engine start-up Pass
-    Engine operation warm-up Pass
-    Engine at normal operating temperature Pass
-    Brake and parking operation Pass
-    Active seat belt test Pass
-    Clutch and transmission operations Pass
-    Overdrive operation Pass
-    Transfer case operation (4-wheel drive only) Pass
-    Steering operation and off center Pass

-    Front end alignment Pass
-    Tilt steering wheel operation Pass
-    Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-    Speedometer and odometer operation Pass
-    Cruise Control operation, including resume Pass
-    Heater and air condition operation Pass
-    Abnormal noises and vibrations Pass
-    Squeaks and rattles Pass
-    Frame Check Pass
-    Body surface, lower body, and upper body damage requiring body shop repair Pass
-    Tire defects and damage, 5/32 8/32 all
-    Drive shaft, joints, CV's and boots Pass
-    Struts/shock absorbers, leaks and wear Pass
-    Exhaust system leaks and damage, including catalytic converter Pass
-    Fuel, oil, coolant, or other fluid leaks Pass
-    Perform emissions test and/or state inspection if required Pass
-    Under hood labels and decals Pass

-    Air filter and In -Cabin Air Filter equipped Pass
-    Battery cables and mount Pass
-    Coolant level and test Pass
-    Under hood fluid levels, including transmission and transfer case fluids Pass
-    Drive belts and hoses Pass
-    Air conditioning levels, check at sight glass Pass
-    Warning lights (including air bag) gauges & horn Pass
-    Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-    Inside and outside rearview mirror operation, adjustment, and condition Pass
-    Glass free of cracks, starts and large chips Pass
-    Dome , courtesy, map and sun visor lights and lighters and power ports Pass

-    Window operation Pass
-    Sunroof or convertible top operation Pass
-    Audio system and clock (set if required) Pass
-    Factory -installed alarm system functional Pass
-    Cigarette lighter operation, replace element if used Pass
-    Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
-    Truck bed, bed liner, tailgate, rear bumper Pass
-    Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
-    Seats and seat belt operation for every position Pass
-    Rear defogger, check with test lights Pass
-    Headlight aim Pass
-    Trunk light and trunk trim appearance Pass
-    Hood, trunk, and fuel filler door latch Pass
-    Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
-    Wheel covers and caps Pass
-    Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6mm front 7mm rear

-    Differential oil level Pass
-    Engine oil and filter changed using genuine replacement parts Pass
-    CHECK AND COMPLETE ALL OPEN RECALL Pass
-    OTHER
-    Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
-    With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
-    Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
-    Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
-    Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date


Year	Make	Model
2015	CHEVROLET	SILVERADO 150
Vehicle Identification Number		Color
1GCRREC6FZ393805		RED

TRUCK	92857	92862
AMANDA KEPHART		

INVENTORY: 1009721

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 256/ 0.40hrs @ 195.57 78.23 19432337 : N-OIL (08800-BOPCK) 8@9.60 76.80 12737081 : SL-N-FILTER (01836-BOPCKT) 1@10.06 10.06 new oil and filter installed	I	
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 256/ 1.00hrs @ 178.95 178.95 inspection complete	I	
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 256/ * 0.90hrs 99.00 4 tires balanced and rotated	I	
#4 - RECALL: CHECK FOR OPEN RECALLS Corrected by NCORWR: NOTIFIED CUSTOMER OF OPEN RECALL ON VEHICLE. CUSTO MER WILL RESCHEDULE AT LATER TIME. LRATE:184.59 Work performed by Tech 256/ 0.00hrs @	I	
#5 * ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 256/ * 1.50hrs 159.95 alingment complete miles out 92862	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	516.13				
PARTS	86.86				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	632.98				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
164 Verified Reviews

❤️ **105**
Customer Favorites



Report

US \$44.99

2015 Chevrolet Silverado 1500 LT

92,857 mi | VIN: 1GCRREC6FZ393805 |

4 Door Extended Cab Pickup | 5.3L V8 F OHV 16V | Gasoline | Rear wheel drive



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

CARFAX VALUE \$18,760

🔧 14 Service History Records

📄 At Least 1 Open Recall

👤 2 Previous Owners

🏠 Personal Vehicle

🌍 Last Owned in Illinois

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/2/26 at 10:38:53 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	04/30/2026
🛞 Tires	✓ Tires rotated	04/30/2026

This car has been recently serviced. That's a good thing!



History-Based Value Report




\$18,760





CARFAX Retail Value


History events affecting this vehicle's value



↑ ✓ No Accidents Reported






-   Service History
-   Personal Vehicle
-   Open Recall

 Additional History Not all accidents / issues are reported to CARFAX	 Owner 1	 Owner 2
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Check for open recalls or schedule dealer service on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

 Title History CARFAX guarantees the information in this section	 Owner 1	 Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate		

 Ownership History The number of owners is estimated	 Owner 1	 Owner 2
Year purchased	2016	2017
Type of owner	Personal	Personal
Estimated length of ownership	10 months	9 yrs. 1 mo.
Owned in the following states/provinces	Illinois	Illinois
Estimated miles driven per year	--	8,866/yr
Last reported odometer reading	10,510	92,857

 Detailed History			
 Owner 1 Purchased: 2016		Personal Vehicle	
Date	Mileage	Source	Comments






08/06/2015	1	Green Buick GMC Davenport, IA 563-823-5978 greenbuickgmc.com/ ★ 4.7 / 5.0 131 Verified Reviews ♥ 97 Customer Favorites		Vehicle offered for sale
08/07/2015	2	Green Family Chevrolet East Moline, IL 309-792-1550 greenc.com/ ★ 4.5 / 5.0 135 Verified Reviews ♥ 112 Customer Favorites		Vehicle serviced - Pre-delivery inspection completed - Door edge guards installed
02/03/2016	33	Green Family Chevrolet East Moline, IL 309-792-1550 greenc.com/ ★ 4.5 / 5.0 135 Verified Reviews ♥ 112 Customer Favorites		Vehicle sold
02/03/2016		Illinois Motor Vehicle Dept.		Vehicle purchase reported - Titled or registered as personal vehicle
02/26/2016		Illinois Motor Vehicle Dept. Moline, IL Title #160576988350		Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported - Vehicle color noted as Black
04/29/2016	3,806	Green Family Chevrolet East Moline, IL 309-792-1550 greenc.com/ ★ 4.5 / 5.0 135 Verified Reviews ♥ 112 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
10/24/2016	9,814	Green Family Chevrolet East Moline, IL 309-792-1550 greenc.com/ ★ 4.5 / 5.0 135 Verified Reviews ♥ 112 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
12/05/2016	10,501	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 164 Verified Reviews ♥ 105 Customer Favorites		Vehicle offered for sale
12/05/2016		Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 164 Verified Reviews ♥ 105 Customer Favorites		Vehicle serviced - Pre-delivery inspection completed
Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!				
12/16/2016		Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 164 Verified Reviews ♥ 105 Customer Favorites		Vehicle serviced - Vehicle washed/detailed

12/26/2016	10,502	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 164 Verified Reviews ♥ 105 Customer Favorites	Odometer reading reported
02/18/2017	10,510	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 164 Verified Reviews ♥ 105 Customer Favorites	Vehicle sold
02/18/2017		Illinois Motor Vehicle Dept.	Vehicle purchase reported
03/20/2017		Illinois Motor Vehicle Dept. Monmouth, IL	Registration issued or renewed

 **Owner 2**
Purchased: 2017

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
8,866 mi/yr

Date	Mileage	Source	Comments
03/21/2017		Illinois Motor Vehicle Dept. Monmouth, IL Title #170806964140	Title issued or updated - New owner reported - Loan or lien reported - Vehicle color noted as Black
07/11/2017	14,786	Keister's Tire Center - Monmouth Monmouth, IL 309-734-2151	 Vehicle serviced - Oil and filter changed
08/08/2017		Chevrolet Dealer West Burlington, IA	Vehicle offered for sale
10/25/2017	17,962	Moore Tires Monmouth, IL 309-715-7145 mooretires.com/ ★ 4.9 / 5.0 97 Verified Reviews ♥ 345 Customer Favorites	 Vehicle serviced - Oil and filter changed
02/14/2018		Illinois Motor Vehicle Dept. Monmouth, IL	Registration issued or renewed
03/02/2018	21,840	Moore Tires Monmouth, IL 309-715-7145 mooretires.com/ ★ 4.9 / 5.0 97 Verified Reviews ♥ 345 Customer Favorites	 Vehicle serviced - Oil and filter changed
07/26/2018		Moore Tires Monmouth, IL 309-715-7145 mooretires.com/ ★ 4.9 / 5.0 97 Verified Reviews ♥ 345 Customer Favorites	 Vehicle serviced - Tire repaired
08/24/2018	26,643	Moore Tires Monmouth, IL 309-715-7145 mooretires.com/ ★ 4.9 / 5.0 97 Verified Reviews	 Vehicle serviced - Oil and filter changed