

# Multi-Point Inspection Checklist

RO# 6039326

Customer Name INVENTORY: 500430


Advisor Name Jim Smith

Technician Name Kevin Randall

Created on 4/30/2026 7:45 AM

Printed on 4/30/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time

 May Require Future Attention

 Requires immediate attention

## Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 all 8/32
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required N/A
-   Under hood labels and decals
-   Air filter and In-Cabin Air Filter equipped
-   Battery cables and mount
-   Coolant level and test -40
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
-   Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
  
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness all 3mm PB
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
  
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager *[Signature]* \_\_\_\_\_ Date 4.30.26

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No
Body	Mileage In	Mileage Out
License Number	Service Advisor	

YEAR	MAKE	Model
2017	CHEVROLET	SILVERADO 150
Vehicle Identification Number		Color
1GCVKSEC1HZ193975		BROWN

4WD DOUBLE CA	133320	133325
Account No	Delivery Date	In-Service Date

INVENTORY: 500430

#1 - MR 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FI ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS-FILL-ALL-FLUID-LEVELS Work by Tech 425/1380 0.40hrs @ 195.58 19432337 : N-OIL (08800-BOPCK) 8@9.60 12737081 : SL-N-FILTER (01836-BOPCKT) 1@6.95 CHANGED OIL AND FILTER	LL	I	78.23 76.80 6.95	12.80 37.04 5.03
#2 - MR 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 425/1380 1.00hrs @ 178.95 PERFORMED INSPECTION		I	178.95	32.00
#3 - MR RECALL: CHECK FOR OPEN RECALLS		I		
#4 * MR BRAKEF: REPLACE FRONT BRAKE PADS AND RESURFACE ROTO BRAKE JOB - FRONT (REPLACE PADS/RESURFACE ROTORS) Corrected by BRAKEF: REPLACE FRONT BRAKE PADS AND RESURFACE ROTORS Work by Tech 425/1380* 1.80hrs 19429895 : SL-N-PAD KIT (05017-BOPCKT) 1@78.00 PERFORMED SERVICE	RS	I	215.00 78.00	57.60 64.70
#5 * MR BRAKER: REPLACE REAR BRAKE PADS AND RESURFACE ROTO BRAKE JOB - REAR (REPLACE PADS/RESURFACE ROTORS) Corrected by BRAKER: REPLACE REAR BRAKE PADS AND RESURFACE ROTORS Work by Tech 425/1380* 1.80hrs 19428015 : SL-N-PAD KIT (05017-BOPCKT) 1@78.00 PERFORMED SERVICE	RS	I	215.00 78.00	57.60 53.39
Account Description Control Re			ference	Amount
46300 SLS-SRV-INTERNAL MECH LABOR-G	6039326		6039326	-687.18
24700 INV-WORK IN PROCESS SERVICE	41380		6039326	-160.00
66300 CST-SRV-INTERNAL MECH LABOR-G	6039326		6039326	160.00
48100 SLS-PTS-INTERNAL RO - GM	6039326		6039326	-78.00

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
162 Verified Reviews

♥ **101**  
Customer Favorites



## Report

US \$44.99

### 2017 Chevrolet Silverado 1500 LTZ

133,318 mi | VIN: 1GCVKSEC1HZ193975 |

4 Door Extended Cab Pickup | 5.3L V8 F OHV 16V | Gasoline | Rear wheel drive w/ 4X4

CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION



**DAMAGE** Minor Damage



**GREAT VALUE** \$19,651

\$2,129 below \$21,780 CARFAX Value



🔧 5 Service History Records

👤 2 Previous Owners

🏠 Personal Vehicle

🌍 Last Owned in Montana

📄 31 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/30/26 at 5:45:04 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Accident / Damage History


Not all accidents / issues are reported to CARFAX

#### Event 1

09/06/2019

**Damage reported: minor damage**

**Damage Severity Scale**



### CARFAX History-Based Value Report

**\$19,651**

Listing Price\*

GREAT VALUE

**\$2,129 below**  
\$21,780 CARFAX Value ⓘ

#### What makes this vehicle a great value?

↑ 🏠 Personal Vehicle



↓ ⓘ Minor Damage

\*As reported to CARFAX as of 4/30/26 3:25:19 AM (CDT)

<b>CARFAX</b> Additional History Not all accidents / issues are reported to CARFAX	👤 Owner 1	👤 Owner 2
<b>Total Loss</b> No total loss reported to CARFAX.	✔ No Issues Reported	✔ No Issues Reported
<b>Structural Damage</b> CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✔ No Issues Reported	✔ No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	✔ No Issues Reported	✔ No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	✔ No Issues Indicated	✔ No Issues Indicated
<b>Accident / Damage</b> Damage reported: 09/06/2019.	Minor Damage	No New Issues Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	✔ No Recalls Reported	✔ No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

<b>CARFAX</b> Title History CARFAX guarantees the information in this section	👤 Owner 1	👤 Owner 2
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	✔ Guaranteed No Problem	✔ Guaranteed No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	✔ Guaranteed No Problem	✔ Guaranteed No Problem




**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

<b>CARFAX</b> Ownership History The number of owners is estimated	👤 Owner 1	👤 Owner 2
Year purchased	2017	2020
Type of owner	Personal	Personal
Estimated length of ownership	2 yrs. 9 mo.	5 yrs. 8 mo.
Owned in the following states/provinces	New York	New York, Montana
Estimated miles driven per year	30,487/yr	7,872/yr
Last reported odometer reading	83,537	133,318



<b>CARFAX</b> Detailed History			
👤 Owner 1 Purchased: 2017		Personal Vehicle 30,487 mi/yr	
Date	Mileage	Source	Comments

06/10/2017	14	New York Inspection Station	<b>Passed safety inspection</b> - Emissions inspection performed
06/26/2017		New York Motor Vehicle Dept. Glens Falls, NY	<b>Title issued or updated</b> - Registration issued or renewed - First owner reported - Titled or registered as personal vehicle - Loan or lien reported - Passed safety inspection
05/07/2018		New York Motor Vehicle Dept. Glens Falls, NY	<b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection
06/26/2018	32,403	New York Inspection Station	<b>Passed safety inspection</b> - Emissions inspection performed
06/23/2019	61,893	New York Inspection Station	<b>Passed safety inspection</b> - Passed emissions inspection
09/06/2019		Damage Report	<b>Damage reported: minor damage</b> - Damage to left side

**CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION**



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

03/27/2020		Lia Nissan of Glens Falls Queensbury, NY 518-681-3800 lianissangf.com ★ 4.7 / 5.0 195 Verified Reviews ❤️ 686 Customer Favorites	<b>Vehicle offered for sale</b>
04/02/2020		Lia Nissan of Glens Falls Queensbury, NY 518-681-3800 lianissangf.com ★ 4.7 / 5.0 195 Verified Reviews ❤️ 686 Customer Favorites	 <b>Vehicle serviced</b> - Pre-delivery inspection completed
05/13/2020		Lia Nissan of Glens Falls Queensbury, NY 518-681-3800 lianissangf.com	 <b>Vehicle serviced</b> - Pre-delivery inspection completed - Maintenance inspection completed - Air filter replaced

Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

★ 4.7 / 5.0 195 Verified Reviews

♥ 686 Customer Favorites

- Brakes checked
- Brake rotor(s) replaced
- Cabin air filter replaced/cleaned
- Drivability/performance checked
- Fluids checked
- Four tires balanced
- Four tires mounted
- Front brake pads replaced
- Front brake rotor(s) replaced
- Fuel system cleaned/serviced
- Emissions inspection performed
- Emissions or safety inspection performed
- Oil and filter changed
- Rear brake pads replaced
- Rear brake rotor(s) replaced
- Safety inspection performed
- Tire condition and pressure checked
- Wiper(s) replaced

05/25/2020	83,460	Lia Nissan of Glens Falls Queensbury, NY 518-681-3800 lianissangf.com ★ 4.7 / 5.0 195 Verified Reviews ♥ 686 Customer Favorites		<b>Vehicle sold</b>
05/28/2020	83,462	New York Inspection Station		<b>Passed safety inspection</b> - Failed emissions inspection
05/28/2020	83,537	Lia Nissan of Glens Falls Queensbury, NY 518-681-3800 lianissangf.com ★ 4.7 / 5.0 195 Verified Reviews ♥ 686 Customer Favorites		<b>Vehicle serviced</b> - Vehicle washed/detailed
05/28/2020		New York Inspection Station		<b>Passed emissions inspection</b>
05/29/2020		New York Motor Vehicle Dept. Troy, NY		<b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection

<b>Owner 2</b> Purchased: 2020	<b>Low mileage!</b> This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 7,872 mi/yr
-----------------------------------	---	---------------------------------

Date	Mileage	Source		Comments
07/06/2020		New York Motor Vehicle Dept. Troy, NY		<b>Title issued or updated</b> - New owner reported - Loan or lien reported
06/03/2021	94,949	New York Inspection Station		<b>Passed safety inspection</b> - Passed emissions inspection
11/15/2021	99,154	Inspection Co.		<b>Inspection performed</b>
06/07/2022		New York Motor Vehicle Dept. Troy, NY		<b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection
07/01/2022	105,242	New York Inspection Station		<b>Passed safety inspection</b> - Passed emissions inspection
09/05/2023		Glass America 877-734-6680 glassusa.com ★ 4.8 / 5.0 1,389 Verified Reviews		<b>Vehicle serviced</b> - Glass repaired
09/13/2023	115,259	Tire Warehouse - Troy Troy, NY		<b>Vehicle serviced</b> - Maintenance inspection completed