

# Multi-Point Inspection Checklist

RO# 6038693

Customer Name INVENTORY: 969670

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN


































































Created on 4/10/2026 2:03 PM

Printed on 4/27/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

- |  |   |   |   |
|--|---|---|---|
|    |    |    | Cold Engine start-up  |
|    |    |    | Engine operation warm-up  |
|    |    |    | Engine at normal operating temperature  |
|    |    |    | Brake and parking operation <u>fb 8/32 rb 7/32</u>  |
|    |    |    | Active seat belt test   |
|    |    |    | Clutch and transmission operations  |
|    |    |    | Overdrive operation   |
|    |    |    | Transfer case operation (4-wheel drive only)  |
|    |    |    | Steering operation and off center   |
|    |    |    | Front end alignment   |
|    |    |    | Tilt steering wheel operation   |
|    |    |    | Windshield wiper and washer operation at all speeds, wiper blade condition  |
|    |    |    | Speedometer and odometer operation  |
|   |   |   | Cruise Control operation, including resume  |
|  |  |  | Heater and air condition operation  |
|  |  |  | Abnormal noises and vibrations  |
|  |  |  | Squeaks and rattles   |
|  |  |  | Frame Check   |
|  |  |  | Body surface, lower body, and upper body damage requiring body shop repair  |
|  |  |  | Tire defects and damage, 5/32 <u>rt 8/32 rt 8/32</u>  |
|  |  |  | Drive shaft, joints, CV's and boots   |
|  |  |  | Struts/shock absorbers, leaks and wear  |
|  |  |  | Exhaust system leaks and damage, including catalytic converter  |
|  |  |  | Fuel, oil, coolant, or other fluid leaks  |
|  |  |  | Perform emissions test and/or state inspection if required  |
|  |  |  | Under hood labels and decals  |
|  |  |  | Air filter and In-Cabin Air Filter equipped   |
|  |  |  | Battery cables and mount  |
|  |  |  | Coolant level and test  |
|  |  |  | Under hood fluid levels, including transmission and transfer case fluids  |
|  |  |  | Drive belts and hoses   |
|  |  |  | Air conditioning levels, check at sight glass   |
|  |  |  | Warning lights (including air bag) gauges & horn  |
|  |  |  | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light <u>Found the license plate light to be out</u> |
|  |  |  | Inside and outside rearview mirror operation, adjustment, and condition   |
|  |  |  | Glass free of cracks, starts and large chips  |
|  |  |  | Dome, courtesy, map and sun visor lights and lighters and power ports   |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

| Year                          | Make      | Model         |
|-------------------------------|-----------|---------------|
| 2021                          | CHEVROLET | EXPRESS CARGO |
| Vehicle Identification Number |           | Color         |
| 1GCWGAFP3M1248095             |           | BLACK         |

| Work Phone     | R/O Open Date   | R/O Number      |
|----------------|-----------------|-----------------|
|                | 4/10/26         | 6038693/1       |
| Home Phone     | R/O Close Date  | Receipt No.     |
|                | 4/14/26         | Original        |
| Body           | Mileage In      | Mileage Out     |
| RWD 2500 135"  | 65300           | 65300           |
| License Number | Service Advisor |                 |
|                | JAKE BACHTELL   |                 |
| Account No.    | Delivery Date   | In-Service Date |
|                |                 |                 |

INVENTORY: 969670

|  |                         |   |
|--|-------------------------|---|
| #1 - 4: 56 POINT INSPECTION<br>Corrected by 4: 56 POINT INSPECTION LRATE:169.95<br>Work performed by Tech 329/9 1.00hrs @ 169.95   | 169.95                  | I |
| #2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL<br>ALL FLUID LEVELS<br>Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE<br>CHASSIS FILL ALL FLUID LEVELS LRATE:184.25<br>Work performed by Tech 329/9 0.40hrs @ 184.25 73.70<br>19432357 : N-OIL (08800-BOPCK) 6@9.60 57.60<br>12737081 : SL-N-FILTER (01836-BOPCKT) 1@12.20 12.20<br>Changed the engine oil and filter.   | 73.70<br>57.60<br>12.20 | I |
| #3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING<br>CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT<br>INCLUDE REPLACEMENT OF DAMAGED OR RUSTED<br>COMPONENTS AND OR PART REPLACEMENT .<br>Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE .<br>INCLUDES SETTING CASTER AND CAMBER AND TOE IF<br>ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF<br>DAMAGED OR RUSTED COMPONENTS AND OR PART<br>REPLACEMENT . LRATE:.00<br>Work performed by Tech 329/9 * 1.50hrs 159.95<br>Performed a 4 wheel alignment. | 159.95                  | I |
| #4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE<br>Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE<br>LRATE:.00<br>Work performed by Tech 329/9 * 0.90hrs 99.00<br>Balanced all four wheels and tires.   | 99.00                   | I |
| #5 * BULB: REPLACED A LIGHT BULB BULB - LICENSE PLATE LIGHT<br>Corrected by BULB: REPLACED A LIGHT BULB LRATE:.00<br>Work performed by Tech 329/9 * 0.30hrs 14.95<br>Replaced license plate bulb.  | 14.95                   | I |

|                       | INTERNAL | SERVICE CONT. | WARRANTY | CUSTOMER PAY | COST |
|-----------------------|----------|---------------|----------|--------------|------|
| LABOR                 | 517.55   |               |          |              |      |
| PARTS                 | 69.80    |               |          |              |      |
| DEDUCTIBLE            |          |               |          |              |      |
| SUBLET                |          |               |          |              |      |
| SHOP SUPPLIES         | 29.99    |               |          |              |      |
| HAZARDOUS MATERIALS   |          |               |          |              |      |
| SALES TAX OR TAX I.D. |          |               |          |              |      |
| SPECIAL ORDER DEPOSIT |          |               |          |              |      |
| DISCOUNTS             |          |               |          |              |      |
|                       | 617.34   |               |          |              |      |



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
160 Verified Reviews

♥ **101**  
Customer Favorites



## Report

US \$44.99

### 2021 Chevrolet Express 2500

65,300 mi | VIN: 1GCGWAFP3M1248095 |

Van | 4.3L V6 F OHV 24V | Gasoline | Rear wheel drive



#### NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

#### GOOD VALUE \$22,771

\$1,369 below \$24,140 CARFAX Value



🔧 18 Service History Records

1 CARFAX 1-Owner Vehicle

🚚 Commercial Vehicle

🌍 Last Owned in Nebraska

📄 28 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/18/26 at 8:56:36 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Recent Service Highlights

Key services performed in the last 12 months

| Service  | Comments   | Date       |
|----------|--|------------|
| 👑 Oil    | ✓ Oil and filter changed   | 04/14/2026 |
| 🌀 Tires  | ✓ Tires rotated  | 04/14/2026 |
| 🌀 Brakes | <ul style="list-style-type: none"> <li>✓ Front brake pads replaced</li> <li>✓ Front brake rotor(s) replaced</li> <li>✓ Rear brake pads replaced</li> <li>✓ Rear brake rotor(s) replaced</li> </ul> | 07/30/2025 |

This car has been recently serviced. That's a good thing!

### CARFAX History-Based Value Report

**\$22,771**

Listing Price\*



\*As reported to CARFAX as of 4/17/26 11:02:29 PM (CDT)

**What makes this vehicle a good value?**

- ↑  No Accidents Reported
- ↑ **1** 1-Owner Vehicle
- ↑  Service History

**CARFAX** Additional History

Not all accidents / issues are reported to CARFAX

**Owner 1**

**Total Loss**

No total loss reported to CARFAX.

No Issues Reported

**Structural Damage**

No structural damage reported to CARFAX.

No Issues Reported

**Airbag Deployment**

No airbag deployment reported to CARFAX.

No Issues Reported

**Odometer Check**

No indication of an odometer rollback.

No Issues Indicated

**Accident / Damage**

No accidents or damage reported to CARFAX.

No Issues Reported

**Manufacturer Recall**

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

No Recalls Reported

**Basic Warranty**

Original warranty estimated to have expired.

**Warranty Expired**

**CARFAX** Title History

CARFAX guarantees the information in this section

**Owner 1**

**Damage Brands**

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

**Guaranteed**  
No Problem

**Odometer Brands**

Not Actual Mileage | Exceeds Mechanical Limits

**Guaranteed**  
No Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

**CARFAX** Ownership History

The number of owners is estimated

**Owner 1**

Year purchased

2021

Type of owner

Commercial

Estimated length of ownership

4 yrs. 10 mo.

Owned in the following states/provinces

Nebraska

Estimated miles driven per year


13,352/yr

Last reported odometer reading

65,300









**CARFAX** Detailed History

 **Owner 1**  
Purchased: 2021








**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.

Commercial Vehicle  
13,352 mi/yr

| Date         | Mileage | Source  | Comments  |
|--------------|---------|---|---|
| Not Reported |         | General Motors  | <b>Original Window Sticker</b><br>  |
| 03/13/2021   | 5       | Husker Auto Group<br>Lincoln, NE<br>402-479-7500<br>huskerautomotive.com/<br>★ 4.6 / 5.0 944 Verified Reviews<br>❤️ 11,411 Customer Favorites |  <b>Vehicle serviced</b><br>- Pre-delivery inspection completed  |
| 04/24/2021   | 12      | Husker Auto Group<br>Lincoln, NE<br>402-479-7500<br>huskerautomotive.com/<br>★ 4.6 / 5.0 944 Verified Reviews<br>❤️ 11,411 Customer Favorites |  <b>Vehicle serviced</b><br>- Catalytic converter replaced   |
| 06/02/2021   |         | Nebraska<br>Motor Vehicle Dept.   | <b>Vehicle purchase reported</b>  |
| 06/06/2021   |         | Husker Auto Group<br>Lincoln, NE<br>402-479-7500<br>huskerautomotive.com/<br>★ 4.6 / 5.0 944 Verified Reviews<br>❤️ 11,411 Customer Favorites |  <b>Vehicle serviced</b><br>- Vehicle washed/detailed   |
| 07/02/2021   |         | Nebraska<br>Motor Vehicle Dept.<br>Omaha, NE  | <b>Title issued or updated</b><br>- Registration issued or renewed<br>- First owner reported<br>- Titled or registered as commercial vehicle<br>- Vehicle color noted as Black  |
| 05/23/2022   |         | Nebraska<br>Motor Vehicle Dept.<br>Omaha, NE  | <b>Registration issued or renewed</b><br>- Titled or registered as commercial vehicle<br>- Registration updated when owner moved the vehicle to a new location<br>- Vehicle color noted as Black  |
| 02/02/2023   | 25,372  | Jiffy Lube<br>Omaha, NE<br>402-334-0393<br>jiffylube.com/<br>★ 4.9 / 5.0 34 Verified Reviews<br>❤️ 1,602 Customer Favorites                   |  <b>Vehicle serviced</b><br>- Oil and filter changed   |
| 04/20/2023   | 29,964  | Jiffy Lube<br>Omaha, NE<br>402-334-0393<br>jiffylube.com/<br>★ 4.9 / 5.0 34 Verified Reviews<br>❤️ 1,602 Customer Favorites                   |  <b>Vehicle serviced</b><br>- Antifreeze/coolant checked<br>- Brake fluid checked<br>- Drive belts checked<br>- Exterior lights checked<br>- Oil and filter changed<br>- Tire condition and pressure checked<br>- Transfer case fluid checked<br>- Wipers/washers checked<br>- Vehicle washed/detailed |
| 05/31/2023   |         | Nebraska<br>Motor Vehicle Dept.   | <b>Registration issued or renewed</b><br>- Titled or registered as commercial vehicle   |

Omaha, NE

- Vehicle color noted as Black

|            |        |   |   |  |
|------------|--------|---|---|--|
| 08/02/2023 | 34,382 | Jiffy Lube<br>Omaha, NE<br>402-334-0393<br>jiffylube.com/<br>★ 4.9 / 5.0 34 Verified Reviews<br>♥ 1,602 Customer Favorites            |    | <b>Vehicle serviced</b><br>- Antifreeze/coolant checked<br>- Brake fluid checked<br>- Drive belts checked<br>- Exterior lights checked<br>- Oil and filter changed<br>- Tire condition and pressure checked<br>- Transfer case fluid checked<br>- Wipers/washers checked<br>- Vehicle washed/detailed                          |
| 11/09/2023 | 38,790 | Jiffy Lube<br>Omaha, NE<br>402-334-0393<br>jiffylube.com/<br>★ 4.9 / 5.0 34 Verified Reviews<br>♥ 1,602 Customer Favorites            |    | <b>Vehicle serviced</b><br>- Antifreeze/coolant checked<br>- Brake fluid checked<br>- Drive belts checked<br>- Exterior lights checked<br>- Oil and filter changed<br>- Tire condition and pressure checked<br>- Transfer case fluid checked<br>- Wipers/washers checked<br>- Vehicle washed/detailed                          |
| 03/11/2024 | 42,977 | Jiffy Lube<br>Omaha, NE<br>402-334-0393<br>jiffylube.com/<br>★ 4.9 / 5.0 34 Verified Reviews<br>♥ 1,602 Customer Favorites            |    | <b>Vehicle serviced</b><br>- Air filter replaced<br>- Antifreeze/coolant checked<br>- Brake fluid checked<br>- Drive belts checked<br>- Exterior lights checked<br>- Oil and filter changed<br>- Tire condition and pressure checked<br>- Transfer case fluid checked<br>- Wipers/washers checked<br>- Vehicle washed/detailed |
| 04/22/2024 |        | Nebraska<br>Motor Vehicle Dept.<br>Omaha, NE  |   | <b>Registration issued or renewed</b><br>- Titled or registered as commercial vehicle<br>- Vehicle color noted as Black  |
| 05/16/2024 | 46,271 | Jiffy Lube<br>Omaha, NE<br>402-334-0393<br>jiffylube.com/<br>★ 4.9 / 5.0 34 Verified Reviews<br>♥ 1,602 Customer Favorites            |  | <b>Vehicle serviced</b><br>- Antifreeze/coolant checked<br>- Brake fluid checked<br>- Drive belts checked<br>- Exterior lights checked<br>- Oil and filter changed<br>- Tire condition and pressure checked<br>- Transfer case fluid checked<br>- Wipers/washers checked<br>- Vehicle washed/detailed                          |
| 05/31/2024 |        | Nebraska<br>Motor Vehicle Dept.<br>Omaha, NE  |   | <b>Registration issued or renewed</b><br>- Titled or registered as commercial vehicle<br>- Vehicle color noted as Black  |
| 07/02/2024 | 48,912 | Jensen Tire & Auto<br>Omaha, NE<br>402-697-9775<br>jensontireandauto.com<br>★ 4.9 / 5.0 48 Verified Reviews<br>♥ 2 Customer Favorites |  | <b>Vehicle serviced</b><br>- Tire condition and pressure checked<br>- Tire(s) balanced   |
| 08/12/2024 | 51,031 | Jiffy Lube<br>Omaha, NE<br>402-334-0393<br>jiffylube.com/<br>★ 4.9 / 5.0 34 Verified Reviews<br>♥ 1,602 Customer Favorites            |  | <b>Vehicle serviced</b><br>- Antifreeze/coolant checked<br>- Brake fluid checked<br>- Drive belts checked<br>- Exterior lights checked<br>- Oil and filter changed<br>- Tire condition and pressure checked<br>- Transfer case fluid checked<br>- Wipers/washers checked<br>- Vehicle washed/detailed                          |
| 10/17/2024 |        | H+H Chevrolet LLC<br>Papillion, NE  |  | <b>Inspection performed</b><br>- Alignment checked   |