

Multi-Point Inspection Checklist

RO# 6036866

Customer Name INVENTORY: 739681

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry






















Created on 2/9/2026 1:25 PM








Printed on 2/10/2026










Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-  Cold Engine start-up Pass
-  Engine operation warm-up Pass
-  Engine at normal operating temperature Pass
-  Brake and parking operation Pass
-  Active seat belt test Pass
-  Clutch and transmission operations Pass
-  Overdrive operation Pass
-  Transfer case operation (4-wheel drive only) Pass
-  Steering operation and off center Pass
-  Front end alignment Pass
-  Tilt steering wheel operation Pass
-  Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-  Speedometer and odometer operation Pass
-  Cruise Control operation, including resume Pass
-  Heater and air condition operation Pass
-  Abnormal noises and vibrations Pass
-  Squeaks and rattles Pass
-  Frame Check Pass
-  Body surface, lower body, and upper body damage requiring body shop repair Pass
-  Tire defects and damage, 5/32 7/32 all
-  Drive shaft, joints, CV's and boots Pass


-  Struts/shock absorbers, leaks and wear Pass
-  Exhaust system leaks and damage, including catalytic converter Pass
-  Fuel, oil, coolant, or other fluid leaks Pass
-  Perform emissions test and/or state inspection if required Pass
-  Under hood labels and decals Pass
-  Air filter and In-Cabin Air Filter equipped Pass
-  Battery cables and mount Pass

-  Coolant level and test Pass
-  Under hood fluid levels, including transmission and transfer case fluids Pass
-  Drive belts and hoses Pass
-  Air conditioning levels, check at sight glass Pass
-  Warning lights (including air bag) gauges & horn Pass
-  Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-  Inside and outside rearview mirror operation, adjustment, and condition Pass
-  Glass free of cracks, starts and large chips Pass
-  Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 7MM ALL
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

| | |
|---|---------------------|
| Technician | Date |
| Service Manager  | Date <u>2-11-20</u> |
| Used Car Manager | Date |
| Customer | Date |

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

| | | |
|----------------|-----------------|-----------------|
| Work Phone | R/O Open Date | R/O Number |
| Home Phone | R/O Close Date | Receipt No. |
| Body | Mileage In | Mileage Out |
| SUV | 18908 | 18908 |
| License Number | Service Advisor | |
| | Jim Smith | |
| Account No. | Delivery Date | In-Service Date |
| | 4/13/23 | 4/13/23 |

| | | |
|-------------------------------|------|--------|
| Year | Make | Model |
| 2023 | GMC | ACADIA |
| Vehicle Identification Number | | Color |
| 1GKKNXLS9PZ205715 | | GRAY |

INVENTORY: 739681

| | | |
|--|---|--|
| #1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 425/ 0.40hrs @ 184.25 73.70 19432357 : N-OIL (08800-BOPCK) 6@8.25 49.50 12735811 : SL-N-FILTER (01836-BOPCKT) 1@13.60 13.60 CHANGED OIL AND FILTER | I | |
| #2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 425/ 1.00hrs @ 169.95 169.95 PERFORMED INSPECTION | I | |
| #3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 425/ * 0.90hrs 99.00 PERFORMED BALANCE AND ROTATE | I | |
| #4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 425/ * 1.50hrs 159.95 PERFORMED ALIGNMENT | I | |
| #5 - RECALL: CHECK FOR OPEN RECALLS Corrected by RECALL: CHECK FOR OPEN RECALLS LRATE:180.14 Work performed by Tech 425/ 0.00hrs @ NO OPEN RECALLS AT THIS TIME | I | |

| | INTERNAL | SERVICE CONT. | WARRANTY | CUSTOMER PAY | COST |
|-----------------------|----------|---------------|----------|--------------|------|
| LABOR | 502.60 | | | | |
| PARTS | 63.10 | | | | |
| DEDUCTIBLE | | | | | |
| SUBLET | | | | | |
| SHOP SUPPLIES | 29.99 | | | | |
| HAZARDOUS MATERIALS | | | | | |
| SALES TAX OR TAX I.D. | | | | | |
| SPECIAL ORDER DEPOSIT | | | | | |
| DISCOUNTS | | | | | |
| | 595.69 | | | | |

Display CARFAX in online listings:

739681



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
153 Verified Reviews

♥ **101**
Customer Favorites



Vehicle History Report™

US \$44.99

2023 GMC ACADIA DENALI

VIN: 1GKKNXLS9PZ205715
4 DOOR WAGON/SPORT UTILITY
3.6L V6 GASOLINE
ALL WHEEL DRIVE
Original Window Sticker
This CARFAX Report Provided by:

Deery Brothers

★ 4.6 / 5.0

153 Verified Reviews

♥ 101 Customer Favorites

✓ No accidents or damage reported to CARFAX

🛢️ Regular oil changes

👍 Good Reliability

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

📊 18,908 Last reported odometer reading





This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/14/26 at 2:14:53 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights





Key services performed in the last 12 months

| Service | Comments | Date |
|---------|--------------------------|------------|
| 🛢️ Oil | ✓ Oil and filter changed | 02/12/2026 |
| 🛞 Tires | ✓ Tires rotated | 02/12/2026 |

| | |
|---|---|
|  Title History CARFAX guarantees the information in this section | Owner 1 |
| Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon | <input checked="" type="checkbox"/> Guaranteed No Problem |
| Odometer Brands Not Actual Mileage Exceeds Mechanical Limits | <input checked="" type="checkbox"/> Guaranteed No Problem |
|  GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate | |

| | |
|---|----------------|
|  Ownership History The number of owners is estimated | Owner 1 |
| Year purchased | 2023 |
| Type of owner | Personal |
| Estimated length of ownership | 2 yrs. 9 mo. |
| Owned in the following states/provinces | Iowa |
| Estimated miles driven per year | 6,591/yr |
| Last reported odometer reading | 18,908 |



|  Detailed History | | | |
|--|--|--|--|
|  Owner 1 Purchased: 2023  | <div style="border: 1px solid blue; padding: 5px;"> Low mileage! This owner drove less than the industry average of 15,000 miles per year. </div> | Personal Vehicle 6,591 mi/yr | |
| Date | Mileage | Source | Comments |
| Not Reported | | General Motors | Original Window Sticker  |
| 04/19/2023 | 1 | Iowa Motor Vehicle Dept. Cedar Falls, IA Title #07AI45010 | Registration issued or renewed - Title or registration issued - First owner reported - Titled or registered as personal vehicle - Vehicle color noted as Gray |