

# Multi-Point Inspection Checklist

RO# 6038251

Customer Name INVENTORY: 969520

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 3/26/2026 1:21 PM

Printed on 4/3/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time

May Require Future Attention

Requires immediate attention

## Maintenance Service

- |                                     |                          |                                     |  |
|-------------------------------------|--------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Cold Engine start-up   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Engine operation warm-up   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Engine at normal operating temperature   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Brake and parking operation <u>fb 8mm rb 9mm</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Active seat belt test  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Clutch and transmission operations   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Overdrive operation  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Transfer case operation (4-wheel drive only)   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Steering operation and off center  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Front end alignment  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Tilt steering wheel operation  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Windshield wiper and washer operation at all speeds, wiper blade condition   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Speedometer and odometer operation   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Cruise Control operation, including resume   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Heater and air condition operation   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Abnormal noises and vibrations   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Squeaks and rattles  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Frame Check  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Body surface, lower body, and upper body damage requiring body shop repair   |
| <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Tire defects and damage, 5/32 <u>ft 4/32 rt 4/32</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Drive shaft, joints, CV's and boots  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Struts/shock absorbers, leaks and wear   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Exhaust system leaks and damage, including catalytic converter   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Fuel, oil, coolant, or other fluid leaks   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Perform emissions test and/or state inspection if required   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Under hood labels and decals   |
| <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Air filter and In-Cabin Air Filter equipped <u>Found the cabin and engine air filter to be dirty</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Battery cables and mount   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Coolant level and test   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Under hood fluid levels, including transmission and transfer case fluids   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Drive belts and hoses  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Air conditioning levels, check at sight glass  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Warning lights (including air bag) gauges & horn   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Inside and outside rearview mirror operation, adjustment, and condition  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Glass free of cracks, starts and large chips   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Dome , courtesy, map and sun visor lights and lighters and power ports   |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

**DEERY BROTHERS**  
 200 S Gear Ave  
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
4WD 4DR DENAL	27848	27848
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	GMC	YUKON XL
Vehicle Identification Number		Color
1GKS2KKT9PR436216		BLACK

INVENTORY: 969520

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.	I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 12735608 : SL-N-FILTER (01836-BCKT) 1@8.00 8.00 19370138 : N-OIL (08800-BOPCKT) 7@9.33 65.31 Changed the engine oil and filter.	I	73.70 8.00 65.31
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 19473528 : N-GY2755022 (05880-BOPCKT) 4@267.49 1069.96 Performed a 4 wheel alignment.	I	159.95 1069.96
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 99.00 Balanced all four wheels and tires.	I	99.00
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 12.00	I	12.00

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	3/26/26	6038251/2
Home Phone	R/O Close Date	Receipt No.
	3/27/26	Original
Body	Mileage In	Mileage Out
4WD 4DR DENAL	27848	27848
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	GMC	YUKON XL
Vehicle Identification Number		Color
1GKS2KKT9PR436216		BLACK

INVENTORY: 969520

19338054 : SL-N-FILTER (09786-BOPCKT) Replaced the cabin air filter.	1@29.95	29.95	
-----			
#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT			I
Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs		12.00	
84121219 : SL-N-ELEMENT (03410-CT) Replaced the engine air filter.	1@49.95	49.95	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	526.60				
PARTS	1223.17				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1779.76				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
159 Verified Reviews

♥ **101**  
Customer Favorites



### Report

US \$44.99

## 2023 GMC Yukon XL Denali Ultimate

27,848 mi | VIN: 1GKS2KKT9PR436216 |  
4 Door Wagon/Sport Utility | 3.0L I6 | Diesel | Rear wheel drive w/ 4X4



#### VEHICLE REACQUIRED

Reacquired by Manufacturer

#### NO ACCIDENTS REPORTED

No Accidents or Damage Reported to CARFAX

Regular oil changes

CARFAX 1-Owner vehicle

Personal vehicle

Last owned in Michigan


28 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/30/26 at 6:21:24 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	Oil and filter changed	03/27/2026
Tires	Tires rotated	03/27/2026

 This car has been recently serviced. That's a good thing!

### Additional History

Not all accidents / issues are reported to CARFAX

Owner 1


**Total Loss**  
No total loss reported to CARFAX.


No Issues Reported

**Structural Damage**  
No structural damage reported to CARFAX.




No Issues Reported











<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have 4 months or 8,152 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

<b>CARFAX Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	


**ALERT!** This vehicle was reacquired by General Motors, LLC pursuant to applicable state consumer warranty laws or to promote customer satisfaction.

<b>CARFAX Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2023
Type of owner	Personal
Estimated length of ownership	2 yrs. 7 mo.
Owned in the following states/provinces	Idaho, Michigan
Estimated miles driven per year	10,457/yr
Last reported odometer reading	27,848

<b>CARFAX Detailed History</b>			
 <b>Owner 1</b> Purchased: 2023			Personal Vehicle 10,457 mi/yr
Date	Mileage	Source	Comments
Not Reported		General Motors	<b>Original Window Sticker</b> 
07/26/2023	5	Rob Green GMC Twin Falls, ID 208-944-4073 robgreengmc.com/ ★ 4.7 / 5.0 33 Verified Reviews	 <b>Vehicle serviced</b> - Pre-delivery inspection completed

		 1 Customer Favorite		
07/29/2023		Idaho Motor Vehicle Dept.		<b>Vehicle purchase reported</b> - Titled or registered as personal vehicle
08/04/2023		Idaho Motor Vehicle Dept. Twin Falls, ID Title #230478544		<b>Registration issued or renewed</b> - Loan or lien reported - Vehicle color noted as Black
09/07/2023	1,860	Rob Green GMC Twin Falls, ID 208-944-4073 robgreengmc.com/ ★ 4.7 / 5.0 33 Verified Reviews ❤️ 1 Customer Favorite		<b>Vehicle serviced</b> - Maintenance inspection completed - Vehicle washed/detailed
10/12/2023	2,956	Rob Green Nissan Hyundai Twin Falls, ID 208-215-3193 robgreennissan.com/ ★ 4.8 / 5.0 30 Verified Reviews ❤️ 4 Customer Favorites		<b>Vehicle serviced</b>
10/26/2023	2,957	Rob Green Nissan Hyundai Twin Falls, ID 208-215-3193 robgreennissan.com/ ★ 4.8 / 5.0 30 Verified Reviews ❤️ 4 Customer Favorites		<b>Vehicle serviced</b>
10/30/2023	2,965	Rob Green GMC Twin Falls, ID 208-944-4073 robgreengmc.com/ ★ 4.7 / 5.0 33 Verified Reviews ❤️ 1 Customer Favorite		<b>Vehicle serviced</b>
10/30/2023		Service Facility		<b>Vehicle reconditioned</b>
11/13/2023		Rob Green GMC Twin Falls, ID 208-944-4073 robgreengmc.com/ ★ 4.7 / 5.0 33 Verified Reviews ❤️ 1 Customer Favorite		<b>Vehicle serviced</b> - Maintenance inspection completed - Vehicle washed/detailed
01/10/2024	4,463	Rob Green GMC Twin Falls, ID 208-944-4073 robgreengmc.com/ ★ 4.7 / 5.0 33 Verified Reviews ❤️ 1 Customer Favorite		<b>Vehicle serviced</b>
01/19/2024	5,184	Rob Green GMC Twin Falls, ID 208-944-4073 robgreengmc.com/ ★ 4.7 / 5.0 33 Verified Reviews ❤️ 1 Customer Favorite		<b>Vehicle serviced</b>
01/31/2024		Rob Green GMC Twin Falls, ID 208-944-4073 robgreengmc.com/ ★ 4.7 / 5.0 33 Verified Reviews ❤️ 1 Customer Favorite		<b>Vehicle serviced</b>