

Multi-Point Inspection Checklist

RO# 6038729

Customer Name INVENTORY: 967842

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 4/13/2026 10:03 AM

Printed on 4/27/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-    Cold Engine start-up Pass
-    Engine operation warm-up Pass
-    Engine at normal operating temperature Pass
-    Brake and parking operation Pass
-    Active seat belt test Pass
-    Clutch and transmission operations Pass
-    Overdrive operation Pass
-    Transfer case operation (4-wheel drive only) Pass
-    Steering operation and off center Pass
-    Front end alignment Pass
-    Tilt steering wheel operation Pass
-    Windshield wiper and washer operation at all speeds, wiper blade condition wipers bad
-    Speedometer and odometer operation Pass
-    Cruise Control operation, including resume Pass
-    Heater and air condition operation Pass
-    Abnormal noises and vibrations Pass
-    Squeaks and rattles Pass
-    Frame Check Pass
-    Body surface, lower body, and upper body damage requiring body shop repair Pass
-    Tire defects and damage, 5/32 8/32 all
-    Drive shaft, joints, CV's and boots Pass
-    Struts/shock absorbers, leaks and wear Pass
-    Exhaust system leaks and damage, including catalytic converter Pass
-    Fuel, oil, coolant, or other fluid leaks Pass
-    Perform emissions test and/or state inspection if required Pass
-    Under hood labels and decals Pass
-    Air filter and In-Cabin Air Filter equipped Fail air filter
-    Battery cables and mount Pass
-    Coolant level and test Pass
-    Under hood fluid levels, including transmission and transfer case fluids Pass
-    Drive belts and hoses Pass
-    Air conditioning levels, check at sight glass Pass
-    Warning lights (including air bag) gauges & horn Pass
-    Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-    Inside and outside rearview mirror operation, adjustment, and condition Pass
-    Glass free of cracks, starts and large chips Pass
-    Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 7mm all
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655


Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2018	CHEVROLET	TAHOE
Vehicle Identification Number		Color
1GNSKBKC0JR303581		

INVENTORY: 967842

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 256/ 0.40hrs @ 184.25 73.70 19420060 : N-OIL (08800-BOPCK) 8@8.10 64.80 12737081 : SL-N-FILTER (01836-BOPCKT) 1@10.06 10.06 new oil and filter installed	I	
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95 inspection complete	I	
#3 - RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:180.14 Work performed by Tech 256/ 0.00hrs @	I	
#4 * AF: REPLACED ENGINE AIR FILTER Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 256/ * 0.10hrs 12.00 23349854 : SL-N-ELEMENT (03410-CT) 1@29.95 29.95 air filter installed	I	
#5 * BLADE: REPLACED WIPER BLADES Corrected by BLADE: REPLACED WIPER BLADES LRATE:.00 Work performed by Tech 256/ * 0.10hrs 10.00 19388171 : SL-N-BLADE (10146-BOPCKT) 2@22.95 45.90 wiper blades installed	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	265.65				
PARTS	150.71				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	446.35				



This report provided free of charge by:
Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
160 Verified Reviews

♥ **101**
Customer Favorites



Report

US \$44.99

2018 Chevrolet Tahoe LT

126,526 mi | VIN: 1GNSKBKC0JR303581 |

4 Door Wagon/Sport Utility | 5.3L V8 F OHV 16V | Gasoline | Rear wheel drive w/ 4X4

CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION



🔧 8 Service History Records

👤 2 Previous Owners

🏠 Personal Vehicle

🌍 Last Owned in Iowa

📄 24 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/18/26 at 8:54:14 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX


Event 1

09/03/2024

Accident reported: minor damage

- Vehicle involved in a side impact collision with another motor vehicle
- Disabling damage reported
- Vehicle disabled
- Vehicle towed
- Airbags did not deploy

Damage Severity Scale



CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	04/14/2026

This car has been recently serviced. That's a good thing!

CARFAX History-Based Value Report

\$24,361

Listing Price*

FAIR VALUE \$23,220 CARFAX Value ⓘ



*As reported to CARFAX as of 4/17/26 10:14:00 PM (CDT)

What makes this vehicle a fair value?

- ↑ 🏠 Personal Vehicle
- ↓ 🚗 Minor Damage

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

	👤 Owner 1	👤 Owner 2
Total Loss No total loss reported to CARFAX.	✅ No Issues Reported	✅ No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✅ No Issues Reported	✅ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✅ No Issues Reported	✅ No Issues Reported
Odometer Check No indication of an odometer rollback.	✅ No Issues Indicated	✅ No Issues Indicated
Accident / Damage Accident reported: 09/03/2024.	✅ No Issues Reported	Accident Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	✅ No Recalls Reported	✅ No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

CARFAX Title History

CARFAX guarantees the information in this section

	👤 Owner 1	👤 Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	✅ Guaranteed No Problem	✅ Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	✅ Guaranteed No Problem	✅ Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
View Terms | View Certificate

CARFAX Ownership History






The number of owners is estimated

	👤 Owner 1	👤 Owner 2
Year purchased	2018	2023
Type of owner	Personal	Personal
Estimated length of ownership	5 yrs. 5 mo.	2 yrs. 4 mo.

Owned in the following states/provinces	Iowa	Iowa
Estimated miles driven per year	16,227/yr	15,779/yr
Last reported odometer reading	65,976	126,526

 Detailed History


 **Owner 1** Personal Vehicle
Purchased: 2018 16,227 mi/yr

Date	Mileage	Source	Comments
04/04/2018	1	Green Buick GMC Davenport, IA 563-823-5978 greenbuickgmc.com/ ★ 4.7 / 5.0 130 Verified Reviews ♥ 97 Customer Favorites	Vehicle offered for sale
04/10/2018	2	Green Family Chevrolet East Moline, IL 309-792-1550 greenc.com/ ★ 4.5 / 5.0 133 Verified Reviews ♥ 112 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed
06/01/2018		Iowa Motor Vehicle Dept. Homestead, IA	Titled or registered as personal vehicle
06/15/2018	14	Green Family Chevrolet East Moline, IL 309-792-1550 greenc.com/ ★ 4.5 / 5.0 133 Verified Reviews ♥ 112 Customer Favorites	 Vehicle serviced
06/25/2018		Iowa Motor Vehicle Dept. Homestead, IA Title #48AA81307	Title or registration issued - First owner reported - Vehicle color noted as Black
11/08/2018	7,865	Billion Automotive Iowa City, IA 319-354-1011 billionauto.com ★ 4.2 / 5.0 86 Verified Reviews ♥ 141 Customer Favorites	 Vehicle serviced - Battery replaced
06/13/2019		Iowa Motor Vehicle Dept. Homestead, IA Title #48AA81307	Registration issued or renewed - Vehicle color noted as Black
10/08/2019		Iowa Motor Vehicle Dept. Homestead, IA Title #48AA81307	Registration issued or renewed - Correction to record - Vehicle color noted as Black
11/19/2019	23,069	Charles Capper Auto Center Marengo, IA 319-642-5525 capperchevy.com/ ★ 5.0 / 5.0 13 Verified Reviews	 Vehicle serviced - Engine/powertrain computer/module checked
03/04/2020	28,370	Charles Capper Auto Center Marengo, IA	 Vehicle serviced - Computer(s) checked

319-642-5525
capperchevy.com/

- Evaporative emissions vent purge valve replaced

★ 5.0 / 5.0 13 Verified Reviews

06/08/2020		Iowa Motor Vehicle Dept. Homestead, IA Title #48AA81307		Registration issued or renewed - Vehicle color noted as Black
06/07/2021		Iowa Motor Vehicle Dept. Homestead, IA Title #48AA98887		Registration issued or renewed - Vehicle color noted as Black
06/16/2022		Iowa Motor Vehicle Dept. Homestead, IA Title #48AA98887		Registration issued or renewed - Vehicle color noted as Black
06/24/2022	65,976	Charles Capper Auto Center Marengo, IA 319-642-5525 capperchevy.com/ ★ 5.0 / 5.0 13 Verified Reviews		Vehicle serviced - Blower motor replaced/repared - Four tires balanced - Four tires mounted - Noise checked
06/08/2023		Iowa Motor Vehicle Dept. Homestead, IA Title #48AA98887		Registration issued or renewed - Vehicle color noted as Black

 **Owner 2**
Purchased: 2023 Personal Vehicle
15,779 mi/yr

Date	Mileage	Source	Comments
11/29/2023	89,044	Iowa Motor Vehicle Dept. Ottumwa, IA Title #90AC84388	Title or registration issued - New owner reported - Vehicle color noted as Black
03/05/2024		Iowa Motor Vehicle Dept. Ottumwa, IA Title #90AC84388	Registration issued or renewed - Vehicle color noted as Black
09/03/2024		Damage Report	Accident reported: minor damage - Vehicle involved in a side impact collision with another motor vehicle - Damage to left rear - Damage to left side - Disabling damage reported - Vehicle disabled - Vehicle towed - Airbags did not deploy

Damage Severity Scale



Minor
Moderate
Severe

**CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION**