

Multi-Point Inspection Checklist

RO# 6033679

Customer Name INVENTORY: 684561

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 10/27/2025 1:57 PM

Printed on 10/28/2025

Did your Service Advisor review the results of this multi-point inspection checklist with you?

-  Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation fb 9mm rb 8mm
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 ft 5/32 rt 5/32
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required
-   Under hood labels and decals
-    Air filter and In-Cabin Air Filter equipped Found the cabin and engine air filter to be dirty
-   Battery cables and mount
-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
-   Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL

OTHER Found the service fuel filter light to be on

Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

With the complexity of the modern automobile, no one can foresee what may happen to it at any time.

Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.

Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.

Customer Acknowledgement:

Technician	Date
Service Manager	Date 10-28-25
Used Car Manager	Date 10-28-25
Customer	Date

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SUV	30250	30250
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date
	8/14/23	8/14/23

Year	Make	Model
2023	CHEVROLET	SUBURBAN
Vehicle Identification Number		Color
1GNSKFKT3PR451255		RADIANT RE

INVENTORY: 684561

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.	I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19370138 : N-OIL (08800-BOPCKT) 7@9.33 65.31 12735608 : SL-N-FILTER (01836-BCKT) 1@8.00 8.00 Changed the engine oil and filter.	I	73.70 65.31 8.00
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.	I	159.95
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 59.95 Balanced all four wheels and tires.	I	59.95
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 10.00 19338054 : SL-N-FILTER (09786-BOPCKT) 1@29.95 29.95	I	10.00 29.95

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	CHEVROLET	SUBURBAN
Vehicle Identification Number	Color	
1GNSKFKT3PR451255	RADIANT RE	

INVENTORY: 684561

Repalced the cabin air filter.			
#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT		I	
Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00			
Work performed by Tech 329/9 * 0.10hrs			10.00
84121219 : SL-N-ELEMENT (03410-CT) 1@49.95			49.95
Replaced the engine air filter.			
#7 * DFF: REPLACE DIESEL FUEL FILTER AND BLEED AIR FROM SYST EM		I	
Corrected by DFF: REPLACE DIESEL FUEL FILTER AND BLEED AIR FROM SYST EM LRATE:.00			
Work performed by Tech 329/9 * 0.90hrs			89.95
13539108 : SL-N-FILTER KIT (03890-CT) 1@83.14			83.14
Replaced the deiseal fuel filter.			

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	573.50				
PARTS	236.35				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	839.84				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
144 Verified Reviews

♥ **102**
Customer Favorites



Vehicle History Report™

US \$44.99

2023 CHEVROLET SUBURBAN PREMIER

VIN: 1GNSKFKT3PR451255
4 DOOR WAGON/SPORT UTILITY
3.0L I6 DIESEL
REAR WHEEL DRIVE W/ 4X4
Original Window Sticker
This CARFAX Report Provided by:


Deery Brothers

★ **4.6 / 5.0**

144 Verified Reviews

♥ **102** Customer Favorites

Damage reported: minor damage



4 Service history records

CARFAX 1-Owner vehicle

Commercial vehicle

30,250 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/30/25 at 5:42:27 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

03/19/2024

Damage reported: minor damage



CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
 Oil	✓ Oil and filter changed	10/28/2025
 Tires	✓ Tires rotated	10/28/2025



This car has been recently serviced. That's a good thing!

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.

✓ No Issues Reported

Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

✓ No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

✓ No Issues Reported

Odometer Check

No indication of an odometer rollback.

✓ No Issues Indicated

Accident / Damage

Damage reported: 03/19/2024.

Minor Damage

Manufacturer Recall

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

✓ No Recalls Reported

Basic Warranty

Original warranty estimated to have 10 months or 5,750 miles remaining. Confirm with dealer or vehicle manufacturer.

✓ Warranty Active

CARFAX Title History

CARFAX guarantees the information in this section

Owner 1

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

✓ Guaranteed No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

✓ Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms | View Certificate

CARFAX Ownership History

The number of owners is estimated

Owner 1

Year purchased	2023
Type of owner	Commercial
Estimated length of ownership	2 yrs. 1 mo.
Owned in the following states/provinces	Iowa
Estimated miles driven per year	13,492/yr
Last reported odometer reading	30,250



CARFAX Detailed History



Owner 1
Purchased: 2023



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Commercial Vehicle
13,492 mi/yr

Date	Mileage	Source	Comments
Not Reported		General Motors	Original Window Sticker
08/31/2023	2	Iowa Motor Vehicle Dept. Keokuk, IA	Title or registration issued - First owner reported - Titled or registered as commercial vehicle - Vehicle color noted as Red
01/23/2024		Iowa Motor Vehicle Dept. Keokuk, IA	Registration issued or renewed - Vehicle color noted as Red
03/19/2024		Damage Report	Damage reported: minor damage - Damage to right rear