

# Multi-Point Inspection Checklist

RO# 6039329

Customer Name INVENTORY: 739781

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 4/30/2026 7:57 AM


























Printed on 5/11/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

-    Cold Engine start-up Pass
-    Engine operation warm-up Pass
-    Engine at normal operating temperature Pass
-    Brake and parking operation Pass
-    Active seat belt test Pass
-    Clutch and transmission operations Pass
-    Overdrive operation Pass
-    Transfer case operation (4-wheel drive only) Pass
-    Steering operation and off center Pass
-    Front end alignment Pass
-    Tilt steering wheel operation Pass
-    Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-    Speedometer and odometer operation Pass
-    Cruise Control operation, including resume Pass
-    Heater and air condition operation Pass
-    Abnormal noises and vibrations Pass
-    Squeaks and rattles Pass
-    Frame Check Pass
-    Body surface, lower body, and upper body damage requiring body shop repair Pass
-    Tire defects and damage, 5/32 front 10 inside choppy back 10, Caution
-    Drive shaft, joints, CV's and boots Pass
-    Struts/shock absorbers, leaks and wear Pass
-    Exhaust system leaks and damage, including catalytic converter Pass
-    Fuel, oil, coolant, or other fluid leaks Pass
-    Perform emissions test and/or state inspection if required Pass
-    Under hood labels and decals Pass
-    Air filter and In-Cabin Air Filter equipped Pass
-    Battery cables and mount Pass
-    Coolant level and test Pass
-    Under hood fluid levels, including transmission and transfer case fluids Pass
-    Drive belts and hoses Pass
-    Air conditioning levels, check at sight glass Pass
-    Warning lights (including air bag) gauges & horn Pass
-    Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-    Inside and outside rearview mirror operation, adjustment, and condition Pass
-    Glass free of cracks, starts and large chips Pass
-    Dome, courtesy, map and sun visor lights and lighters and power ports Pass

-  Window operation Pass
-  Sunroof or convertible top operation Pass
-  Audio system and clock (set if required) Pass
-  Factory -installed alarm system functional Pass
-  Cigarette lighter operation, replace element if used Pass
-  Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
-  Truck bed, bed liner, tailgate, rear bumper Pass
-  Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
-  Seats and seat belt operation for every position Pass
-  Rear defogger, check with test lights Pass
-  Headlight aim Pass
-  Trunk light and trunk trim appearance Pass
-  Hood, trunk, and fuel filler door latch Pass
-  Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
-  Wheel covers and caps Pass
-  Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 8mm all
-  Differential oil level Pass
-  Engine oil and filter changed using genuine replacement parts Pass
-  CHECK AND COMPLETE ALL OPEN RECALL Pass
-  OTHER
-  Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
-  With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
-  Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
-  Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
-  Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2024	GMC	SIERRA 3500HD
Vehicle Identification Number		Color
1GT49YEY0RF398292		BLACK

TRUCK	8918	8923
AMANDA KEPHART	6/28/24	6/28/24

INVENTORY: 739781

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 256/ 0.40hrs @ 195.57 78.23 88864038 : N-OIL (08800-BOPCKT) 10@10.79 107.90 12737081 : SL-N-FILTER (01836-BOPCKT) 1@10.06 10.06 new oil and filter installed	I	
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 256/ 1.00hrs @ 178.95 178.95 inspection complete	I	
#3 - RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:184.59 Work performed by Tech 256/ 0.00hrs @	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	257.18				
PARTS	117.96				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	405.13				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
164 Verified Reviews

♥ **105**  
Customer Favorites



## Report

US \$44.99

### 2024 GMC Sierra 3500HD Denali Ultimate

8,918 mi | VIN: 1GT49Y0RF398292 |

Crew Pickup | 6.6L V8 F OHV 32V | Diesel | Rear wheel drive w/ 4X4



**NO ACCIDENTS REPORTED**

✓ No Accidents or Damage Reported to CARFAX

**CARFAX VALUE \$82,360**

**GOOD RELIABILITY**



🔧 2 Service History Records

1 CARFAX 1-Owner Vehicle

🏠 Personal Vehicle

🌍 Last Owned in Iowa

📄 8 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/2/26 at 10:20:17 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	04/30/2026

This car has been recently serviced. That's a good thing!

### CARFAX History-Based Value Report

**\$82,360**

CARFAX Retail Value

#### History events affecting this vehicle's value

- ↑ ✓ No Accidents Reported
- ↑ 1 1-Owner Vehicle
- ↑ 🛠️ Service History

↑ 🏠 Personal Vehicle

### CARFAX Reliability Forecast

Based on 2024 GMC Sierra 3500HD Denali Ultimate with similar mileage

#### 3-Year Reliability Forecast



Good news! This vehicle is expected to have average risk of repair and average repair costs.



#### What makes this vehicle have good reliability?

\$\$\$ **Average Repair Cost**  
\$330 avg per year

✂ **Average Likelihood of Repair**

### CARFAX Additional History

Not all accidents / issues are reported to CARFAX

👤 Owner 1

#### Total Loss

No total loss reported to CARFAX.

✅ No Issues Reported

#### Structural Damage

No structural damage reported to CARFAX.

✅ No Issues Reported

#### Airbag Deployment

No airbag deployment reported to CARFAX.

✅ No Issues Reported

#### Odometer Check

No indication of an odometer rollback.

✅ No Issues Indicated

#### Accident / Damage

No accidents or damage reported to CARFAX.

✅ No Issues Reported

#### Manufacturer Recall

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

✅ No Recalls Reported

#### Basic Warranty

Original warranty estimated to have 13 months or 27,082 miles remaining. Confirm with dealer or vehicle manufacturer.

✅ Warranty Active

### CARFAX Title History

CARFAX guarantees the information in this section

👤 Owner 1

#### Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

✅ **Guaranteed**  
No Problem

#### Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

✅ **Guaranteed**  
No Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

### CARFAX Ownership History

The number of owners is estimated

👤 Owner 1

Year purchased

2024

Type of owner

Personal

Estimated length of ownership

1 yr. 10 mo.

Owned in the following states/provinces

Iowa



Estimated miles driven per year	4,670/yr
Last reported odometer reading	8,918

**CARFAX** Detailed History

**Owner 1**  
Purchased: 2024

**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle  
4,670 mi/yr

Date	Mileage	Source	Comments
Not Reported		General Motors	<b>Original Window Sticker</b> 
06/01/2024		Iowa Motor Vehicle Dept. Burlington, IA	<b>Titled or registered as personal vehicle</b>
07/22/2024	21	Iowa Motor Vehicle Dept. Burlington, IA Title #29AC76690	<b>Title or registration issued</b> - First owner reported - Vehicle color noted as Black
12/30/2024		Iowa Motor Vehicle Dept. Burlington, IA Title #29AC76690	<b>Registration issued or renewed</b> - Vehicle color noted as Black
12/10/2025		Iowa Motor Vehicle Dept. Burlington, IA Title #29AC76690	<b>Registration issued or renewed</b> - Vehicle color noted as Black
01/22/2026	8,437	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 164 Verified Reviews ❤️ 105 Customer Favorites	<b>Vehicle serviced</b> - 5,000 mile service performed - Air filter replaced - Cabin air filter replaced/cleaned - Oil and filter changed
04/26/2026	8,880	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 164 Verified Reviews ❤️ 105 Customer Favorites	<b>Vehicle offered for sale</b>
04/30/2026	8,918	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 164 Verified Reviews ❤️ 105 Customer Favorites	<b>Vehicle serviced</b> - Maintenance inspection completed - Oil and filter changed

Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).

**CARFAX** Glossary

**First Owner**

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

**Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

**Reliability Forecast**

The CARFAX 3-Year Reliability Forecast predicts the likelihood of repairs for a vehicle over the next three years. This forecast is based on vehicles of the same year, make, and model with similar mileage, damage, service history, and other factors, and assumes an average of 15,000 miles driven per year. Repairs are separate from regular maintenance, such as oil changes. Some of the repairs predicted may be covered under warranty. The 3-Year Reliability Forecast is based on data reported to Carfax and is only a prediction, not a guarantee.

Follow Us:  [facebook.com/CARFAX](https://facebook.com/CARFAX)  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.  
5/2/26 10:20:17 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2024 GMC SIERRA 3500HD vehicle (VIN: 1GT49YEY0RF398292), which is based on information supplied to CARFAX and available as of 5/2/26 at 11:20 AM (EDT).

\_\_\_\_\_  
Customer Signature

\_\_\_\_\_  
Date

\_\_\_\_\_  
Dealer Signature

\_\_\_\_\_  
Date