

# Multi-Point Inspection Checklist

RO# 6040274

Customer Name INVENTORY: 739821

Advisor Name Jim Smith

Technician Name KADEN SCHMITZ

Created on 5/28/2026 7:49 AM

Printed on 5/28/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time



May Require Future Attention

Requires immediate attention

## Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 8/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks seeping oil on top side of engine **B**
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped Fail, Cabin **A**
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
  
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 7-8MM
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
  
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician	Date
Service Manager 	Date <u>5-28-20</u>
Used Car Manager 	Date <u>5/28/26</u>
Customer	Date

REPAIR ORDER - AUDIT			Work Phone	R/O Open Date	R/O Number
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655				05/28/26	6040274/1
			Home Phone	R/O Close Date	Receipt No
				05/28/26	Original
			Body	Mileage In	Mileage Out
	TRUCK	164597	164599		
YEAR	MAKE	Model	License Number	Service Advisor	
2020	GMC	SIERRA 1500		Jim Smith	131
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
1GTU9DEL7LZ255276		RED		03/16/20	03/13/20

INVENTORY: 739821

#1 - MR 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FI ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work by Tech 847/8478 0.40hrs @ 195.58 19432337 : N-OIL (08800-BOPCK) 8@9.60 12742682 : SL-N-FILTER (01836-BOPCKT) 1@25.63 PERFORMED SERVICE	LL	I	78.23 76.80 25.63	7.60 37.04 10.57
#2 - MR 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 847/8478 1.00hrs @ 178.95 PERFORMED INSPECTION		I	178.95	19.00
#3 - MR RECALL: CHECK FOR OPEN RECALLS		I		
#4 * MR ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER Work by Tech 847/8478* 0.10hrs 19338054 : SL-N-FILTER (09786-BOPCKT) 1@49.95 REPLACED FILTER		I	12.00 49.95	1.90 22.55

Account	Description	Control	Reference	Amount
46300	SLS-SRV-INTERNAL MECH LABOR-G	6040274	6040274	-269.18
24700	INV-WORK IN PROCESS SERVICE	338478	6040274	-28.50
66300	CST-SRV-INTERNAL MECH LABOR-G	6040274	6040274	28.50
49100	SLS-PTS-GAS OIL & GREASE	6040274	6040274	-75.58
69100	CST-PTS-GAS OIL & GREASE	6040274	6040274	33.12
24200	INVENTORY-PTS/ACC-GM	6040274	6040274	-33.12
49100	SLS-PTS-GAS OIL & GREASE	6040274	6040274	-76.80
69100	CST-PTS-GAS OIL & GREASE	6040274	6040274	37.04
24200	INVENTORY-PTS/ACC-GM	6040274	6040274	-37.04
66900	CST-SRV-MECH SHOP SUPPLIES	6040274	6040274	-29.99
24100	INVENTORY - USED TRUCKS	739821	6040274	451.55

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR	269.18				28.50
PARTS	152.38				70.16
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	451.55				98.66

This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

**2025 TOP-RATED DEALER**

★ **4.6 / 5.0**  
175 Verified Reviews

♥ **1,528**

Customer Favorites



## Report

US \$44.99

### 2020 GMC Sierra 1500 SLT

163,256 mi | VIN: 1GTU9DEL7LZ255276 |

Crew Pickup | 6.2L V8 F OHV 16V | Gasoline | Rear wheel drive w/ 4X4

CARFAX HAS THE MOST  
ACCIDENT & DAMAGE  
INFORMATION



**DAMAGE** Minor Damage



Minor

Moderate

Severe

✂ 5 Service History Records

1 CARFAX 1-Owner Vehicle

👛 Corporate Vehicle

🌍 Last Owned in Iowa

📁 17 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/28/26 at 5:29:52 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



### Accident / Damage History

Not all accidents / issues are reported to CARFAX

#### Event 1

10/21/2021

**Damage reported: minor damage**

Damage Severity Scale



Minor

Moderate

Severe



### Additional History

Not all accidents / issues are reported to CARFAX

👤 Owner 1

#### Total Loss

No total loss reported to CARFAX.

✅ No Issues Reported

#### Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

✅ No Issues Reported

#### Airbag Deployment

No airbag deployment reported to CARFAX.





✅ No Issues Reported

<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> Damage reported: 10/21/2021.	Minor Damage
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	<b>Warranty Expired</b>




<b>CARFAX Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

<b>CARFAX Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2020
Type of owner	Corporate
Estimated length of ownership	6 yrs. 2 mo.
Owned in the following states/provinces	Iowa
Estimated miles driven per year	26,146/yr
Last reported odometer reading	163,256



<b>CARFAX Detailed History</b>			
 <b>Owner 1</b> Purchased: 2020		Corporate Vehicle 26,146 mi/yr	
Date	Mileage	Source	Comments
Not Reported		General Motors	<b>Original Window Sticker</b> 
03/01/2020		Iowa Motor Vehicle Dept. Keokuk, IA	<b>Titled or registered as corporate vehicle</b>
03/12/2020	5	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 175 Verified Reviews ❤️ 1,528 Customer Favorites	 <b>Vehicle serviced</b> - Pre-delivery inspection completed - Oil and filter changed - Vehicle washed/detailed
03/23/2020	135	Deery Brothers West Burlington, IA	 <b>Vehicle serviced</b> - Cold air intake installed

319-752-6000  
 deerybrothers.com  
 ★ 4.6 / 5.0 175 Verified Reviews  
 ❤️ 1,528 Customer Favorites

04/02/2020		Iowa Motor Vehicle Dept. Keokuk, IA Title #56AC02678N		<b>Title or registration issued</b> - First owner reported - Vehicle color noted as Red
08/07/2020	550	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 175 Verified Reviews ❤️ 1,528 Customer Favorites		<b>Vehicle serviced</b> - Tonneau cover installed
12/30/2020		Iowa Motor Vehicle Dept. Keokuk, IA Title #56AC02678N		<b>Registration issued or renewed</b> - Vehicle color noted as Red
02/15/2021		Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 175 Verified Reviews ❤️ 1,528 Customer Favorites		<b>Vehicle serviced</b> - Maintenance inspection completed - Oil and filter changed - Tires rotated
10/21/2021		Damage Report		<b>Damage reported: minor damage</b>  <div data-bbox="850 963 1256 1119" data-label="Figure"> <p>Damage Severity Scale</p> <p>Minor Moderate Severe</p> </div> <div data-bbox="878 1150 1507 1226" data-label="Text"> <p>Minor damage is usually cosmetic, including dents or scratches to the vehicle body.</p> </div>
12/22/2021		Iowa Motor Vehicle Dept. Keokuk, IA Title #56AC02678N		<b>Registration issued or renewed</b> - Vehicle color noted as Red
05/20/2022	68,229	Ed's Auto Repair Keokuk, IA 319-524-2025 ★ 5.0 / 5.0 6 Verified Reviews		<b>Vehicle serviced</b> - Serpentine belt replaced
12/14/2022		Iowa Motor Vehicle Dept. Keokuk, IA Title #56AC02678N		<b>Registration issued or renewed</b> - Vehicle color noted as Red
01/23/2024		Iowa Motor Vehicle Dept. Keokuk, IA Title #56AC02678N		<b>Registration issued or renewed</b> - Vehicle color noted as Red
12/27/2024		Iowa Motor Vehicle Dept. Keokuk, IA Title #56AC02678N		<b>Registration issued or renewed</b> - Vehicle color noted as Red
12/19/2025		Iowa Motor Vehicle Dept. Keokuk, IA Title #56AC02678N		<b>Registration issued or renewed</b> - Vehicle color noted as Red