

# Multi-Point Inspection Checklist

RO# 6037442

Customer Name INVENTORY: 739691

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 2/27/2026 12:33 PM

Printed on 3/3/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time    
  May Require Future Attention    
  Requires immediate attention

## Maintenance Service

- |                                     |                          |                                     |  |
|-------------------------------------|--------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Cold Engine start-up   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Engine operation warm-up   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Engine at normal operating temperature   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Brake and parking operation <u>fb 8mm rb 9mm</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Active seat belt test  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Clutch and transmission operations   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Overdrive operation  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Transfer case operation (4-wheel drive only)   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Steering operation and off center  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Front end alignment  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Tilt steering wheel operation  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Windshield wiper and washer operation at all speeds, wiper blade condition   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Speedometer and odometer operation   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Cruise Control operation, including resume   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Heater and air condition operation   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Abnormal noises and vibrations   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Squeaks and rattles  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Frame Check  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Body surface, lower body, and upper body damage requiring body shop repair   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Tire defects and damage, 5/32 <u>ft 8/32 rt 7/32</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | <del>Drive shaft, joints, CV's and boots</del>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Struts/shock absorbers, leaks and wear   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Exhaust system leaks and damage, including catalytic converter   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Fuel, oil, coolant, or other fluid leaks   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Perform emissions test and/or state inspection if required   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Under hood labels and decals   |
| <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Air filter and In -Cabin Air Filter equipped <u>Found the cabin air filter to be dirty</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Battery cables and mount   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Coolant level and test   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Under hood fluid levels, including transmission and transfer case fluids   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Drive belts and hoses  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Air conditioning levels, check at sight glass  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Warning lights (including air bag) gauges & horn   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Inside and outside rearview mirror operation, adjustment, and condition  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Glass free of cracks, starts and large chips   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Dome , courtesy, map and sun visor lights and lighters and power ports   |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
  
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
  
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date


Year	Make	Model
2022	GMC	SIERRA 1500
Vehicle Identification Number		Color
1GTUUCET9NZ522283		SILVER

TRUCK	25807	25807
JAKE BACHTELL	5/21/22	5/09/22

INVENTORY: 739691

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.	169.95	I
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 12735608 : SL-N-FILTER (01836-BCKT) 1@6.95 6.95 19370138 : N-OIL (08800-BOPCKT) 7@9.33 65.31 Changed the engine oil and filter.	73.70 6.95 65.31	I
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.	159.95	I
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 99.00 Balanced all four wheels and tires.	99.00	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	502.60				
PARTS	72.26				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	604.85				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
154 Verified Reviews

♥ **101**  
Customer Favorites



### Vehicle History Report™

US \$44.99

#### 2022 GMC SIERRA 1500 ELEVATION

VIN: 1GTUUCET9NZ522283  
CREW PICKUP  
3.0L I6  
DIESEL  
REAR WHEEL DRIVE W/ 4X4  
Original Window Sticker

This CARFAX Report Provided by:

**Deery Brothers**

★ **4.6 / 5.0**  
154 Verified Reviews  
♥ **101** Customer Favorites

✓ No accidents or damage reported to CARFAX

🔧 **9** Service history records

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

🌍 Last owned in Illinois

📊 **25,807** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/28/26 at 12:03:46 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.




### Recent Service Highlights


Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	02/27/2026
🛞 Tires	✓ Tires rotated	09/09/2025



This car has been recently serviced. That's a good thing!

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	<b>Owner 1</b>
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	<b>Warranty Expired</b>

 <b>Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

 <b>Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2022
Type of owner	Personal
Estimated length of ownership	3 yrs. 9 mo.
Owned in the following states/provinces	Illinois
Estimated miles driven per year	6,771/yr



Last reported odometer reading

25,807

**CARFAX** Detailed History



**Owner 1**  
Purchased: 2022

















**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle  
6,771 mi/yr

Date	Mileage	Source	Comments
Not Reported		General Motors	<b>Original Window Sticker</b> 
05/21/2022		Illinois Motor Vehicle Dept.	<b>Vehicle purchase reported</b>
05/26/2022	10	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 154 Verified Reviews ❤️ 101 Customer Favorites	<b>Vehicle serviced</b> - Pre-delivery inspection completed - Oil and filter changed - Paint protection applied - Tailpipe extension(s) installed - Vehicle washed/detailed
07/01/2022	499	Illinois Motor Vehicle Dept. Nauvoo, IL	<b>Title issued or updated</b> - Registration issued or renewed - First owner reported - Titled or registered as personal vehicle - Vehicle color noted as Silver
08/30/2022		Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 154 Verified Reviews ❤️ 101 Customer Favorites	<b>Vehicle serviced</b> - One tire replaced - Tire pressure sensor replaced - Tonneau cover installed
09/30/2022	2,070	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 154 Verified Reviews	<b>Vehicle serviced</b> - Vehicle washed/detailed

 **101** Customer Favorites

11/23/2022	2,744	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com  <b>4.6 / 5.0</b> 154 Verified Reviews  <b>101</b> Customer Favorites	 <b>Vehicle serviced</b> - Vehicle washed/detailed
01/27/2023	3,908	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com  <b>4.6 / 5.0</b> 154 Verified Reviews  <b>101</b> Customer Favorites	 <b>Vehicle serviced</b> - Maintenance inspection completed - Oil and filter changed - Transmission fluid changed
06/02/2023		Illinois Motor Vehicle Dept. Nauvoo, IL	<b>Registration issued or renewed</b>
05/10/2024		Illinois Motor Vehicle Dept. Nauvoo, IL	<b>Registration issued or renewed</b>
04/28/2025	19,721	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/  <b>4.6 / 5.0</b> 154 Verified Reviews  <b>101</b> Customer Favorites	 <b>Vehicle serviced</b> - Maintenance inspection completed
06/06/2025		Illinois Motor Vehicle Dept. Nauvoo, IL	<b>Registration issued or renewed</b>
08/29/2025	20,983	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/  <b>4.6 / 5.0</b> 154 Verified Reviews  <b>101</b> Customer Favorites	 <b>Vehicle serviced</b> - Vehicle washed/detailed
09/09/2025	22,701	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/  <b>4.6 / 5.0</b> 154 Verified Reviews	 <b>Vehicle serviced</b> - Maintenance inspection completed - 5,000 mile service performed - Air filter replaced - Cabin air filter replaced/cleaned - Fluids checked