

Multi-Point Inspection Checklist

RO# 6038547

Customer Name INVENTORY: 685011

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 4/6/2026 3:05 PM

Printed on 4/15/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-   Cold Engine start-up Pass
-   Engine operation warm-up Pass
-   Engine at normal operating temperature Pass
-   Brake and parking operation Pass
-   Active seat belt test Pass
-   Clutch and transmission operations Pass
-   Overdrive operation Pass
-   Transfer case operation (4-wheel drive only) Pass
-   Steering operation and off center Pass
-   Front end alignment Pass
-   Tilt steering wheel operation Pass
-   Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-   Speedometer and odometer operation Pass
-   Cruise Control operation, including resume Pass
-   Heater and air condition operation Pass
-   Abnormal noises and vibrations Pass
-   Squeaks and rattles Pass
-   Frame Check Pass
-   Body surface, lower body, and upper body damage requiring body shop repair Pass
-   Tire defects and damage, 5/32 6/32 all
-   Drive shaft, joints, CV's and boots Pass
-   Struts/shock absorbers, leaks and wear Pass
-   Exhaust system leaks and damage, including catalytic converter Pass
-   Fuel, oil, coolant, or other fluid leaks Pass
-   Perform emissions test and/or state inspection if required Pass
-   Under hood labels and decals Pass
-   Air filter and In -Cabin Air Filter equipped Caution
-   Battery cables and mount Pass
-   Coolant level and test Pass
-   Under hood fluid levels, including transmission and transfer case fluids Pass
-   Drive belts and hoses Pass
-   Air conditioning levels, check at sight glass Pass
-   Warning lights (including air bag) gauges & horn Pass
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-   Inside and outside rearview mirror operation, adjustment, and condition Pass
-   Glass free of cracks, starts and large chips Pass
-   Dome , courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation Pass
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper Pass
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6mm all
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

4/06/26
6038547/1
4/09/26
Original
107113
107113

Year	Make	Model
2018	GMC	SIERRA 1500
Vehicle Identification Number	Color	
1GTV2MEC2JZ365299	WHITE	

INVENTORY: 685011

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 256/ 0.40hrs @ 184.25 73.70 19432357 : N-OIL (08800-BOPCK) 8@9.60 76.80 12735811 : SL-N-FILTER (01836-BOPCKT) 1@6.95 6.95 new oil and filter	I
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95 inspection complete	I
#3 - RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:180.14 Work performed by Tech 256/ 0.00hrs @	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	243.65				
PARTS	83.75				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	357.39				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
159 Verified Reviews

♥ **101**
Customer Favorites



Report

US \$44.99

2018 GMC Sierra 1500 SLE

107,116 mi | VIN: 1GTV2MEC2JZ365299 |

4 Door Extended Cab Pickup | 5.3L V8 F OHV 16V | Gasoline | Rear wheel drive w/ 4X4

CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION



ACCIDENT

! Airbag Deployed

🔧 31 Service history records

👤 2 Previous owners

🏠 Personal vehicle

🌍 Last owned in Illinois

📄 53 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/11/26 at 8:59:24 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Accident / Damage History


Not all accidents / issues are reported to CARFAX

Event 1

01/29/2022

Accident reported

- It hit an animal
- It hit a deer
- Vehicle towed
- Multiple airbags deployed



CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	04/09/2026

Tires
✓ Tires rotated
12/20/2025

This car has been recently serviced. That's a good thing!

CARFAX Additional History <small>Not all accidents / issues are reported to CARFAX</small>	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✓ No Issues Reported	✓ No Issues Reported
Airbag Deployment Airbag deployment reported: 01/29/2022.	✓ No Issues Reported	Airbag Deployment
Odometer Check No indication of an odometer rollback.	✓ No Issues Indicated	✓ No Issues Indicated
Accident / Damage Accident reported: 01/29/2022.	✓ No Issues Reported	Accident Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	✓ No Recalls Reported	✓ No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

CARFAX Title History <small>CARFAX guarantees the information in this section</small>	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	✓ Guaranteed No Problem	✓ Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	✓ Guaranteed No Problem	✓ Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

CARFAX Ownership History <small>The number of owners is estimated</small>	Owner 1	Owner 2
Year purchased	2019	2021
Type of owner	Personal	Personal
Estimated length of ownership	1 yr. 3 mo.	5 yrs. 1 mo.
Owned in the following states/provinces	Illinois	Illinois
Estimated miles driven per year	12,684/yr	17,370/yr
Last reported odometer reading	16,651	107,116

CARFAX Detailed History

Owner 1
Purchased: 2019

Personal Vehicle
12,684 mi/yr

Date	Mileage	Source		Comments
06/13/2018	5	Kunes Country of Stoughton Stoughton, WI 608-873-3545 https://kunesstoughton.com ★ 4.4 / 5.0 222 Verified Reviews ♥ 2,606 Customer Favorites		Vehicle serviced - Pre-delivery inspection completed - Fluids checked - Vehicle washed/detailed
06/19/2018		Kunes Country of Stoughton Stoughton, WI 608-873-3545 https://kunesstoughton.com ★ 4.4 / 5.0 222 Verified Reviews ♥ 2,606 Customer Favorites		Vehicle offered for sale
12/19/2018		Kunes Country of Stoughton Stoughton, WI 608-873-3545 https://kunesstoughton.com ★ 4.4 / 5.0 222 Verified Reviews ♥ 2,606 Customer Favorites		Vehicle sold
12/27/2018		Kunes Auto Group of Macomb Macomb, IL 309-837-5757 kunesmacomb.com ★ 4.7 / 5.0 108 Verified Reviews ♥ 1,150 Customer Favorites		Vehicle offered for sale
09/27/2019	5,157	Kunes Auto Group of Macomb Macomb, IL 309-837-5757 kunesmacomb.com ★ 4.7 / 5.0 108 Verified Reviews ♥ 1,150 Customer Favorites		Vehicle sold
09/27/2019		Illinois Motor Vehicle Dept.		Vehicle purchase reported - Titled or registered as personal vehicle
09/27/2019		Warrantech Automotive, Inc. Blandinsville, IL warrantech.com		Service contract issued
09/30/2019	5,434	Kunes Auto Group of Macomb Macomb, IL 309-837-5757 kunesmacomb.com ★ 4.7 / 5.0 108 Verified Reviews ♥ 1,150 Customer Favorites		Vehicle serviced - Vehicle washed/detailed
10/28/2019		Illinois Motor Vehicle Dept. Blandinsville, IL Title #193016966890		Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported - Vehicle color noted as White
11/13/2019	6,568	Kunes Auto Group of Macomb Macomb, IL 309-837-5757 kunesmacomb.com ★ 4.7 / 5.0 108 Verified Reviews ♥ 1,150 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed
05/15/2020		Illinois Motor Vehicle Dept. Blandinsville, IL		Registration issued or renewed - Correction to record
08/13/2020	12,183	Illinois		Title issued or updated

Motor Vehicle Dept.
Blandinsville, IL
Title #202266130710

- Correction to record
- Loan or lien reported

01/07/2021 16,264

Kunes Auto Group of Macomb
Macomb, IL
309-837-5757
kunesmacomb.com



- Vehicle serviced**
- Oil and filter changed
 - Tires rotated

★ 4.7 / 5.0 108 Verified Reviews
♥ 1,150 Customer Favorites



Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

01/11/2021

Kunes Auto Group of Macomb
Macomb, IL
309-837-5757
kunesmacomb.com

Vehicle offered for sale

★ 4.7 / 5.0 108 Verified Reviews
♥ 1,150 Customer Favorites

01/23/2021 16,337

Kunes Auto Group of Macomb
Macomb, IL
309-837-5757
kunesmacomb.com

Vehicle sold

★ 4.7 / 5.0 108 Verified Reviews
♥ 1,150 Customer Favorites

01/23/2021

Illinois
Motor Vehicle Dept.

Vehicle purchase reported

01/28/2021 16,651

Kunes Auto Group of Macomb
Macomb, IL
309-837-5757
kunesmacomb.com



- Vehicle serviced**
- Vehicle washed/detailed

★ 4.7 / 5.0 108 Verified Reviews
♥ 1,150 Customer Favorites

01/29/2021

Illinois
Motor Vehicle Dept.
Roseville, IL

Registration issued or renewed

Owner 2
Purchased: 2021

Personal Vehicle
17,370 mi/yr

Date	Mileage	Source	Comments
02/19/2021		Illinois Motor Vehicle Dept. Roseville, IL Title #210506929380	Title issued or updated - New owner reported - Loan or lien reported - Vehicle color noted as White
04/20/2021	20,833	Kunes Auto Group of Macomb Macomb, IL 309-837-5757 kunesmacomb.com ★ 4.7 / 5.0 108 Verified Reviews ♥ 1,150 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Oil and filter changed
08/06/2021	25,798	Kunes Auto Group of Macomb Macomb, IL 309-837-5757 kunesmacomb.com ★ 4.7 / 5.0 108 Verified Reviews ♥ 1,150 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Oil and filter changed
10/29/2021	30,554	Kunes Auto Group of Macomb Macomb, IL	Vehicle serviced - Maintenance inspection completed