

Multi-Point Inspection Checklist

RO# 6037309

Customer Name INVENTORY: 969160

Advisor Name Jim Smith

Technician Name Kevin Randall











































Created on 2/24/2026 12:49 PM

































Printed on 2/24/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service


-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only) N/A
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 LF 8/32 ALL OTHERS 5/32
-   Drive shaft, joints, CV's and boots

-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required N/A
-   Under hood labels and decals
-   Air filter and In-Cabin Air Filter equipped
-   Battery cables and mount
-   Coolant level and test -50
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
-   Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used N/A
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 7MM FRONT 8MM REAR
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician	Date
Service Manager 	Date <u>2-24-26</u>
Used Car Manager	Date
Customer	Date

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655


Work Phone	R/O Open Date	R/O Number
	2/24/26	6037309/1
Home Phone	R/O Close Date	Receipt No.
	2/24/26	Original
Body	Mileage In	Mileage Out
	27054	27054

Year	Make	Model	License Number	Service Advisor
2023	CADILLAC	XT5		Jim Smith
Vehicle Identification Number		Color	Account No.	Delivery Date
1GYKNFRS3PZ195691		SILVER		2/06/24

INVENTORY: 969160

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 425/ 0.40hrs @ 184.25 73.70 19432357 : N-OIL (08800-BOPCK) 6@9.60 57.60 12735811 : SL-N-FILTER (01836-BOPCKT) 1@11.23 11.23 SERVICE COMPLETED	I	
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 425/ 1.00hrs @ 169.95 169.95 INSPECTION COMPLETED	I	
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 425/ * 0.90hrs 99.00 SERVICE COMPLETED	I	
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 425/ * 1.50hrs 159.95 SET REAR AND FRONT TOE	I	
#5 - RECALL: CHECK FOR OPEN RECALLS Corrected by RECALL: CHECK FOR OPEN RECALLS LRATE:180.14 Work performed by Tech 425/ 0.00hrs @ NO RECALLS AT THIS TIME	C	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	502.60				
PARTS	68.83				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	601.42				




This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

★ **4.6 / 5.0**
 153 Verified Reviews

♥ **101**
 Customer Favorites




Vehicle History Report™

US \$44.99


2023 CADILLAC XT5 PREMIUM LUXURY

VIN: 1GYKNFRS3PZ195691
 4 DOOR WAGON/SPORT UTILITY
 3.6L V6 GASOLINE
 ALL WHEEL DRIVE
 Original Window Sticker
 This CARFAX Report Provided by:
Deery Brothers
 ★ 4.6 / 5.0
 153 Verified Reviews
 ♥ 101 Customer Favorites

<input checked="" type="checkbox"/>	No accidents or damage reported to CARFAX
	3 Service history records
	Good Reliability
	CARFAX 1-Owner vehicle
	Personal vehicle
	27,054 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/25/26 at 5:38:20 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	02/24/2026
Tires	✓ Tires rotated	01/07/2026
Brakes	✓ Brake fluid flushed/changed	01/07/2026



This car has been recently serviced. That's a good thing!



Reliability Forecast

Based on 2023 Cadillac XT5 Premium Luxury with similar mileage

3-Year Reliability Forecast



Fair Reliability

Good Reliability

Great Reliability

Good news! This vehicle is expected to have average risk of repair and average repair costs.



What makes this vehicle have good reliability?

- Top 50%** compared to similar vehicles
- Average Repair Cost**
\$330 avg per year
- Average Likelihood of Repair**



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.

No Issues Reported

Structural Damage

No structural damage reported to CARFAX.

No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

Odometer Check

No indication of an odometer rollback.

No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.

No Issues Reported

Manufacturer Recall



No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

No Recalls Reported





Basic Warranty

Original warranty estimated to have 13 months or 22,946 miles remaining. Confirm with dealer or vehicle manufacturer.

Warranty Active

 Title History CARFAX guarantees the information in this section		Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon		<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits		<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate		

 Ownership History The number of owners is estimated		Owner 1
Year purchased		2023
Type of owner		Personal
Estimated length of ownership		2 yrs. 11 mo.
Owned in the following states/provinces		Iowa
Estimated miles driven per year		9,051/yr
Last reported odometer reading		27,054

 Detailed History			
 Owner 1 Purchased: 2023		<div style="border: 1px solid blue; padding: 5px;"> Low mileage! This owner drove less than the industry average of 15,000 miles per year. </div>	Personal Vehicle 9,051 mi/yr
Date	Mileage	Source	Comments
Not Reported		General Motors	Original Window Sticker 
03/01/2023		Iowa Motor Vehicle Dept. Fort Madison, IA	Titled or registered as personal vehicle
04/10/2023	9	Iowa	Title or registration issued