

Multi-Point Inspection Checklist

RO# 6038613

Customer Name INVENTORY: 969610

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 4/8/2026 12:49 PM

Printed on 4/8/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-   Cold Engine start-up Pass
-   Engine operation warm-up Pass
-   Engine at normal operating temperature Pass
-   Brake and parking operation Pass
-   Active seat belt test Pass
-   Clutch and transmission operations Pass
-   Overdrive operation Pass
-   Transfer case operation (4-wheel drive only) Pass
-   Steering operation and off center Pass
-   Front end alignment Pass
-   Tilt steering wheel operation Pass
-   Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-   Speedometer and odometer operation Pass
-   Cruise Control operation, including resume Pass
-   Heater and air condition operation Pass
-   Abnormal noises and vibrations Pass
-   Squeaks and rattles Pass
-   Frame Check Pass
-   Body surface, lower body, and upper body damage requiring body shop repair Pass
-   Tire defects and damage, 5/32 8/32 all
-   Drive shaft, joints, CV's and boots Pass
-   Struts/shock absorbers, leaks and wear Pass
-   Exhaust system leaks and damage, including catalytic converter Pass
-   Fuel, oil, coolant, or other fluid leaks Pass
-   Perform emissions test and/or state inspection if required Pass
-   Under hood labels and decals Pass
-   Air filter and In-Cabin Air Filter equipped Fail
-   Battery cables and mount Pass
-   Coolant level and test Pass
-   Under hood fluid levels, including transmission and transfer case fluids Pass
-   Drive belts and hoses Pass
-   Air conditioning levels, check at sight glass Pass
-   Warning lights (including air bag) gauges & horn Pass
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-   Inside and outside rearview mirror operation, adjustment, and condition Pass
-   Glass free of cracks, starts and large chips Pass
-   Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 7mm front 9mm rear
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:



Technician	Date
Service Manager	Date 4.8.26
Used Car Manager	Date 4/8/26
Customer	Date



2C4RC1BG0RR129096

Odometer:40679

Chrysler : Pacifica : 2024 : Front Wheel Drive ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.

REPAIR ORDER - AUDIT			Work Phone	R/O Open Date	R/O Number		
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655				04/08/26	6038613/1		
			Home Phone	R/O Close Date	Receipt No		
				04/09/26	Original		
			Body	Mileage In	Mileage Out		
			TOURING L FWD	40679	40679		
YEAR	MAKE	Model	License Number	Service Advisor			
2024	CHRYSLER	PACIFICA		AMANDA KEPHART	1403		
Vehicle Identification Number			Account No	Delivery Date	In-Service Date		
2C4RC1BG0RR129096							
INVENTORY: 969610							
#1 - QL 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FI ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work by Tech 256/756 0.40hrs @ 184.25 19420060 : N-OIL (08800-BOPCK) 5@8.10 R94010 : OIL FILTER 1@10.43 new oil and filter installed			LL	I	11.20 22.65 4.30		
#2 - QL 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 256/756 1.00hrs @ 169.95 inspection complete				I	28.00		
#3 - QL GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTAT Work by Tech 256/756 * 0.90hrs service complete			E	I	25.20		
#4 - QL ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTE COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work by Tech 256/756 * 1.50hrs alingment complete			D	I	42.00		
#5 - QL RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. Work by Tech 256/756 0.00hrs @				I			
#6 * QL ICF: REPLACED IN CABIN AIR FILTER				I			
			INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR							
PARTS							
DEDUCTIBLE							
SUBLET							
SHOP SUPPLIES							
HAZARDOUS MATERIALS							
SALES TAX OR TAX I.D.							
SPECIAL ORDER DEPOSIT							
DISCOUNTS							

REPAIR ORDER - AUDIT			Work Phone	R/O Open Date	R/O Number
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655				04/08/26	6038613/2
			Home Phone	R/O Close Date	Receipt No
				04/09/26	Original
			Body	Mileage In	Mileage Out
		TOURING L FWD	40679	40679	
YEAR	MAKE	Model	License Number	Service Advisor	
2024	CHRYSLER	PACIFICA		AMANDA KEPHART 1403	
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
2C4RC1BG0RR129096		SILVER			


INVENTORY: 969610

Corrected by ICF: REPLACED IN CABIN AIR FILTER								
Work by Tech 256/756 * 0.10hrs						12.00		2.80
PC99238C : CABIN AIR FILTER 1@49.95						49.95		14.49
new cabin filter								

#7 * QL AF: REPLACED ENGINE AIR FILTER								
Corrected by AF: REPLACED ENGINE AIR FILTER								
Work by Tech 256/756 * 0.10hrs						12.00		2.80
PA99209 : AIR FILTER 1@29.95						29.95		14.85
new air filter installed								

Line						Hours		.00
1	4/08/26	Tech 256	Start 13:13	End 13:14		Hours		.00
2	4/08/26	Tech 256	Start 13:14	End 13:14		Hours		.10
3	4/08/26	Tech 256	Start 13:08	End 13:13		Hours		.50
4	4/08/26	Tech 256	Start 14:12	End 14:43		Hours		.00
6	4/08/26	Tech 256	Start 13:28	End 13:28		Hours		.00
7	4/08/26	Tech 256	Start 13:28	End 13:28		Hours		.00
Account	Description	Control	Re	ference	Amount			
46100	SLS-SRV-QUICKLANE-LABOR-GM	6038613		6038613	-526.60			
24700	INV-WORK IN PROCESS SERVICE	217756		6038613	-112.00			
66100	CST-SRV-QUICKLANE-LABOR-GM	6038613		6038613	112.00			
46750	SLS-PTS-CUSTOMER MECH RO-OTHE	6038613		6038613	-79.90			
66750	CST-PTS-CUSTOMER MECH RO-OTHE	6038613		6038613	29.34			
24230	INVENTORY-PTS/ACCESS-OTHER	6038613		6038613	-29.34			
46750	SLS-PTS-CUSTOMER MECH RO-OTHE	6038613		6038613	-10.43			
66750	CST-PTS-CUSTOMER MECH RO-OTHE	6038613		6038613	4.30			
24230	INVENTORY-PTS/ACCESS-OTHER	6038613		6038613	-4.30			
49100	SLS-PTS-GAS OIL & GREASE	6038613		6038613	-40.50			
69100	CST-PTS-GAS OIL & GREASE	6038613		6038613	22.65			
24200	INVENTORY-PTS/ACC-GM	6038613		6038613	-22.65			
66900	CST-SRV-MECH SHOP SUPPLIES	6038613		6038613	-29.99			
24100	INVENTORY - USED TRUCKS	969610		6038613	687.42			

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR	526.60				112.00
PARTS	130.83				56.29
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	687.42				168.29



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
159 Verified Reviews

♥ **101**
Customer Favorites



Report

US \$44.99

2024 Chrysler Pacifica Touring L

39,957 mi | VIN: 2C4RC1BG0RR129096 |

Van | 3.6L V6 F DOHC 24V | Gasoline | Front wheel drive

CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION



🔧 9 Service history records

1 CARFAX 1-Owner vehicle

🚗 Rental vehicle

🌍 Last owned in Florida

📄 14 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/9/26 at 5:40:18 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Accident / Damage History


Not all accidents / issues are reported to CARFAX

Event 1

03/20/2025

Accident reported: minor damage

Damage Severity Scale



CARFAX Additional History

Not all accidents / issues are reported to CARFAX

👤 Owner 1

Total Loss

No total loss reported to CARFAX.

✅ No Issues Reported

Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

✅ No Issues Reported

Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage Accident reported: 03/20/2025.	Minor Damage
Manufacturer Recall No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

Title History

CARFAX guarantees the information in this section

Owner 1

Damage Brands
Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

Guaranteed
No Problem

Odometer Brands
Not Actual Mileage | Exceeds Mechanical Limits

Guaranteed
No Problem

GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

Ownership History

The number of owners is estimated

Owner 1

Year purchased	2024
Type of owner	Rental
Estimated length of ownership	2 yrs. 1 mo.
Owned in the following states/provinces	Oklahoma, Florida
Estimated miles driven per year	19,923/yr
Last reported odometer reading	39,957

Detailed History

	<p>Owner 1 Purchased: 2024</p>	<p>Rental Vehicle 19,923 mi/yr</p>	
Date	Mileage	Source	Comments
Not Reported		FCA US LLC	<p>Original Window Sticker</p>
03/07/2024		Oklahoma Motor Vehicle Dept. Tulsa, OK	Titled or registered as rental vehicle
03/07/2024	10	Florida Motor Vehicle Dept. Title #0154044842	<p>Vehicle purchase reported</p> <ul style="list-style-type: none"> - Title issued or updated - Registration issued or renewed - First owner reported - Vehicle color noted as Silver