

Multi-Point Inspection Checklist

RO# 6038902

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Customer Name INVENTORY: 969630

Advisor Name Jim Smith

Technician Name TYLER MCWILLIAMS

Created on 4/17/2026 10:59 AM

Printed on 4/17/2026

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 6/32nds Front and back
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required N/A
-   Under hood labels and decals
-    Air filter and In-Cabin Air Filter equipped
-   Battery cables and mount
-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
-   Dome , courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6 Fronts 7 Rears
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER N/A
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician	Date
Service Manager	Date <u>4-17-26</u>
Used Car Manager	Date <u>4/17/26</u>
Customer	Date

REPAIR ORDER - AUDIT

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	04/17/26	6038902/1
Home Phone	R/O Close Date	Receipt No
	04/22/26	Original
Body	Mileage In	Mileage Out
TOURING L FWD	43176	43178
License Number	Service Advisor	
	Jlm Smith	131
Account No	Delivery Date	In-Service Date

YEAR	MAKE	Model
2024	CHRYSLER	PACIFICA
Vehicle Identification Number		Color
2C4RC1BG7RR107077		WHITE

INVENTORY: 969630

#1 - MR 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FI ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work by Tech 649/4925 0.40hrs @ 195.58 19432337 : N-OIL (08800-BOPCK) 509.60 R94010 : OIL FILTER 1010.43 Changed oil and filter and topped off fluids.	LL	I	78.23 48.00 10.43	23.15 4.30
#2 - MR 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 649/4925 1.00hrs @ 178.95 56 point inspection.		I	178.95	
#3 - MR GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTAT Work by Tech 649/4925* 0.90hrs Balanced and rotated tires.	E	I	99.00	
#4 - MR ALIGN: COMPUTERIZED ALIGNMENT SERVICE , INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTE COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work by Tech 649/4925* 1.50hrs PERFORMED ALIGNMENT	O	I	159.95	
#5 - MR RECALL: CHECK FOR OPEN RECALLS Checked for recalls.		I		
#6 * QL TIRE: SINGLE TIRE REPAIR AND BALANCE TIRE AS NEEDED UPON INSPECTION FOUND NAIL IN TIRE Caused by		I		

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
160 Verified Reviews

❤️ **101**
Customer Favorites



Report

US \$44.99

2024 Chrysler Pacifica Touring L

43,027 mi | VIN: 2C4RC1BG7RR107077 |

Van | 3.6L V6 F DOHC 24V | Gasoline | Front wheel drive



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

CARFAX VALUE \$28,870

🛢️ Regular Oil Changes

1 CARFAX 1-Owner Vehicle

🚗 Rental Vehicle

🌍 Last Owned in Florida

📄 14 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/21/26 at 6:38:21 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	06/10/2025
🛞 Tires	✓ Tires rotated	06/10/2025

This car has been recently serviced. That's a good thing!

CARFAX History-Based Value Report

\$28,870

CARFAX Retail Value

History events affecting this vehicle's value

↑ ✓ No Accidents Reported




- 1-Owner Vehicle
- Regular Oil Changes
- Non-Personal Vehicle

Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

Ownership History The number of owners is estimated	Owner 1
Year purchased	2024
Type of owner	Rental
Estimated length of ownership	2 yrs. 3 mo.
Owned in the following states/provinces	Oklahoma, Florida
Estimated miles driven per year	19,293/yr
Last reported odometer reading	43,027

Detailed History			
Owner 1 Purchased: 2024	Rental Vehicle 19,293 mi/yr		
Date	Mileage	Source	Comments

Not Reported		FCA US LLC		Original Window Sticker
				
01/15/2024	10	Florida Motor Vehicle Dept.		Odometer reading reported
01/23/2024		Oklahoma Motor Vehicle Dept. Tulsa, OK		Titled or registered as rental vehicle
01/23/2024		Florida Motor Vehicle Dept. Title #0153544121		Vehicle purchase reported - Title issued or updated - Registration issued or renewed - First owner reported - Vehicle color noted as White
04/30/2024		Florida Motor Vehicle Dept. Tulsa, OK Title #0153544121		Registration issued or renewed - Vehicle color noted as White
06/26/2024	8,845	Get Spiffy Inc Durham, NC 844-438-7743 getspiffy.com/ ★ 4.5 / 5.0 414 Verified Reviews ❤️ 1 Customer Favorite		Vehicle serviced - Oil and filter changed
10/22/2024	16,236	Daytona Dodge Chrysler Jeep Ram Daytona Beach, FL 386-274-0571 daytonadodgechrysler.net ★ 4.4 / 5.0 1,405 Verified Reviews ❤️ 12,338 Customer Favorites		Vehicle serviced - A/C and heating system checked - A/C evaporator replaced
12/02/2024	18,700	Get Spiffy Inc Durham, NC 844-438-7743 getspiffy.com/ ★ 4.5 / 5.0 414 Verified Reviews ❤️ 1 Customer Favorite		Vehicle serviced - Oil and filter changed
03/11/2025	27,206	Get Spiffy Inc Durham, NC 844-438-7743 getspiffy.com/ ★ 4.5 / 5.0 414 Verified Reviews ❤️ 1 Customer Favorite		Vehicle serviced - Oil and filter changed
04/02/2025	28,035	Get Spiffy Inc Durham, NC 844-438-7743 getspiffy.com/ ★ 4.5 / 5.0 414 Verified Reviews ❤️ 1 Customer Favorite		Vehicle serviced - Vehicle washed/detailed
05/29/2025		Florida Motor Vehicle Dept. Tulsa, OK Title #0153544121		Registration issued or renewed - Vehicle color noted as White
06/10/2025	36,570	Graham Tire Of Fort Dodge, Iowa Fort Dodge, IA 515-576-7295 graham.com ★ 4.8 / 5.0 69 Verified Reviews		Vehicle serviced - Oil and filter changed - Tires rotated