

Multi-Point Inspection Checklist

RO# 6036057

Customer Name INVENTORY: 968860

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 1/13/2026 3:55 PM

Printed on 1/26/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation fb 9mm rb 8m
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 ft 6/32 rt 4/32
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required
-   Under hood labels and decals
-    Air filter and In-Cabin Air Filter equipped Found the engine air filter to be dirty
-   Battery cables and mount
-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
-   Dome , courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
LIMITED FWD	49663	49663
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2024	CHRYSLER	PACIFICA
Vehicle Identification Number		Color
2C4RC1GG5RR142306		SILVER

INVENTORY: 968860

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 169.95 MGA10649 : AIR FILTER 1@29.95 29.95	I	
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 5@8.92 44.60 R94010 : OIL FILTER 1@10.43 10.43	I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95	I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 59.95	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	463.55				
PARTS	84.98				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	578.52				



This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

★ **4.6 / 5.0**
 148 Verified Reviews

♥ **102**
 Customer Favorites



Vehicle History Report™

US \$44.99

2024 CHRYSLER PACIFICA LIMITED

VIN: 2C4RC1GG5RR142306
 VAN
 3.6L V6
 GASOLINE
 FRONT WHEEL DRIVE
 Original Window Sticker

This CARFAX Report Provided by:
Deery Brothers
 ★ 4.6 / 5.0
 148 Verified Reviews
 ♥ 102 Customer Favorites

- ✔ No accidents or damage reported to CARFAX
- ✂ 1 Service history record
- 📄 At least 1 open recall
- 1 CARFAX 1-Owner vehicle
- 🚗 Rental vehicle
- 00M **49,663** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/17/26 at 10:06:06 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
 Oil	✔ Oil and filter changed	01/15/2026
 Tires	✔ Tires rotated	01/15/2026



This car has been recently serviced. That's a good thing!

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires repair.	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2024
Type of owner	Rental
Estimated length of ownership	1 yr. 9 mo.
Owned in the following states/provinces	Illinois
Estimated miles driven per year	27,930/yr
Last reported odometer reading	49,663





Detailed History



Owner 1
Purchased: 2024

Rental Vehicle
27,930 mi/yr

Date	Mileage	Source	Comments
Not Reported		FCA US LLC	Original Window Sticker 
04/05/2024		Illinois Motor Vehicle Dept.	Vehicle purchase reported - Titled or registered as rental vehicle
04/16/2024	5	Illinois Motor Vehicle Dept. Chicago, IL	Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported - Vehicle color noted as Silver
06/24/2025		Illinois Motor Vehicle Dept. Chicago, IL	Registration issued or renewed
06/24/2025		FCA US LLC	Manufacturer Safety recall issued - NHTSA #25V-302 - Recall #54C 2022-2025 RU SIDE CURTAIN AIRBAG EJECTION MITIGATI - Status: Remedy Available Click here for a copy of the owner letter for this Recall or call 1- 800-853-1403 if you have any questions or need additional information on this recall. ➔ Learn more about this recall

Description: FCA US will conduct a voluntary safety recall on all affected vehicles to replace one or both CABs as needed. For vehicles in FCA US Recall ID 06C, FCA US will replace both CABs. For vehicles in FCA US Recall ID 54C, FCA US will replace the driver's side CAB. For vehicles in FCA US Recall ID 55C, FCA US will replace the passenger's side CAB.

Curtain airbags which do not have proper pressure retention may reduce occupant protection and increase the risk of partial and complete ejection and injury of an occupant through a side window during certain types of crashes.

Remedy: FCA US will conduct a voluntary safety recall on all affected vehicles to replace one or both CABs as needed. For vehicles in FCA US Recall ID 06C, FCA US will replace both

CABs. For vehicles in FCA US Recall ID 54C, FCA US will replace the driver's side CAB. For vehicles in FCA US Recall ID 55C, FCA US will replace the passenger's side CAB.

01/07/2026 Online Listing **Vehicle offered for sale**

01/14/2026 49,663 Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/
★ 4.6 / 5.0
148 Verified Reviews
❤️ 102 Customer Favorites **Vehicle offered for sale**

01/15/2026 Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/
★ 4.6 / 5.0
148 Verified Reviews
❤️ 102 Customer Favorites **Vehicle serviced**
- Maintenance inspection completed
- Air filter replaced
- Oil and filter changed
- Tires rotated



Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

01/17/2026 CARFAX Car Care **Manufacturer Recommended Maintenance Schedules**



Get this vehicle's maintenance schedule, service history and recall alerts at [carfax.com/service](https://www.carfax.com/service).

Have Questions? Please visit our Help Center at www.carfax.com.

CARFAX Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Rental

Vehicle was registered by a rental agency.