

Multi-Point Inspection Checklist

RO# 6038842

Customer Name INVENTORY: 969680

Advisor Name Jim Smith

Technician Name TYLER MCWILLIAMS

Created on 4/16/2026 7:39 AM

Printed on 4/16/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time
- May Require Future Attention
- Requires immediate attention

Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 7/32nds Front and Back
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required N/A
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped Caution TS
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 10MM Front and Back
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER N/A
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager *[Signature]* _____ Date 4.16.26

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

			Work Phone	R/O Open Date	R/O Number
				04/16/26	6038842/1
			Home Phone	R/O Close Date	Receipt No
				04/16/26	Original
			Body	Mileage In	Mileage Out
			4WD CREW CAB	14779	14782
YEAR	MAKE	Model	License Number	Service Advisor	
2026	CHEVROLET	SILVERADO 150		Jim Smith	131
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
2GCUKEED2T1114904		BLACK			

INVENTORY: 969680

#1 - MR 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FI ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work by Tech 649/4925 0.40hrs @ 195.58 19432337 : N-OIL (08800-BOPCK) 8@9.60 12735811 : SI-N-FILTER (01836-BOPCKT) 1@6.95 Changed oil and filter and topped off fluids.	LL	I	78.23 76.80 6.95	37.04 5.61
#2 - MR 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 649/4925 1.00hrs @ 178.95 56 point inspection.		I	178.95	
#3 - MR GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTAT Work by Tech 649/4925* 0.90hrs Balanced and rotated tires.	E	I	99.00	
#4 - MR ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTE COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work by Tech 649/4925* 1.50hrs Alignment performed.	D	I	159.95	
#5 - MR RECALL: CHECK FOR OPEN RECALLS Checked for recalls.		I		
#6 * MR ICF: REPLACED IN CABIN AIR FILTER Corrected by ICF: REPLACED IN CABIN AIR FILTER Work by Tech 649/4925* 0.10hrs		I	12.00	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT			Work Phone	R/O Open Date	R/O Number
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655			Home Phone	R/O Close Date	Receipt No
			Body	Mileage In	Mileage Out
			4WD CREW CAB	14779	14782
YEAR	MAKE	Model	License Number	Service Advisor	
2026	CHEVROLET	SILVERADO 150		Jim Smith	131
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
2GCUKEED2T1114904		BLACK			

INVENTORY: 969680

19338055 : SL-N-FILTER (09786-BOPCKT)	1@29.95	29.95		20.33	
Replaced cabin filter.					

#7 * MR AF: REPLACED ENGINE AIR FILTER					
Corrected by AF: REPLACED ENGINE AIR FILTER					
Work by Tech 649/4925*	0.10hrs	12.00			
84121217 : SL-N-ELEMENT (03410-CT)	1@49.95	49.95		35.91	
Replaced engine filter.					

Line 1	4/16/26	Tech 649	Start 7:42	End 8:03	Hours .40
Line 2	4/16/26	Tech 649	Start 8:03	End 8:13	Hours .20
Line 3	4/16/26	Tech 649	Start 9:13	End 9:26	Hours .20
Line 4	4/16/26	Tech 649	Start 8:50	End 9:12	Hours .40
Line 5	4/16/26	Tech 649	Start 8:41	End 8:41	Hours .00
Line 6	4/16/26	Tech 649	Start 8:42	End 8:49	Hours .10
Line 7	4/16/26	Tech 649	Start 8:49	End 8:49	Hours .00
Account	Description	Control	Re	ference	Amount
46300	SLS-SRV-INTERNAL MECH LABOR-G	6038842		6038842	-540.13
49100	SLS-PTS-GAS OIL & GREASE	6038842		6038842	-79.90
69100	CST-PTS-GAS OIL & GREASE	6038842		6038842	56.24
24200	INVENTORY-PTS/ACC-GM	6038842		6038842	-56.24
48100	SLS-PTS-INTERNAL RO - GM	6038842		6038842	-6.95
68100	CST-PTS-INTERNAL RO - GM	6038842		6038842	5.61
24200	INVENTORY-PTS/ACC-GM	6038842		6038842	-5.61
49100	SLS-PTS-GAS OIL & GREASE	6038842		6038842	-76.80
69100	CST-PTS-GAS OIL & GREASE	6038842		6038842	37.04
24200	INVENTORY-PTS/ACC-GM	6038842		6038842	-37.04
66900	CST-SRV-MECH SHOP SUPPLIES	6038842		6038842	-29.99
24100	INVENTORY - USED TRUCKS	969680		6038842	733.77

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR	540.13				
PARTS	163.65				98.89
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	733.77				98.89



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
160 Verified Reviews

♥ **101**
Customer Favorites



Report

US \$44.99

2026 Chevrolet Silverado 1500 RST

14,779 mi | VIN: 2GCUKEED2T1114904 |

Crew Pickup | 5.3L V8 F OHV 16V | Gasoline | Rear wheel drive w/ 4X4



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

CARFAX VALUE \$45,530

🔧 1 Service History Record

1 CARFAX 1-Owner Vehicle

🚗 Rental Vehicle

🌍 Last Owned in Illinois

📄 5 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/18/26 at 9:03:52 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	04/16/2026
🛞 Tires	✓ Tires rotated	04/16/2026

This car has been recently serviced. That's a good thing!



History-Based Value Report

\$45,530

CARFAX Retail Value

History events affecting this vehicle's value

↑ ✓ No Accidents Reported

- 1-Owner Vehicle
- Service History
- Non-Personal Vehicle

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.

No Issues Reported

Structural Damage

No structural damage reported to CARFAX.

No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

Odometer Check

No indication of an odometer rollback.

No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.

No Issues Reported

Manufacturer Recall

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

No Recalls Reported

Basic Warranty

Original warranty estimated to have 30 months or 21,221 miles remaining. Confirm with dealer or vehicle manufacturer.

Warranty Active

CARFAX Title History

CARFAX guarantees the information in this section

Owner 1

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

Guaranteed No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

CARFAX Ownership History

The number of owners is estimated

Owner 1

Year purchased

2025

Type of owner

Rental

Estimated length of ownership

6 months

Owned in the following states/provinces

Illinois

Estimated miles driven per year

Last reported odometer reading



14,779



CARFAX Detailed History

Owner 1 Rental Vehicle
Purchased: 2025

Date	Mileage	Source	Comments
------	---------	--------	----------

Not Reported		General Motors	Original Window Sticker 
09/30/2025		Illinois Motor Vehicle Dept.	Vehicle purchase reported - Titled or registered as rental vehicle
10/10/2025	10	Illinois Motor Vehicle Dept. Lombard, IL Title #252836920650	Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported - Vehicle color noted as Black
04/16/2026	14,512	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 160 Verified Reviews ♥ 101 Customer Favorites	Vehicle offered for sale
04/16/2026	14,779	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 160 Verified Reviews ♥ 101 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Air filter replaced - Cabin air filter replaced/cleaned - Oil and filter changed - Tires rotated

Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

CARFAX Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Rental

Vehicle was registered by a rental agency.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  facebook.com/CARFAX  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
4/18/26 9:03:52 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2026 CHEVROLET SILVERADO 1500 vehicle (VIN: 2GCUKEED2T1114904), which is based on information supplied to CARFAX and available as of 4/18/26 at 10:03 AM (EDT).

Customer Signature

Date

Dealer Signature

Date