

Multi-Point Inspection Checklist

RO# 6036973

Customer Name INVENTORY: 500191

Advisor Name AMANDA KEPHART

Technician Name Kevin Randall

Created on 2/12/2026 11:11 AM

Printed on 3/3/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-    Cold Engine start-up Pass
-    Engine operation warm-up Pass
-    Engine at normal operating temperature Caution, Pass
-    Brake and parking operation Pass
-    Active seat belt test Pass
-    Clutch and transmission operations Pass
-    Overdrive operation Pass
-    Transfer case operation (4-wheel drive only) Pass
-    Steering operation and off center Pass
-    Front end alignment Pass
-    Tilt steering wheel operation Pass
-    Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-    Speedometer and odometer operation Pass
-    Cruise Control operation, including resume Pass
-    Heater and air condition operation Pass
-    Abnormal noises and vibrations Pass
-    Squeaks and rattles Pass
-    Frame Check Pass
-    Body surface, lower body, and upper body damage requiring body shop repair Pass
-    Tire defects and damage, 5/32 7/32 ALL
-    ~~Drive shaft, joints, CV's and boots Pass~~
-    Struts/shock absorbers, leaks and wear Pass
-    Exhaust system leaks and damage, including catalytic converter Pass
-    Fuel, oil, coolant, or other fluid leaks Pass
-    Perform emissions test and/or state inspection if required Pass
-    Under hood labels and decals Pass
-    Air filter and In-Cabin Air Filter equipped Pass
-    Battery cables and mount Pass
-    Coolant level and test Pass
-    Under hood fluid levels, including transmission and transfer case fluids Pass
-    Drive belts and hoses Pass
-    Air conditioning levels, check at sight glass Pass
-    Warning lights (including air bag) gauges & horn Pass
-    Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-    Inside and outside rearview mirror operation, adjustment, and condition Pass
-    Glass free of cracks, starts and large chips Pass
-    Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6MM ALL
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician Date

Service Manager Date

Used Car Manager Date

Customer Date

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

| | | | |
|-------------------------------|--------|-----------------|-----------------|
| Work Phone | | R/O Open Date | R/O Number |
| Home Phone | | 2/12/26 | 6036973/1 |
| Body | | R/O Close Date | Receipt No. |
| SEDAN | | 2/27/26 | Original |
| License Number | | Mileage In | Mileage Out |
| | | 81179 | 81179 |
| Year | Make | Service Advisor | |
| 2019 | TOYOTA | AMANDA KEPHART | |
| Model | | Account No. | In-Service Date |
| COROLLA | | Delivery Date | |
| Vehicle Identification Number | | | |
| 2T1BURHE9KC146407 | | | |
| Color | | | |
| WHITE | | | |

INVENTORY: 500191

| | | |
|--|---|--|
| #1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 256/ 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 5@8.92 44.60 90915-YZZN1 : FILTER, OIL 1@9.53 9.53 OIL AND NEW FILTER ADDED | I | |
| #2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95 INSPECTION COMPLETE | I | |
| #3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 256/ * 0.90hrs 99.00 TIRES ROTATED AND BALLANCED | I | |
| #4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 256/ * 1.50hrs 159.95 ALINGMENT COMPLETE | I | |
| #5 * 20TA02: TOYOTA RECALL 20TA02 - VEHICLE MAY STALL DURING DR IVING AT HIGHER SPEED Corrected by SOP: PARTS TO REPAIR YOUR VEHICLE HAD TO BE SPECIAL ORDERED. WE WILL CONTACT YOU AS SOON AS WE RECEIVE TH E REQUIRED PARTS TO REPAIR YOUR | I | |

| | INTERNAL | SERVICE CONT. | WARRANTY | CUSTOMER PAY | COST |
|-----------------------|----------|---------------|----------|--------------|------|
| LABOR | | | | | |
| PARTS | | | | | |
| DEDUCTIBLE | | | | | |
| SUBLET | | | | | |
| SHOP SUPPLIES | | | | | |
| HAZARDOUS MATERIALS | | | | | |
| SALES TAX OR TAX I.D. | | | | | |
| SPECIAL ORDER DEPOSIT | | | | | |
| DISCOUNTS | | | | | |

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

| | | |
|----------------|-----------------|-----------------|
| Work Phone | R/O Open Date | R/O Number |
| Home Phone | R/O Close Date | Receipt No. |
| Body | Mileage In | Mileage Out |
| License Number | Service Advisor | |
| Account No. | Delivery Date | In-Service Date |

| | | |
|-------------------------------|--------|---------|
| Year | Make | Model |
| 2019 | TOYOTA | COROLLA |
| Vehicle Identification Number | Color | |
| 2T1BURHE9KC146407 | WHITE | |

| | | |
|----------------|-------|-------|
| SEDAN | 81179 | 81179 |
| AMANDA KEPHART | | |

INVENTORY: 500191

VEHICLE. IF YOU HA VE ANY FURTHER QUESTIONS PLEASE
 VEHICLE. IF YOU HA VE ANY FURTHER QUESTIONS PLEASE
 CONTACT THE SERVIC LRATE:180.14

| | | |
|------------------------------------|-----------|---------|
| Work performed by Tech 256/ | 0.00hrs @ | |
| 04009-80112 : REPLACEMENT KIT, FUE | 1@0.97 | Ordered |
| 04009-86237 : KIT, PUMP, FUEL | 1@246.89 | Ordered |
| 04009-95102 : HOLDER, FUEL TANK PI | 1@1.12 | Ordered |
| 04009-95202 : RETAINER, FP GAUGE, | 1@28.32 | Ordered |

| | INTERNAL | SERVICE CONT. | WARRANTY | CUSTOMER PAY | COST |
|-----------------------|----------|---------------|----------|--------------|------|
| LABOR | 502.60 | | | | |
| PARTS | 54.13 | | | | |
| DEDUCTIBLE | | | | | |
| SUBLET | | | | | |
| SHOP SUPPLIES | 29.99 | | | | |
| HAZARDOUS MATERIALS | | | | | |
| SALES TAX OR TAX I.D. | | | | | |
| SPECIAL ORDER DEPOSIT | | | | | |
| DISCOUNTS | | | | | |
| | 586.72 | | | | |



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
153 Verified Reviews

♥ **101**
Customer Favorites



Vehicle History Report™

US \$44.99

2019 TOYOTA COROLLA LE

VIN: 2T1BURHE9KC146407
SEDAN 4 DR
1.8L I4 F DOHC 16V
GASOLINE
FRONT WHEEL DRIVE
Original Window Sticker

This CARFAX Report Provided by:

Deery Brothers

★ 4.6 / 5.0

153 Verified Reviews

♥ 101 Customer Favorites

Damage reported

14 Service history records

At least 1 open recall

3 Previous owners

Types of owners: Rental, Personal

81,178 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/21/26 at 4:37:07 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

12/12/2019

Damage reported



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Owner 2

Owner 3

Total Loss

No total loss reported to CARFAX.

No Issues Reported

No Issues Reported

No Issues Reported

| | | | |
|---|---|---|---|
| Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist. | <input checked="" type="checkbox"/> No Issues Reported | <input checked="" type="checkbox"/> No Issues Reported | <input checked="" type="checkbox"/> No Issues Reported |
| Airbag Deployment No airbag deployment reported to CARFAX. | <input checked="" type="checkbox"/> No Issues Reported | <input checked="" type="checkbox"/> No Issues Reported | <input checked="" type="checkbox"/> No Issues Reported |
| Odometer Check No indication of an odometer rollback. | <input checked="" type="checkbox"/> No Issues Indicated | <input checked="" type="checkbox"/> No Issues Indicated | <input checked="" type="checkbox"/> No Issues Indicated |
| Accident / Damage Damage reported: 12/12/2019. | Damage Reported | No New Issues Reported | No New Issues Reported |
| Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Toyota dealer near you to schedule an appointment. View Toyota disclosure | Recall Reported | No New Recalls Reported | No New Recalls Reported |
| Basic Warranty Original warranty estimated to have expired. | Warranty Expired | Warranty Expired | Warranty Expired |

|  Title History CARFAX guarantees the information in this section | Owner 1 | Owner 2 | Owner 3 |
|---|---|---|---|
| Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon | <input checked="" type="checkbox"/> Guaranteed No Problem | <input checked="" type="checkbox"/> Guaranteed No Problem | <input checked="" type="checkbox"/> Guaranteed No Problem |
| Odometer Brands Not Actual Mileage Exceeds Mechanical Limits | <input checked="" type="checkbox"/> Guaranteed No Problem | <input checked="" type="checkbox"/> Guaranteed No Problem | <input checked="" type="checkbox"/> Guaranteed No Problem |



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

|  Ownership History The number of owners is estimated | Owner 1 | Owner 2 | Owner 3 |
|---|-------------|-------------|---------------|
| Year purchased | 2018 | 2020 | 2022 |
| Type of owner | Rental | Personal | Personal |
| Estimated length of ownership | 1 year | 1 yr. 5 mo. | 3 yrs. 11 mo. |
| Owned in the following states/provinces | See Details | Iowa | Iowa |
| Estimated miles driven per year | 31,454/yr | --- | --- |
| Last reported odometer reading | 43,627 | 75,271 | 81,178 |