


Multi-Point Inspection Form

RO# 6037369
 INVENTORY: 969090
 VIN 2T3P1RFVXSC526283
 Advisor JAKE BACHTELL
 Technician Dylan Miller
 Created On 3/3/2026

Checked and OK at this time May Require Future Attention Requires immediate attention

Interior / Exterior	
<input checked="" type="checkbox"/>	<input type="checkbox"/> Bulbs and Lights
<input checked="" type="checkbox"/>	<input type="checkbox"/> Windshield Washer Spray / Wiper Operation / Wiper Blades / Including Rear (if applicable)
<input checked="" type="checkbox"/>	<input type="checkbox"/> Windshield / Window Condition
<input checked="" type="checkbox"/>	<input type="checkbox"/> Upholstery / Carpet / Floor Mats / Mirrors / Trim
<input checked="" type="checkbox"/>	<input type="checkbox"/> Horn Operation
<input type="checkbox"/>	<input type="checkbox"/> Clutch Operation (if equipped)
<input type="checkbox"/>	<input checked="" type="checkbox"/> Cabin/HEPA Filter (if equipped)
Battery Performance	
<input checked="" type="checkbox"/>	<input type="checkbox"/> Battery Terminals / Cables / Mountings
<input checked="" type="checkbox"/>	<input type="checkbox"/> Check Condition of Battery (Storage Capacity Test if Applicable)
Under Hood	
<input checked="" type="checkbox"/>	<input type="checkbox"/> Fluids: Oil / Coolant / Power Steering / Brake Fluid / Washer
<input type="checkbox"/>	<input checked="" type="checkbox"/> Engine Air Filter
<input checked="" type="checkbox"/>	<input type="checkbox"/> Belts / Tensioners (condition and adjustment)
<input checked="" type="checkbox"/>	<input type="checkbox"/> Cooling System Hoses / Heater Hoses / Air Conditioning Hoses and Connections
<input checked="" type="checkbox"/>	<input type="checkbox"/> Radiator Core / Air Conditioning Condenser (if equipped)

Under Vehicle	
<input checked="" type="checkbox"/>	<input type="checkbox"/> Shock Absorbers / Suspension
<input checked="" type="checkbox"/>	<input type="checkbox"/> Steering Gear Box / Linkage and Boots / Ball Joints / Dust Covers
<input checked="" type="checkbox"/>	<input type="checkbox"/> Muffler / Exhaust Pipes / Mountings
<input checked="" type="checkbox"/>	<input type="checkbox"/> Engine Oil and/or Fluid Leaks
<input checked="" type="checkbox"/>	<input type="checkbox"/> Drive Shaft Boots / Constant Velocity Boots / U-joints / Transmission Linkage (if equipped)
<input checked="" type="checkbox"/>	<input type="checkbox"/> Transmission / Differential / Transfer Case (Check Fluid Level, Fluid Condition and Fluid Leaks)
<input checked="" type="checkbox"/>	<input type="checkbox"/> Fuel Lines and Connections / Fuel Tank Band / Fuel Tank Vapor Vent System Hoses
<input checked="" type="checkbox"/>	<input type="checkbox"/> Inspect Nuts and Bolts on Body Chassis
Tread Depth (measured in 1/32")	
	
<input type="checkbox"/>	<input type="checkbox"/> LF <u>5</u>
<input type="checkbox"/>	<input type="checkbox"/> RF <u>5</u>
<input type="checkbox"/>	<input type="checkbox"/> LR <u>5</u>
<input type="checkbox"/>	<input type="checkbox"/> RR <u>5</u>
<input type="checkbox"/>	<input type="checkbox"/> Spare Tire (if applicable)
<input type="checkbox"/>	<input type="checkbox"/> LF/RF Tire Pressure <u>35</u>
<input type="checkbox"/>	<input type="checkbox"/> LR/RR Tire Pressure <u>35</u>

Abnormal Wear Pattern of Tires	
<input type="checkbox"/>	<input type="checkbox"/> LF
<input type="checkbox"/>	<input type="checkbox"/> RF
<input type="checkbox"/>	<input type="checkbox"/> LR
<input type="checkbox"/>	<input type="checkbox"/> RR
Check Brake Linings (measured in millimeters)	
<input checked="" type="checkbox"/>	<input type="checkbox"/> LF <u>10</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/> RF <u>10</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/> LR <u>10</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/> RR <u>10</u>

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone		R/O Open Date	R/O Number
Home Phone		2/25/26	6037369/1
Body		R/O Close Date	Receipt No.
XLE AWD		2/27/26	Original
License Number		Mileage In	Mileage Out
		25837	25837
Year	Make	Service Advisor	
2025	TOYOTA	JAKE BACHTELL	
Model		Account No.	In-Service Date
RAV4		Delivery Date	
Vehicle Identification Number		Color	
2T3P1RFVXSC526283		GRAY METAL	

INVENTORY: 969090

<p>#1 - TOYCERT: TOYOTA USED CAR CERTIFICATION Corrected by TOYCERT: TOYOTA USED CAR CERTIFICATION LRATE:195.45 Work performed by Tech 461/4 2.00hrs @ 195.45 390.90 00279-BLK16-01 : GTMO OW16 BK SP WTY 5@9.60 48.00 90915-YZZN1 : FILTER, OIL 1@9.53 9.53 performed toyota certification. cert# 2060475812</p>		I
<p>#2 * ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 461/4 * 1.50hrs 159.95 performed alignment. rear toe and front toe were out of specs. set rear toe then set front toe. test drove and wheel was straight and vehicle drove straight.</p>		I
<p>#3 * GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 461/4 * 0.90hrs 99.00 rotated and balanced all four wheels</p>		I
<p>#4 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 461/4 * 0.10hrs 12.00 87139-YZZ93 : ELEMENT, AIR REFINER 1@49.95 49.95 replaced cabin filter</p>		I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2025	TOYOTA	RAV4
Vehicle Identification Number	Color	
2T3P1RFVXSC526283	GRAY METAL	

2/25/26	6037369/2
2/27/26	Original
XLE AWD	25837
JAKE BACHTELL	25837

INVENTORY: 969090


#5 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT

Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00

Work performed by Tech 461/4	* 0.10hrs	12.00
17801-F0050 : ELEMENT SUB-ASSY, AI	1@29.95	29.95
replaced engine air filter		

I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	673.85				
PARTS	137.43				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	841.27				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
154 Verified Reviews

♥ **101**
Customer Favorites



Vehicle History Report™

US \$44.99

2025 TOYOTA RAV4 XLE

VIN: 2T3P1RFVXSC526283
4 DOOR WAGON/SPORT UTILITY
2.5L I4 F DOHC 16V GASOLINE
ALL WHEEL DRIVE
Original Window Sticker
This CARFAX Report Provided by:

Deery Brothers

★ 4.6 / 5.0

154 Verified Reviews

♥ 101 Customer Favorites



No accidents or damage reported to CARFAX



Regular oil changes



CARFAX 1-Owner vehicle



Rental vehicle



Last owned in Iowa



25,831 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/28/26 at 12:08:43 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.




Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	02/24/2026
Tires	✓ Tires rotated	12/15/2025

This car has been recently serviced. That's a good thing!

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. View Toyota disclosure	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have 27 months or 10,169 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2025
Type of owner	Rental
Estimated length of ownership	9 months
Owned in the following states/provinces	Iowa
Estimated miles driven per year	---



Last reported odometer reading

25,831






Detailed History










Owner 1

Purchased: 2025

Rental Vehicle

Date	Mileage	Source	Comments
04/07/2025		Toyota Motor Sales, USA, Inc.	Original Window Sticker 
04/17/2025		Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 154 Verified Reviews ❤️ 101 Customer Favorites	Vehicle offered for sale
05/01/2025 1		Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 154 Verified Reviews ❤️ 101 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Oil and filter changed - Vehicle washed/detailed
05/01/2025		Iowa Motor Vehicle Dept. West Burlington, IA	Titled or registered as rental vehicle
05/12/2025 175		Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 154 Verified Reviews ❤️ 101 Customer Favorites	 Vehicle serviced - Vehicle washed/detailed
05/15/2025		Iowa Motor Vehicle Dept. West Burlington, IA	Title or registration issued - First owner reported - Titled or registered as rental vehicle - Vehicle color noted as Gray

06/26/2025	1,473	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 154 Verified Reviews ❤️ 101 Customer Favorites	 Vehicle serviced - Vehicle washed/detailed
07/10/2025	2,492	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 154 Verified Reviews ❤️ 101 Customer Favorites	 Vehicle serviced - Vehicle washed/detailed
07/22/2025	2,846	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 154 Verified Reviews ❤️ 101 Customer Favorites	 Vehicle serviced - Vehicle washed/detailed
08/08/2025	5,333	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 154 Verified Reviews ❤️ 101 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated - Vehicle washed/detailed
08/21/2025	8,353	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 154 Verified Reviews ❤️ 101 Customer Favorites	 Vehicle serviced - Vehicle washed/detailed
09/03/2025	9,782	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 154 Verified Reviews ❤️ 101 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - 5,000 mile service performed - Oil and filter changed - Tires rotated - Vehicle washed/detailed
09/19/2025	12,460	Deery Brothers West Burlington, IA 319-752-6000	 Vehicle serviced - Vehicle washed/detailed