

Multi-Point Inspection Checklist

RO# 6037452

Customer Name INVENTORY: 969110

Advisor Name JAKE BACHTELL

Technician Name Dylan Miller

Created on 2/27/2026 5:56 PM

Printed on 3/19/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 all four tires are at 7/32nds
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER missing owners manual and floor mats
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2025	FORD	BRONCO SPORT
Vehicle Identification Number	Color	
3FMCR9DA6SRE46775	BROWN	

BADLANDS 4X4	13481	13481
JAKE BACHTELL		

INVENTORY: 969110

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 461/4 1.00hrs @ 169.95 performed 56 point inspection	I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 461/4 0.40hrs @ 184.25 19419537 : N-OIL (08800-BOPCKT) 6@9.60 57.60 19419226 : SL-N-FILTER (01836-BOPCKT) 1@6.90 6.90 changed engine oil and filter. reset maintenance and installed sticker	I	73.70 57.60 6.90
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 461/4 * 1.50hrs performed alignment. front toe was out of specs. set front toe and test drove. wheel was straight and vehicle drove straight	I	159.95
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 461/4 * 0.90hrs rotated and balanced all four wheels	I	99.00

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	502.60				
PARTS	64.50				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	597.09				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
154 Verified Reviews

♥ **101**
Customer Favorites



Vehicle History Report™

US \$44.99

2025 FORD BRONCO SPORT BADLANDS

VIN: 3FMCR9DA6SRE46775
4 DOOR WAGON/SPORT
UTILITY
2.0L I4 F DOHC 16V
GASOLINE
FRONT WHEEL DRIVE W/ 4X4
Original Window Sticker
This CARFAX Report Provided
by:

Deery Brothers

★ 4.6 / 5.0

154 Verified Reviews

♥ 101 Customer Favorites



No accidents or damage reported to CARFAX



2 Service history records



CARFAX 1-Owner vehicle



Rental vehicle



Last owned in Minnesota



13,481 Last reported odometer reading




This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/5/26 at 6:16:01 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.





Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	03/04/2026
	This car has been recently serviced. That's a good thing!	

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. A current list of recalls is available at Ford Motor Company.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have 25 months or 22,519 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2025
Type of owner	Rental
Estimated length of ownership	7 months
Owned in the following states/provinces	Minnesota
Estimated miles driven per year	---



Last reported odometer reading




13,481

CARFAX Detailed History



Owner 1
Purchased: 2025

Rental Vehicle

Date	Mileage	Source	Comments
Not Reported		Ford Motor Company	<p>Vehicle manufactured and shipped to original dealer</p> <p>Original Window Sticker</p> 
03/24/2025	15	Minnesota Motor Vehicle Dept.	<p>Vehicle purchase reported - Titled or registered as rental vehicle</p>
03/31/2025		Minnesota Motor Vehicle Dept. Saint Paul, MN	<p>Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported</p>
11/18/2025		Online Listing	<p>Vehicle offered for sale</p>
02/10/2026	13,359	Golf Mill Ford Niles, IL 847-470-9800 golfmillford.com ★ 4.6 / 5.0 1,584 Verified Reviews ❤️ 15,773 Customer Favorites	 <p>Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Computer(s) checked - Computer reprogrammed - Tire condition and pressure checked</p>
02/23/2026		Auto Auction	<p>Vehicle sold</p> <div style="border: 1px solid blue; padding: 5px; margin-top: 10px;"> Millions of used vehicles are bought and sold at auction every year. </div>
02/28/2026	13,481	 Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 154 Verified Reviews	<p>Vehicle offered for sale</p>