

Multi-Point Inspection Checklist

RO# 6038888

Customer Name INVENTORY: 969700

Advisor Name Jim Smith

Technician Name Kevin Randall

Created on 4/17/2026 7:39 AM

Printed on 4/17/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time May Require Future Attention Requires immediate attention

Maintenance Service


- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 all 8/32 all 8/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required N/A N/A
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped
- Battery cables and mount
- Coolant level and test -40 -40
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness FRONT 8MM REAR 6MM
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager  _____ Date 4-17-26

Used Car Manager _____ Date _____


Customer _____ Date _____

REPAIR ORDER - AUDIT			Work Phone	R/O Open Date	R/O Number
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655			Home Phone	R/O Close Date	Receipt No
			Body	Mileage In	Mileage Out
			4WD CREW CAB	22887	22889
			License Number	Service Advisor	
YEAR	MAKE	Model		Jim Smith	131
2024	CHEVROLET	SILVERADO 150			
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
3GCUDDE85RG386676		SLATE GRAY			

INVENTORY: 969700

#1 - MR 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FI ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work by Tech 425/1380 0.40hrs @ 195.58 19458926 : SL-N-FILTER (01836-BOPCKT) 106.95 19370138 : N-OIL (08800-BOPCKT) 709.33 PERFORMED SERVICE	LL	I	78.23 6.95 65.31	12.80 5.92 48.72
#2 - MR 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 425/1380 1.00hrs @ 178.95 INSPECTION PERFORMED		I	178.95	32.00
#3 - MR GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTAT Work by Tech 425/1380* 0.90hrs SERVICE PERFORMED	E	I	99.00	28.80
#4 - MR ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTE COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work by Tech 425/1380* 1.50hrs PERFORMED ALIGNMENT	D	I	159.95	48.00
#5 - MR RECALL: CHECK FOR OPEN RECALLS		I		
#6 * MR DFF: REPLACE DIESEL FUEL FILTER AND BLEED AIR FROM SYST EM Corrected by DFF: REPLACE DIESEL FUEL FILTER AND BLEED AIR FROM SYST EM		I		

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
160 Verified Reviews

♥ **101**
Customer Favorites



Report

US \$44.99

2024 Chevrolet Silverado 1500 LT

22,749 mi | VIN: 3GCUUDE85RG386676 |
Crew Pickup | 3.0L I6 F DOHC 24V | Diesel | Rear wheel drive w/ 4X4

CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION



BRANDED TITLE

! Buyback/Lemon

ACCIDENT Minor Damage



Minor Moderate Severe

CARFAX VALUE \$42,330

🛢️ Regular Oil Changes

1 CARFAX 1-Owner Vehicle

🏠 Personal Vehicle

🌍 Last Owned in California

📄 22 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/18/26 at 9:00:01 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

04/02/2025

Accident reported: minor damage

- Vehicle involved in a rear-end collision with another motor vehicle
- Airbags did not deploy

Damage Severity Scale



Minor Moderate Severe

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	12/31/2025

Tires

Tires rotated

12/31/2025

This car has been recently serviced. That's a good thing!

CARFAX History-Based Value Report

\$42,330

CARFAX Retail Value

History events affecting this vehicle's value

- 1-Owner Vehicle
- Regular Oil Changes
- Buyback / Lemon
- Minor Damage

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.

No Issues Reported

Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

Odometer Check

No indication of an odometer rollback.

No Issues Indicated

Accident / Damage

Accident reported: 04/02/2025.

Minor Damage

Manufacturer Recall

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

No Recalls Reported

Basic Warranty

Original warranty estimated to have 18 months or 13,251 miles remaining. Confirm with dealer or vehicle manufacturer.

Warranty Active

CARFAX Title History

Owner 1

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

Alert!
Problem Found

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

No Problem



ALERT! - Severe problems were reported by a state Department of Motor Vehicles (DMV). This vehicle does not qualify for the CARFAX Buyback Guarantee.

CARFAX Ownership History

The number of owners is estimated

Owner 1

Year purchased

2024

Type of owner









Personal

Estimated length of ownership	1 yr. 5 mo.
Owned in the following states/provinces	California
Estimated miles driven per year	15,069/yr
Last reported odometer reading	22,749

CARFAX Detailed History

Owner 1 Personal Vehicle
 Purchased: 2024 15,069 mi/yr

Date	Mileage	Source	Comments
Not Reported		General Motors	Original Window Sticker
07/31/2024	5	STEVES Chevrolet of Oakdale, Inc Oakdale, CA 209-845-7910 steveschevroletoakdale.com/ ★ 4.9 / 5.0 648 Verified Reviews ♥ 4,755 Customer Favorites	Vehicle offered for sale
08/15/2024	19	STEVES Chevrolet of Oakdale, Inc Oakdale, CA ★ 4.9 / 5.0 648 Verified Reviews ♥ 4,755 Customer Favorites	Vehicle serviced - Pre-delivery inspection completed - Accessories installed - No-start/hard start condition checked
08/28/2024		Steves Chevrolet of Chowchilla Chowchilla, CA 559-715-4626 steveschevroletchowchilla.com ★ 5.0 / 5.0 201 Verified Reviews ♥ 2,185 Customer Favorites	Vehicle offered for sale
09/27/2024	20	STEVES Chevrolet of Oakdale, Inc Oakdale, CA 209-845-7910 steveschevroletoakdale.com/ ★ 4.9 / 5.0 648 Verified Reviews ♥ 4,755 Customer Favorites	Vehicle offered for sale
09/30/2024	158	California Motor Vehicle Dept. Oakdale, CA	Odometer reading reported
10/11/2024		California Motor Vehicle Dept. Oakdale, CA	Title issued or updated - First owner reported - Titled or registered as personal vehicle
02/09/2025	6,566	STEVES Chevrolet of Oakdale, Inc Oakdale, CA ★ 4.9 / 5.0 648 Verified Reviews ♥ 4,755 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Tires rotated
03/24/2025	7,585	STEVES Chevrolet of Oakdale, Inc Oakdale, CA ★ 4.9 / 5.0 648 Verified Reviews ♥ 4,755 Customer Favorites	Vehicle serviced - Tire condition and pressure checked

04/02/2025		Damage Report		<p>Accident reported: minor damage</p> <ul style="list-style-type: none"> - Vehicle involved in a rear-end collision with another motor vehicle - Airbags did not deploy
<div style="border: 1px solid #ccc; padding: 5px; width: fit-content; margin: 0 auto;"> <p>Damage Severity Scale</p>  <p>Minor Moderate Severe</p> </div>				
<div style="border: 1px solid #ccc; padding: 5px; width: fit-content; margin: 0 auto;"> <p>Minor damage is usually cosmetic, including dents or scratches to the vehicle body.</p> </div>				
04/08/2025	9,049	<p>McCoy Tire Co. Inc Modesto, CA 209-491-0206 mccoypassengertire.com/location.aspx</p> <p>★ 4.9 / 5.0 154 Verified Reviews ♥ 46 Customer Favorites</p>		<p>Vehicle serviced</p> <ul style="list-style-type: none"> - Tire condition and pressure checked
05/30/2025	13,196	<p>Nereson Chevrolet Detroit Lakes, MN 800-279-1746 neresonautomotive.com/</p> <p>★ 4.8 / 5.0 61 Verified Reviews ♥ 45 Customer Favorites</p>		<p>Vehicle serviced</p> <ul style="list-style-type: none"> - Maintenance inspection completed - Engine/powertrain computer/module checked
07/31/2025	15,198	<p>STEVES Chevrolet of Oakdale, Inc Oakdale, CA</p> <p>★ 4.9 / 5.0 648 Verified Reviews ♥ 4,755 Customer Favorites</p>		<p>Vehicle serviced</p> <ul style="list-style-type: none"> - Maintenance inspection completed - Heater core replaced - Oil and filter changed - Tire condition and pressure checked - Tires rotated
10/31/2025	19,650	<p>STEVES Chevrolet of Oakdale, Inc Oakdale, CA</p> <p>★ 4.9 / 5.0 648 Verified Reviews ♥ 4,755 Customer Favorites</p>		<p>Vehicle serviced</p>
12/31/2025	22,116	<p>STEVES Chevrolet of Oakdale, Inc Oakdale, CA</p> <p>★ 4.9 / 5.0 648 Verified Reviews ♥ 4,755 Customer Favorites</p>		<p>Vehicle serviced</p> <ul style="list-style-type: none"> - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Tires rotated
01/10/2026		General Motors, LLC		<p>VEHICLE REACQUIRED</p> <p>Vehicle reacquired by the manufacturer pursuant to applicable state consumer warranty laws or to promote customer satisfaction.</p> <p>Reason provided by Manufacturer:</p> <ul style="list-style-type: none"> - HVAC Odor.
01/10/2026	22,337	California Motor Vehicle Dept.		Odometer reading reported
01/23/2026		California Motor Vehicle Dept. Oakdale, CA		<p>Title issued or updated</p> <ul style="list-style-type: none"> - Loan or lien reported
01/30/2026		<p>STEVES Chevrolet of Oakdale, Inc Oakdale, CA</p> <p>★ 4.9 / 5.0 648 Verified Reviews ♥ 4,755 Customer Favorites</p>		<p>Vehicle serviced</p> <ul style="list-style-type: none"> - Tire condition and pressure checked