

Multi-Point Inspection Checklist

RO# 6028295

Customer Name INVENTORY: 966251

Advisor Name AMANDA KEPHART

Technician Name JOEL PROENNEKE

Created on 5/14/2025 8:31 AM

Printed on 5/15/2025

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time May Require Future Attention Requires immediate attention

Maintenance Service


- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 ALL 5/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped AIR AND CABIN FILTERS DIRTY 
- Battery cables and mount
- Coolant level and test -50
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition

- Glass free of cracks, starts and large chips
- Dome , courtesy, map and sun visor lights and lighters and power ports
- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness **F7MM, R7MM**
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager  _____ Date 5-29-25

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone			R/O Open Date	R/O Number
Home Phone			5/14/25	6028295/1
Body			R/O Close Date	Receipt No.
TRUCK			5/29/25	Original
License Number			Mileage In	Mileage Out
			27538	27538
Year	Make	Model	Service Advisor	
2022	GMC	SIERRA 1500	JAKE BACHTELL	
Vehicle Identification Number		Color	Account No.	Delivery Date
3GTPUCEK9NG674763		GRAY		11/01/22
			In-Service Date	10/22/22

INVENTORY: **966251**

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Caused by CHANGED OIL AND FILTER Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS CHANGED OIL AND FILTER Work performed by Tech 428/8 0.40hrs @ 184.25 73.70 19432357 : N-OIL (08800-BOPCK) 6@8.10 48.60 12735608 : SL-N-FILTER (01836-BCKT) 1@8.00 8.00	I	
#2 - 4: 56 POINT INSPECTION Caused by PERFORMED 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION PERFORMED 56 POINT INSPECTION Work performed by Tech 428/8 1.00hrs @ 169.95 169.95	I	
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Caused by ROTATED AND BALANCED TIRES Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE ROTATED AND BALANCED TIRES Work performed by Tech 428/8 * 0.90hrs 59.95	I	
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Caused by PERFORMED ALIGNMENT Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . PERFORMED ALIGNMENT Work performed by Tech 428/8 * 1.50hrs 159.95 RESET CAMBER AND TOE	I	
#5 - RECALL: CHECK FOR OPEN RECALLS Caused by RECALL CHECK	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

MAY 29 2025 MS

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Year			Make		Model		Work Phone	R/O Open Date	R/O Number
2022			GMC		SIERRA 1500		Home Phone	5/14/25	6028295/2
Vehicle Identification Number					Color		Body	R/O Close Date	Receipt No.
3GTPUCEK9NG674763					GRAY		TRUCK	5/29/25	Original
							Mileage In	Mileage Out	
							27538	27538	
							License Number	Service Advisor	
								JAKE BACHTTELL	
							Account No.	Delivery Date	In-Service Date
								11/01/22	10/22/22

INVENTORY: 966251

#6 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Caused by REPLACED CABIN FILTER Corrected by ICF: REPLACED IN CABIN AIR FILTER REPLACED CABIN FILTER Work performed by Tech 428/8 * 0.10hrs 10.00 19338055 : SL-N-FILTER (09786-BOPCKT) 1@49.95 49.95	I	
#7 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Caused by REPLACED AIR FILTER Corrected by AF: REPLACED ENGINE AIR FILTER REPLACED AIR FILTER Work performed by Tech 428/8 * 0.10hrs 10.00 84121217 : SL-N-ELEMENT (03410-CT) 1@29.95 29.95	I	
#8 * RECALL: CHECK FOR OPEN RECALLS perform recall n242435631 Caused by RECALL Corrected by 9107414: CHECK FOR OPEN RECALLS RECALL Work performed by Tech 461/4 0.40hrs @ 160.00 64.00 performed recall as per bulletin# N242435631-05 Serial Data Gateway Module Reprogramming with SPS ONLY wcc# 0syz278180842 for sdgm program	W	
#9 * RECALL: CHECK FOR OPEN RECALLS perform recall n242450630 Caused by RECALL Corrected by 9107552: CHECK FOR OPEN RECALLS RECALL Work performed by Tech 461/4 0.30hrs @ 160.00 48.00 performed recall as per bulletin# N242450630 Engine Control Module Reprogramming with SPS wcc# 11yz278178903 for ecm program	W	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	483.55		112.00		
PARTS	136.50				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	45.97				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	666.02		112.00		



Vehicle History Report™

US \$44.99

2022 GMC SIERRA 1500 ELEVATION

VIN: 3GTPUCEK9NG674763
 CREW PICKUP
 2.7L I4
 GASOLINE
 REAR WHEEL DRIVE W/ 4X4
 Original Window Sticker

No accidents or damage reported to CARFAX

5 Service history records

CARFAX 1-Owner vehicle

Personal lease vehicle

Last owned in Iowa

27,555 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/29/25 at 5:24:07 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.

No Issues Reported

Structural Damage

No structural damage reported to CARFAX.

No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

Odometer Check

No indication of an odometer rollback.

No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.

No Issues Reported

Manufacturer Recall



No open recalls reported to CARFAX. Check for open recalls on GM vehicles at [recalls.gm.com](https://www.gm.com/recalls).

No Recalls Reported

Basic Warranty






Original warranty estimated to have 5 months or 8,445 miles remaining. Confirm with dealer or vehicle manufacturer.

Warranty Active



 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2022
Type of owner	Personal lease
Estimated length of ownership	2 yrs. 7 mo.
Owned in the following states/provinces	Iowa
Estimated miles driven per year	10,346/yr
Last reported odometer reading	27,555



 Detailed History			
 Owner 1 Purchased: 2022 	<div style="border: 1px solid blue; padding: 5px;"> Low mileage! This owner drove less than the industry average of 15,000 miles per year. </div>	Personal Lease Vehicle 10,346 mi/yr	
Date	Mileage	Source	Comments
Not Reported		General Motors	Original Window Sticker 
09/26/2022	2	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com	 Vehicle serviced - Pre-delivery inspection completed

★ **4.6 / 5.0**
 127 Verified Reviews
 ❤️ **103** Customer Favorites

10/01/2022	Iowa Motor Vehicle Dept. Danville, IA	Titled or registered as personal lease vehicle
10/07/2022	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 127 Verified Reviews ❤️ 103 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Oil and filter changed
11/10/2022 472	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 127 Verified Reviews ❤️ 103 Customer Favorites	 Vehicle serviced
11/28/2022	Iowa Motor Vehicle Dept. Danville, IA	Title or registration issued - First owner reported - Vehicle color noted as Black
01/31/2023	Iowa Motor Vehicle Dept. Danville, IA	Registration issued or renewed - Vehicle color noted as Black
01/10/2024	Iowa Motor Vehicle Dept. Danville, IA	Registration issued or renewed - Vehicle color noted as Black
09/19/2024	General Motors	Manufacturer Customer Satisfaction Program issued - Program #N242435631 SERIAL DATA GATEWAY MODULE - Status: Remedy Available Locate an authorized General Motors dealer to obtain more information about this campaign. ⊖ Learn more about this campaign

Description: Certain model years and vehicle makes noted in the table above may have a condition where the battery is at risk for a drain following an over-the-air update.

Remedy: Dealers are to reprogram the serial data gateway module.