

Multi-Point Inspection Checklist

RO# 6038531

Customer Name INVENTORY: 739751

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 4/6/2026 11:01 AM

Printed on 4/15/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?



Checked and OK at this time



May Require Future Attention



Requires immediate attention

Maintenance Service

-   Cold Engine start-up Pass
-   Engine operation warm-up Pass
-   Engine at normal operating temperature Pass
-   Brake and parking operation Pass
-   Active seat belt test Pass
-   Clutch and transmission operations Pass
-   Overdrive operation Pass
-   Transfer case operation (4-wheel drive only) Pass
-   Steering operation and off center Pass
-   Front end alignment Pass
-   Tilt steering wheel operation Pass
-   Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-   Speedometer and odometer operation Pass
-   Cruise Control operation, including resume Pass
-   Heater and air condition operation Pass
-   Abnormal noises and vibrations Pass
-   Squeaks and rattles Pass
-   Frame Check Pass
-   Body surface, lower body, and upper body damage requiring body shop repair Pass
-   Tire defects and damage, 5/32 6/32 all
-   Drive shaft, joints, CV's and boots Pass
-   Struts/shock absorbers, leaks and wear Pass
-   Exhaust system leaks and damage, including catalytic converter Pass
-   Fuel, oil, coolant, or other fluid leaks Pass
-   Perform emissions test and/or state inspection if required Pass
-   Under hood labels and decals Pass
-   Air filter and In-Cabin Air Filter equipped Pass
-   Battery cables and mount Pass
-   Coolant level and test Pass
-   Under hood fluid levels, including transmission and transfer case fluids Pass
-   Drive belts and hoses Pass
-   Air conditioning levels, check at sight glass Pass
-   Warning lights (including air bag) gauges & horn Pass
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-   Inside and outside rearview mirror operation, adjustment, and condition Pass
-   Glass free of cracks, starts and large chips Pass
- Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper Pass
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6/32 all
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Year	Make	Model
2024	GMC	SIERRA 1500
Vehicle Identification Number		Color
3GTUUED0RG114033		WHITE

Work Phone	R/O Open Date	R/O Number
	4/06/26	6038531/1
Home Phone	R/O Close Date	Receipt No.
	4/07/26	Original
Body	Mileage In	Mileage Out
TRUCK	46926	46926
License Number	Service Advisor	
	AMANDA KEPHART	
Account No.	Delivery Date	In-Service Date
	1/17/24	1/17/24

INVENTORY: 739751

<p>#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 256/ 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 8@9.60 76.80 12735811 : SL-N-FILTER (01836-BOPCKT) 1@6.95 6.95 new oil and filter</p>		I	
<p>#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95 inspection complete</p>		I	
<p>#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 256/ * 0.90hrs 99.00 balance and rotate complete</p>		I	
<p>#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 256/ * 1.50hrs 159.95 alingment complete</p>		I	
<p>#5 * NCORWR: NOTIFIED CUSTOMER OF OPEN RECALL ON VEHICLE. CUSTO MER WILL RESCHEDULE AT LATER TIME.</p>		C	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	502.60				
PARTS	83.75				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	616.34				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
159 Verified Reviews

♥ **101**
Customer Favorites



Report

US \$44.99

2024 GMC Sierra 1500 SLT

46,000 mi | VIN: 3GTUUED0RG114033 |
Crew Pickup | 5.3L V8 F OHV 16V | Gasoline | Rear wheel drive w/ 4X4



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

🛢️ Regular oil changes

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

🌍 Last owned in Illinois

📁 13 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/7/26 at 5:52:55 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	01/20/2026
🛞 Tires	✓ Tires rotated	01/20/2026



This car has been recently serviced. That's a good thing!

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

👤 Owner 1

Total Loss

No total loss reported to CARFAX.


✓ No Issues Reported

Structural Damage



No structural damage reported to CARFAX.

✓ No Issues Reported

Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

CARFAX Ownership History The number of owners is estimated	Owner 1
Year purchased	2024
Type of owner	Personal
Estimated length of ownership	2 yrs. 2 mo.
Owned in the following states/provinces	Illinois
Estimated miles driven per year	20,754/yr
Last reported odometer reading	46,000

CARFAX Detailed History			
Owner 1 Purchased: 2024			Personal Vehicle 20,754 mi/yr
Date	Mileage	Source	Comments
Not Reported		General Motors	Original Window Sticker 
01/17/2024		Illinois Motor Vehicle Dept.	Vehicle purchase reported - Titled or registered as personal vehicle
03/14/2024	8	Illinois Motor Vehicle Dept. Hamilton, IL Title #240746903580	Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported - Vehicle color noted as White
05/17/2024	7,877	Carson Motors Carthage, IL	 Vehicle serviced - Maintenance inspection completed

217-357-2925
 carsongm.com/
 ★ 4.8 / 5.0 40 Verified Reviews
 ❤️ 31 Customer Favorites

- Oil and filter changed
 - Tires rotated

08/08/2024

General Motors

Manufacturer Customer Satisfaction Program issued

- Program #N242435631 SERIAL DATA GATEWAY MODULE
 - Status: Remedy Available

Locate an authorized General Motors dealer to obtain more information about this campaign.

🔗 [Learn more about this campaign](#)

Description: Certain model years and vehicle makes noted in the table above may have a condition where the battery is at risk for a drain following an over-the-air update.

Remedy: Dealers are to reprogram the serial data gateway module.

08/19/2024

14,785

Carson Motors
 Carthage, IL
 217-357-2925
 carsongm.com/
 ★ 4.8 / 5.0 40 Verified Reviews
 ❤️ 31 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
 - Drive belts checked
 - Oil and filter changed
 - Tires rotated
 - Vehicle washed/detailed

02/28/2025

22,914

Carson Motors
 Carthage, IL
 217-357-2925
 carsonmotorsinc.com/newanduse
 dcars?clearall=1
 ★ 4.8 / 5.0 40 Verified Reviews
 ❤️ 31 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
 - Oil and filter changed
 - Tires rotated
 - Vehicle washed/detailed

02/28/2025

Illinois
 Motor Vehicle Dept.
 Hamilton, IL

Registration issued or renewed

05/19/2025

29,394

Carson Motors
 Carthage, IL
 217-357-2925
 carsonmotorsinc.com/newanduse
 dcars?clearall=1
 ★ 4.8 / 5.0 40 Verified Reviews
 ❤️ 31 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
 - Oil and filter changed
 - Tires rotated
 - Vehicle washed/detailed

08/14/2025

36,095

Carson Motors
 Carthage, IL
 217-357-2925
 carsonmotorsinc.com/newanduse
 dcars?clearall=1
 ★ 4.8 / 5.0 40 Verified Reviews
 ❤️ 31 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
 - Oil and filter changed
 - Tires rotated
 - Vehicle washed/detailed

01/20/2026

43,169

Carson Motors
 Carthage, IL
 217-357-2925
 carsonmotorsinc.com/newanduse
 dcars?clearall=1
 ★ 4.8 / 5.0 40 Verified Reviews
 ❤️ 31 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
 - Oil and filter changed
 - Tires rotated
 - Vehicle washed/detailed

02/19/2026

Illinois
 Motor Vehicle Dept.
 Hamilton, IL

Registration issued or renewed

04/05/2026

46,000

Deery Brothers
 West Burlington, IA
 319-752-6000

Vehicle offered for sale