

# Multi-Point Inspection Checklist

RO# 6038542

Customer Name INVENTORY: 684892

Advisor Name AMANDA KEPHART

Technician Name TYLER MCWILLIAMS

Created on 4/6/2026 2:11 PM

Printed on 4/6/2026


Did your Service Advisor review the results of this multi-point inspection checklist with you?

-  Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 10/32nds front and rear
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required
-   Under hood labels and decals
-    Air filter and In-Cabin Air Filter equipped Engine air filter 
-   Battery cables and mount
-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
-   Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
  
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 8mm fronts 9 mm rear
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER N/A
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
  
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

|   |                    |
|---|--------------------|
| Technician  | Date               |
| Service Manager  | Date <u>4-6-26</u> |
| Used Car Manager  | Date               |
| Customer  | Date               |

| REPAIR ORDER - AUDIT  |       |       | Work Phone     | R/O Open Date   | R/O Number      |
|---|-------|-------|----------------|-----------------|-----------------|
| DEERY BROTHERS<br>200 S Gear Ave<br>West Burlington, IA 52655 |       |       |                | 04/06/26        | 6038542/1       |
|   |       |       | Home Phone     | R/O Close Date  | Receipt No      |
|   |       |       |                | 04/09/26        | Original        |
|   |       |       | Body           | Mileage In      | Mileage Out     |
|   | SUV   | 91504 | 91507          |                 |                 |
| YEAR  | MAKE  | Model | License Number | Service Advisor |                 |
| 2021  | HONDA | PILOT |                | Jim Smith       | 131             |
| Vehicle Identification Number                                 |       | Color | Account No     | Delivery Date   | In-Service Date |
| 5FNYP6H79MB027601   |       | BLACK |                |                 |                 |

INVENTORY: 684892

|   |    |   |                        |               |
|---|----|---|------------------------|---------------|
| #1 - QL 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FI<br>ALL FLUID LEVELS<br>Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE<br>CHASSIS FILL ALL FLUID LEVELS<br>Work by Tech 649/4925 0.40hrs @ 184.25<br>19432337 : N-OIL (08800-BOPCK) 6@9.60<br>R85358MP : FILTER 1@6.95<br>Changed oil and filter and topped off fluids.   | LL | I | 73.70<br>57.60<br>6.95 | 27.78<br>3.98 |
| #2 - QL 4: 56 POINT INSPECTION<br>Corrected by 4: 56 POINT INSPECTION<br>Work by Tech 649/4925 1.00hrs @ 169.95<br>56 point inspection.   |    | I | 169.95                 |               |
| #3 - QL ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES<br>SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE.<br>DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTE<br>COMPONENTS AND OR PART REPLACEMENT .<br>Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE .<br>INCLUDES SETTING CASTER AND CAMBER AND TOE IF<br>ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF<br>DAMAGED OR RUSTED COMPONENTS AND OR PART<br>REPLACEMENT .<br>Work by Tech 649/4925* 1.50hrs<br>alignment complete | D  | I | 159.95                 |               |
| #4 - QL GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE<br>Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTAT<br>Work by Tech 649/4925* 0.90hrs<br>balance and rotate complete   | E  | I | 99.00                  |               |
| #5 - QL RECALL: CHECK FOR OPEN RECALLS  |    | I |                        |               |
| #6 * QL AF: REPLACED ENGINE AIR FILTER<br>Corrected by AF: REPLACED ENGINE AIR FILTER<br>Work by Tech 649/4925* 0.10hrs<br>PA99178 : AIR FILTER 1@29.95   |    | I | 12.00<br>29.95         | 12.13         |

|                       | INTERNAL | SERVICE CONT. | WARRANTY | CUSTOMER | COST |
|-----------------------|----------|---------------|----------|----------|------|
| LABOR                 |          |               |          |          |      |
| PARTS                 |          |               |          |          |      |
| DEDUCTIBLE            |          |               |          |          |      |
| SUBLET                |          |               |          |          |      |
| SHOP SUPPLIES         |          |               |          |          |      |
| HAZARDOUS MATERIALS   |          |               |          |          |      |
| SALES TAX OR TAX I.D. |          |               |          |          |      |
| SPECIAL ORDER DEPOSIT |          |               |          |          |      |
| DISCOUNTS             |          |               |          |          |      |
|                       |          |               |          |          |      |



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
159 Verified Reviews

♥ **101**  
Customer Favorites




## Report

US \$44.99

### 2021 Honda Pilot Black Edition

91,000 mi | VIN: 5FNYP6H79MB027601 |  
4 Door Wagon/Sport Utility | 3.5L V6 F SOHC 24V | Gasoline | All wheel drive

CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION



🔧 14 Service history records

👤 2 Previous owners

🏠 Types of owners: Personal lease, Personal

🌍 Last owned in Missouri

📁 31 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/9/26 at 5:39:16 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

01/12/2023  
Damage reported: minor damage



### CARFAX Reliability Forecast

Based on 2021 Honda Pilot Black Edition with similar mileage

#### 3-Year Reliability Forecast



#### What makes this vehicle have great reliability?

🏆 Top 25% compared to similar vehicles

Good news! This vehicle is expected to have low risk of repair and average repair costs.



\$\$\$ **Average Repair Cost**  
\$320 avg per year

✂ **Low Likelihood of Repair**

| <b>CARFAX</b> Additional History<br>Not all accidents / issues are reported to CARFAX                                | 👤 Owner 1             | 👤 Owner 2              |
|--|-----------------------|------------------------|
| <b>Total Loss</b><br>No total loss reported to CARFAX.   | ✔ No Issues Reported  | ✔ No Issues Reported   |
| <b>Structural Damage</b><br>CARFAX recommends that you have this vehicle inspected by a collision repair specialist. | ✔ No Issues Reported  | ✔ No Issues Reported   |
| <b>Airbag Deployment</b><br>No airbag deployment reported to CARFAX.   | ✔ No Issues Reported  | ✔ No Issues Reported   |
| <b>Odometer Check</b><br>No indication of an odometer rollback.  | ✔ No Issues Indicated | ✔ No Issues Indicated  |
| <b>Accident / Damage</b><br>Damage reported: 01/12/2023.   | Minor Damage          | No New Issues Reported |
| <b>Manufacturer Recall</b><br>No open recalls reported to CARFAX.  | ✔ No Recalls Reported | ✔ No Recalls Reported  |
| <b>Basic Warranty</b><br>Original warranty estimated to have expired.  | Warranty Expired      | Warranty Expired       |

| <b>CARFAX</b> Title History<br>CARFAX guarantees the information in this section | 👤 Owner 1               | 👤 Owner 2               |
|--|-------------------------|-------------------------|
| <b>Damage Brands</b><br>Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon   | ✔ Guaranteed No Problem | ✔ Guaranteed No Problem |
| <b>Odometer Brands</b><br>Not Actual Mileage   Exceeds Mechanical Limits         | ✔ Guaranteed No Problem | ✔ Guaranteed No Problem |



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.  
[View Terms](#) | [View Certificate](#)

| <b>CARFAX</b> Ownership History<br>The number of owners is estimated | 👤 Owner 1      | 👤 Owner 2    |
|--|----------------|--------------|
| Year purchased   | 2020           | 2023         |
| Type of owner  | Personal lease | Personal     |
| Estimated length of ownership  | 2 yrs. 5 mo.   | 2 yrs. 9 mo. |
| Owned in the following states/provinces                              | Ohio, Missouri | Missouri     |
| Estimated miles driven per year                                      | 11,186/yr      | 22,322/yr    |
| Last reported odometer reading                                       | 27,603         | 91,000       |

**CARFAX** Detailed History









👤 **Owner 1**  
Purchased: 2020



**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.

Personal Lease Vehicle  
11,186 mi/yr

| Date       | Mileage | Source  |   | Comments  |
|------------|---------|---|---|---|
| 10/19/2020 | 5       | Germain Honda of Dublin<br>Dublin, OH<br>614-764-9449<br>germainhondaofdublin.com<br>★ 4.5 / 5.0 2,951 Verified Reviews<br>❤️ 37,410 Customer Favorites |    | <b>Vehicle serviced</b><br>- Pre-delivery inspection completed<br>- Nitrogen fill tires   |
| 11/07/2020 | 7       | Ohio<br>Motor Vehicle Dept.<br>Powell, OH   |   | <b>Vehicle purchase reported</b><br>- Titled or registered as personal lease vehicle  |
| 11/09/2020 |         | Germain Honda of Dublin<br>Dublin, OH<br>614-764-9449<br>germainhondaofdublin.com<br>★ 4.5 / 5.0 2,951 Verified Reviews<br>❤️ 37,410 Customer Favorites |    | <b>Vehicle serviced</b>   |
| 11/18/2020 |         | Ohio<br>Motor Vehicle Dept.<br>Troy, OH<br>Title #2516193193  |   | <b>Title issued or updated</b><br>- First owner reported  |
| 11/23/2020 |         | Ohio<br>Motor Vehicle Dept.<br>Powell, OH<br>Title #2516193193  |   | <b>Registration issued or renewed</b><br>- Titled or registered as personal lease vehicle   |
| 07/27/2021 | 7,464   | Germain Honda of Dublin<br>Dublin, OH<br>614-764-9449<br>germainhondaofdublin.com<br>★ 4.5 / 5.0 2,951 Verified Reviews<br>❤️ 37,410 Customer Favorites |    | <b>Vehicle serviced</b><br>- Maintenance inspection completed<br>- Oil and filter changed<br>- Tires rotated  |
| 09/22/2021 |         | Ohio<br>Motor Vehicle Dept.<br>Troy, OH<br>Title #2516193193  |   | <b>Title or registration issued to manufacturer</b>   |
| 12/16/2021 |         | Ohio<br>Motor Vehicle Dept.<br>Troy, OH<br>Title #2516193193  |   | <b>Registration issued or renewed</b>   |
| 05/31/2022 | 14,661  | Germain Honda of Dublin<br>Dublin, OH<br>614-764-9449<br>germainhondaofdublin.com<br>★ 4.5 / 5.0 2,951 Verified Reviews<br>❤️ 37,410 Customer Favorites |  | <b>Vehicle serviced</b><br>- Maintenance inspection completed<br>- Brakes checked<br>- Differential fluid flushed/changed<br>- Drive belts checked<br>- Fuel system cleaned/serviced<br>- Oil and filter changed<br>- Rear differential fluid flushed/changed<br>- Rear differential serviced<br>- Steering/suspension checked<br>- Tires rotated |
| 10/28/2022 | 22,877  | Germain Honda of Dublin<br>Dublin, OH<br>614-764-9449<br>germainhondaofdublin.com<br>★ 4.5 / 5.0 2,951 Verified Reviews<br>❤️ 37,410 Customer Favorites |  | <b>Vehicle serviced</b><br>- Maintenance inspection completed<br>- Brake fluid flushed/changed<br>- Oil and filter changed<br>- Tires rotated   |
| 11/21/2022 |         | Ohio<br>Motor Vehicle Dept.<br>Troy, OH<br>Title #2516193193  |   | <b>Registration issued or renewed</b>   |

|            |   |  |
|------------|---|--|
| 01/12/2023 | Damage Report   | <p><b>Damage reported: minor damage</b></p> <div data-bbox="844 147 1242 304"> <p><b>Damage Severity Scale</b></p>  <p>Minor      Moderate      Severe</p> </div> <div data-bbox="1226 168 1339 325">  </div> <div data-bbox="730 336 836 451">  </div> <div data-bbox="868 346 1502 430"> <p>Minor damage is usually cosmetic, including dents or scratches to the vehicle body.</p> </div>   |
| 02/28/2023 | 25,391<br>Germain Honda of Dublin<br>Dublin, OH<br>614-764-9449<br>germainhondaofdublin.com<br>★ 4.5 / 5.0 2,951 Verified Reviews<br>❤️ 37,410 Customer Favorites |  <p><b>Vehicle serviced</b></p>   |
| 04/03/2023 | 27,207<br>Germain Honda of Dublin<br>Dublin, OH<br>614-764-9449<br>germainhondaofdublin.com<br>★ 4.5 / 5.0 2,951 Verified Reviews<br>❤️ 37,410 Customer Favorites |  <p><b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Maintenance inspection completed</li> <li>- Computer reprogrammed</li> <li>- Four wheel alignment performed</li> </ul>   |
| 04/26/2023 | 27,590<br>Missouri<br>Motor Vehicle Dept.   | <p><b>Vehicle purchase reported</b></p>  |
| 04/27/2023 | Columbia Honda<br>Columbia, MO<br>573-442-3107<br>columbiahonda.com/<br>★ 4.8 / 5.0 2,465 Verified Reviews<br>❤️ 15,804 Customer Favorites                        | <p><b>Vehicle offered for sale</b></p>   |
| 05/04/2023 | 27,591<br>Columbia Honda<br>Columbia, MO<br>573-442-3107<br>columbiahonda.com<br>★ 4.8 / 5.0 2,465 Verified Reviews<br>❤️ 15,804 Customer Favorites               |  <p><b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Pre-delivery inspection completed</li> <li>- Brakes checked</li> <li>- Brake fluid flushed/changed</li> <li>- Cabin air filter replaced/cleaned</li> <li>- Differential fluid flushed/changed</li> <li>- Emissions or safety inspection performed</li> <li>- Oil and filter changed</li> <li>- Rear differential serviced</li> <li>- Safety inspection performed</li> <li>- Transfer case fluid flushed/changed</li> </ul> <div data-bbox="730 1459 836 1575">  </div> <div data-bbox="876 1470 1502 1543"> <p>Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!</p> </div> |
| 05/05/2023 | Honda Certified Dealer<br>Columbia, MO<br>                                     | <p><b>Offered for sale as a Honda Certified Pre-Owned Vehicle</b></p> <ul style="list-style-type: none"> <li>- Crystal Black Pearl exterior</li> <li>- Black interior</li> </ul>   |
| 05/11/2023 | Missouri<br>Motor Vehicle Dept.<br>Columbia, MO<br>Title #ULD98420  | <p><b>Title issued or updated</b></p> <ul style="list-style-type: none"> <li>- Dealer took title of this vehicle while it was in inventory</li> </ul>  |
| 05/22/2023 | Missouri<br>Motor Vehicle Dept.   | <p><b>Vehicle purchase reported</b></p>  |
| 05/26/2023 | 27,603<br>Honda Certified Dealer<br>Columbia, MO  | <p><b>Sold as a Honda Certified Pre-Owned Vehicle</b></p>  |