

# Multi-Point Inspection Checklist

RO# 6037406

Customer Name INVENTORY: 969120

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 2/26/2026 3:04 PM

Printed on 3/3/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation fb 9mm rb 8mm
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 ft 6/32 rt 6/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In -Cabin Air Filter equipped Found the cabin and engine air filter to be dirty
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome , courtesy, map and sun visor lights and lighters and power ports

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	BUICK	ENCLAVE
Vehicle Identification Number		Color
5GAEVAKW5PJ182105		GRAY

AWD 4DR ESSEN	42367	42367
JAKE BACHTTELL		

INVENTORY: 969120

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.			I	
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 19419537 : N-OIL (08800-BOPCKT) 6@9.60 57.60 12735811 : SL-N-FILTER (01836-BOPCKT) 1@6.95 6.95 Changed the engine oil and filter.			I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs Performed a 4 wheel alignment.			I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs Balanced all four wheels and tires.			I	
#5 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 23321606 : SL-N-ELEMENT (03410-BCKT) 1@49.95 49.95			I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
 200 S Gear Ave  
 West Burlington, IA 52655


Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	BUICK	ENCLAVE
Vehicle Identification Number	Color	
5GAEVAKW5PJ182105	GRAY	

INVENTORY: 969120

Replaced the engine air filter.			
#6 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 19338054 : SL-N-FILTER (09786-BOPCKT) 1@29.95 Replaced the cabin air filter.		I	
#7 * BRACKET: INSTALL LICENSE PLATE BRACKET Corrected by BRACKET: INSTALL LICENSE PLATE BRACKET LRATE:.00 Work performed by Tech 329/9 * 0.20hrs 84430482 : N-BRACKET (07800-B) 1@45.91 Installed the front license plate bracket.		I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	549.10				
PARTS	190.36				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	769.45				



This report provided free of charge by:

**Deery Brothers**  
 200 S Gear Ave  
 West Burlington, IA 52655  
 319-271-8758

★ **4.6 / 5.0**  
 154 Verified Reviews

♥ **101**  
 Customer Favorites



## Vehicle History Report™

US \$44.99

### 2023 BUICK ENCLAVE ESSENCE

VIN: 5GAEVAKW5PJ182105  
 4 DOOR WAGON/SPORT UTILITY  
 3.6L V6 F DOHC 24V GASOLINE  
 ALL WHEEL DRIVE  
 Original Window Sticker  
 This CARFAX Report Provided by:

**Deery Brothers**

★ 4.6 / 5.0

154 Verified Reviews

♥ 101 Customer Favorites

✓ No accidents or damage reported to CARFAX

🛢️ Regular oil changes

👍 Good Reliability

1 CARFAX 1-Owner vehicle

🏠 Personal lease vehicle

📊 42,367 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/28/26 at 12:10:10 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	02/27/2026
🛞 Tires	✓ Tires rotated	10/08/2025

This car has been recently serviced. That's a good thing!



## Reliability Forecast

Based on 2023 Buick Enclave Essence with similar mileage

### 3-Year Reliability Forecast



Fair Reliability

**Good Reliability**

Great Reliability

Good news! This vehicle is expected to have average risk of repair and average repair costs.



### What makes this vehicle have good reliability?

**Top 50%** compared to similar vehicles

**Average Repair Cost**  
\$330 avg per year

**Oil Changes** performed regularly

**Average Likelihood of Repair**



## Additional History

Not all accidents / issues are reported to CARFAX

**Owner 1**

#### Total Loss

No total loss reported to CARFAX.

No Issues Reported

#### Structural Damage

No structural damage reported to CARFAX.

No Issues Reported

#### Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

#### Odometer Check

No indication of an odometer rollback.

No Issues Indicated

#### Accident / Damage

No accidents or damage reported to CARFAX.

No Issues Reported

#### Manufacturer Recall

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at [recalls.gm.com](https://recalls.gm.com).

No Recalls Reported

#### Basic Warranty

Original warranty estimated to have expired.

**Warranty Expired**



## Title History

CARFAX guarantees the information in this section

**Owner 1**

#### Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

**Guaranteed**  
No Problem

#### Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

**Guaranteed**  
No Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.  
View Terms | View Certificate

<b>CARFAX</b> Ownership History		Owner 1
The number of owners is estimated		
Year purchased		2023
Type of owner		Personal lease
Estimated length of ownership		3 years
Owned in the following states/provinces		Michigan
Estimated miles driven per year		13,757/yr
Last reported odometer reading		42,367

<b>CARFAX</b> Detailed History			
<b>Owner 1</b> Purchased: 2023		<b>Low mileage!</b> This owner drove less than the industry average of 15,000 miles per year.	Personal Lease Vehicle 13,757 mi/yr
Date	Mileage	Source	Comments
Not Reported		General Motors	<b>Original Window Sticker</b> 
12/07/2022		Clift Buick GMC Adrian, MI 517-265-6107 cliftauto.com ★ 4.7 / 5.0 110 Verified Reviews ❤️ 64 Customer Favorites	<b>Vehicle offered for sale</b>
12/29/2022	3	Clift Buick GMC Adrian, MI 517-265-6107 cliftauto.com ★ 4.7 / 5.0	<b>Vehicle serviced</b> - Pre-delivery inspection completed - Vehicle washed/detailed