

CUSTOMER TRADE-IN EVALUATION

Your participation will assist the future owner of the vehicle you traded in to become better acquainted with its background from the person who knows it best. This unique program was adapted as a means of further evidencing the quality of the vehicles we sell to our valued customers.

THIS CUSTOMER TRADE-IN EVALUATION PERTAINS TO THE FOLLOWING VEHICLE:

Make Nissan Model Murano Stock # 1128351

Year 2015 VIN 5N1AZ2MH4FN275593

Salesperson Ivan Swearingen

To the best of my knowledge the following items need to be repaired None

Any additional upgrades _____

Maintenance History Regular oil changes

Repairs were done where _____

Additional Comments went up 4 years

Would you allow prospective customers to contact you with further questions about your trade? _____

Customer Name Jim [Signature]

Thank you for your assistance in helping exceed our customer automotive expectations.

You are under no obligation to complete this form or include any information.

MULTI-POINT INSPECTION REPORT

Prevention saves time and money

Keep Vehicles Trouble-Free and Fun to Drive!



1128351

Customer:	
VIN: 5N1A2Z2MH4FN275593	License:
Model: MURAN	Color:
	Odometer: 75,312

MAINTENANCE SERVICE	Future Attention	Immediate Attention	SERVICE RECOMMENDED
	Checked & OK		

- 1 - Cold engine start-up
- 2 - Engine operation warm-up
- 3 - Engine at normal operating temperature
- 4 - Brake and parking brake operation
- 5 - Active seat belt test
- 6 - Clutch and transmission operation
- 7 - Overdrive operation
- 8 - Transfer case operation (4-wheel drive only)
- 9 - Steering operation and off center
- 10 - Front end alignment
- 11 - Tilt steering wheel operation
- 12 - Windshield wiper and washer operation at all speeds, wiper blade condition
- 13 - Speedometer and odometer operation
- 14 - Cruise control operation, including resume
- 15 - Heater and air conditioning operation
- 16 - Abnormal noises and vibrations
- 17 - Squeaks and rattles
- 18 - Frame Check
- 19 - Body surface, lower body, and under body damage requiring body shop repair
- 20 - Tire defects and damage, 5/32
- 21 - Drive shaft, joints, CV's and boots
- 22 - Struts/shock absorbers, leaks and wear
- 23 - Exhaust system leaks and damage, including catalytic convertor
- 24 - Fuel, oil, coolant, or other fluid leaks
- 25 - Perform emmissions test and/or state inspection if required
- 26 - Under hood lables and decals
- 27 - Air filter and In - Cabin Air Filter if equipped
- 28 - Battery cables and mount
- 29 - Coolant level and test
- 30 - Under hood fluid levels, including transmission and transfer case fluids
- 31 - Drive belts and hoses
- 32 - Air conditioning levels, check at sight glass
- 33 - Warning lights (including air bag) gauges & horn
- 34 - Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, backup lights, and license plate light
- 35 - Inside and outside rearview mirror operation, adjustment, and condition



NA

10/32 ALL TIRES

NA

SERVICE ADVISED

-40

Tech Name : 18425 KEVIN RANDALL

Date: 02/19/2019

Your Advisor Info:

Name : LEVI CAHILL

Phone :

e-Mail : lcahill@deerybrothers.com

Customer Signature

Next Service Due 80,312 - 06/21/2019

Handwritten signature and date: KH 2-26-19

MULTI-POINT INSPECTION REPORT

Prevention saves time and money

Keep Vehicles Trouble-Free and Fun to Drive!



Customer:

VIN: 5N1AZ2MH4FN275593

License:

Model: MURAN

Color:

Odometer: 75,312

MAINTENANCE SERVICE


Future Attention

Checked & OK

Immediate Attention

SERVICE RECOMMENDED

- 36 - Glass free of cracks, stars, and large chips
- 37 - Dome, courtesy, map and sun visor lights and lighters and power ports
- 38 - Window operation
- 39 - Sunroof or convertible top operation
- 40 - Audio system and clock (set if required)
- 41 - Factory-installed alarm system functional
- 42 - Cigarette lighter operation, replace element if used
- 43 - Headliner, sun visors, dash pad, upholstery, console, cup holders, trim panels, carpets
- 44 - Truck bed, bed liner, tailgate, rear bumper
- 45 - Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
- 46 - Seats and seat belt operation for every position
- 47 - Rear defogger, check with test lights
- 48 - Headlight aim
- 49 - Trunk light and trunk trim appearance
- 50 - Hood, trunk, and fuel filler door latches
- 51 - Spare tire pressure, jack and tire wrench match vehicle and work properly
- 52 - Wheel covers and caps
- 53 - Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes, inspect rotors/drums for minimum thickness
- 54 - Differential oil level
- 55 - Engine oil and filter changed using genuine replacement parts
- 56 - CHECK AND COMPLETE ALL OPEN RECALLS
- 57 - OTHER
- 58 - Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- 59 - With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- 60 - Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- 61 - Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- 62 - Customer Acknowledgement:
X _____



ROCK CHIP

NA

FRONT 7MM REAR 4MM



Tech Name : 18425 KEVIN RANDALL

Date: 02/19/2019

Your Advisor Info:

Name : LEVI CAHILL

Phone :

e-Mail : lcahill@deerybrothers.com

Customer Signature

Next Service Due

80,312 - 06/21/2019



SA No: 18187

TagNo: T593

DATE:

RO #: 680191

MULTI-POINT INSPECTION REPORT

Prevention saves time and money


Keep Vehicles Trouble-Free and Fun to Drive!



Customer:		License:	
VIN: 5 N 1 A Z 2 M H 4 F N 2 7 5 5 9 3			
Model: MURAN	Color:	Odometer: 75,312	

RECOMMENDED SERVICES RESULTS

ESTIMATE	D	A
----------	---	---

28 - Battery cables and mount <i>Comment:</i> SERVICE ADVISED	<input type="checkbox"/> Future Attention 
Subtotal	
36 - Glass free of cracks, stars, and large chips <i>Comment:</i> ROCK CHIP	<input type="checkbox"/> Future Attention
Subtotal	
53 - Pull four wheels and check brakes for minimum 50% remaining wear on <i>Comment:</i> FRONT 7MM REAR 4MM	<input type="checkbox"/> Future Attention
Subtotal	

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Not responsible of damage from freezing due to lack of antifreeze. The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to

Tech Name : **KEVIN RANDALL**Date: **02/19/2019**

Your Advisor Info:

Name : LEVI CAHILL

Phone :

e-Mail : lcahill@deerybrothers.com

Customer Signature

Next Service Due
 80,312 - 06/21/2019


Customer Number:
Unit Number:

Invoice No: **680191**

ACCOUNTING

Deery Brothers

200 S. GEAR · P.O. BOX 1 · W. BURLINGTON, IOWA 52655
319-752-6000 · 888-752-6000
SERVICE HOTLINE: (319) 752-6600
FAX: (319) 752-1100
www.deerybrothers.com

DEERY BROTHERS, INC.

200 S GEAR AVE.
W. BURLINGTON IA 52655

Page 1 of 2

Home: Bus: Cell:

Email:

SERVICE ADVISOR: **18187 LEVI CAHILL**

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
WHT	15	NISSAN MURANO	5N1AZ2MH4FN275593		75312 / 75312	T593
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
			17:00 19FEB19		110.88	CASH
R.O. OPENED	READY	OPTIONS: STK:1128351				
13:12 19FEB19	10:02 21FEB19					

LINE	OPCODE	TECH	TYPE	A/HRS	S/HRS	COST	SALE	COMP	LIST	NET	TOTAL
A	56		POINT INSPECTION								
	4	56	POINT INSPECTION								
			18425 IUT	0.80	1.00	1340	10300			103.00	103.00
			VERSION 1 (EMP# 18425,19FEB19 14:34): 75312 TEST DRIVE AND INSPECTION COMPLETED								
B			CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS								
	1		CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS								
			18425 IUT	0.33	0.40	553	4120			41.20	41.20
			1 W W-SOL			457	803	0	8.03	8.03	8.03
			1 BC BRAKE-CLN			441	876	0	8.76	8.76	8.76
			1 K885 BG BAT/SK			495	887	0	8.87	8.87	8.87
			5 88865701 OIL			1425	3100	0	6.20	6.20	31.00
			1 15208-65F0E OIL FILTER			512	587	0	5.87	5.87	5.87
			VERSION 1 (EMP# 18425,19FEB19 15:03): 75312 OIL CHANGE COMPLETED								
C			INSTALL DEERY BROTHERS PRE-OWNED PROTECTION PACKAGE. PROVIDES \$2000.00 DOLLARS OF COVERAGE ON FOUR MAJOR VEHICLE COMPONENTS. TRANSMISSION, FUEL SYSTEM, COOLING SYSTEM, POWER STEERING SYSTEM. AND UP TO \$6000.00 DOLLARS ON THE ENGINE								
			DBPOP INSTALL DEERY BROTHERS PRE-OWNED PROTECTION PACKAGE. PROVIDES \$2000.00 DOLLARS OF COVERAGE ON FOUR MAJOR VEHICLE COMPONENTS. TRANSMISSION, FUEL SYSTEM, COOLING SYSTEM, POWER STEERING SYSTEM. AND UP TO \$6000.00 DOLLARS ON THE ENGINE								
			18425 IUT	0.00	0.00	0	0			0.00	0.00
			1 K6915 GAS USED CAR KIT			8300	11600	0	116.00	116.00	116.00
			VERSION 1 (EMP# 18425,19FEB19 15:06): 75312 DEERY CAR INSTALLED								
D**			REPLACE REAR BRAKE LINING AND RESURFACE DRUMS OR ROTORS .								
			GM24P REPLACE REAR BRAKE LINING AND RESURFACE DRUMS OR ROTORS .								
			18425 IUT	0.32	1.80	536	8200			82.00	82.00
			1 DD06M-8H38PNW PAD KIT-DISC BR			3900	6800	0	68.00	68.00	68.00

R.O.#: 680191

VIN.#: 5N1AZ2MH4FN275593

WE HONOR OUR COMPETITORS COUPONS	WE HAVE COLLISION REPAIR	EXPRESS LUBE SERVICE
PARTS & SERVICE HOURS MON. - FRI. 7:00 AM - 6:00 PM SAT. 7:00 AM - 5:00 PM	DISCOUNT RENTALS AVAILABLE	

STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	DESCRIPTION	TOTALS
	LABOR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES	
	TOTAL CHARGES	
	LESS	
	SALES TAX	
	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT

Customer Number:
Unit Number:

Invoice No: **680191**
ACCOUNTING



200 S. GEAR · P.O. BOX 1 · W. BURLINGTON, IOWA 52655
319-752-6000 · 888-752-6000
SERVICE HOTLINE: (319) 752-6600
FAX: (319) 752-1100
www.deerybrothers.com

DEERY BROTHERS, INC.
200 S GEAR AVE.
W. BURLINGTON IA 52655

Home: Bus: Cell: Email:

Cell:

COLLISION CENTER: (319) 758-6900

SERVICE ADVISOR: **18187 LEVI CAHILL**

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
WHT	15	NISSAN MURANO	5N1AZ2MH4FN275593		75312 / 75312	T593
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
			17:00 19FEB19		110.88 CASH	21FEB19
R.O. OPENED	READY	OPTIONS: STK:1128351				
13:12 19FEB19	10:02 21FEB19					

LINE	OPCODE	TECH	TYPE	A/HRS	S/HRS	COST	SALE	COMP	LIST	NET	TOTAL
1	K860G	STOP	SQUEAL			925	1295	0	12.95	12.95	12.95
VERSION 1 (EMP# 18425,19FEB19 15:54): 75312 TURNED ROTORS AND REPLACED BRAKE PADS											
EPA COMPLIANCE AND SHOP SUPPLIES						0	3642				36.42

FOR QUICK, CONVENIENT SERVICE, RESERVATIONS FOR YOUR NEXT SCHEDULED MAINTENANCE IS NOT NEEDED BUT RECOMMENDED. CALL 319-752-6600 FOR YOUR NEXT SERVICE RESERVATION. WE WELCOME ALL WALK-IN CUSTOMERS.

WE WANT OUR CUSTOMERS 100% SATISFIED!

R.O.#: 680191

VIN.#: 5N1AZ2MH4FN275593

DATE	START	FINISH	DURATION	TYPE	TECH	LINE(S)	CHG
02-19-19	13:46	14:34	0.80	W	18425	A	
	14:43	15:03	0.33	W	18425	B	
	15:03	15:06	0.05	W	18425	D	
	15:06	15:06	0.00	W	18425	C	
	15:38	15:54	0.27	W	18425	D	

ACCOUNT	SALE	COST	CONTROL	ACCOUNT	SALE	COST	CONTROL
46301	22620	2429		48100	25948	16455	
66900	3642	0		24100	52210	*****	

COST, SALE, & COMP TOTALS 18884 52210 0

WE HONOR OUR COMPETITORS COUPONS	WE HAVE COLLISION REPAIR	EXPRESS LUBE SERVICE
---	---------------------------------	-----------------------------

PARTS & SERVICE HOURS MON. - FRI. 7:00 AM - 6:00 PM SAT. 7:00 AM - 5:00 PM	DISCOUNT RENTALS AVAILABLE
---	-----------------------------------

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	\$ 0.00
PARTS AMOUNT	\$ 0.00
GAS, OIL, LUBE	\$ 0.00
SUBLET AMOUNT	\$ 0.00
MISC. CHARGES	\$ 0.00
TOTAL CHARGES	\$ 0.00
LESS	\$ 0.00
SALES TAX	\$ 0.00
PLEASE PAY THIS AMOUNT	\$ 0.00



Your AutoCheck Vehicle History Report

Report run: 03/07/2019 20:04:55 EST



2015 Nissan Murano Platinum / S /
SL / SV
SUV 4D (3.5L V6 DI)

VIN: 5N1AZ2MH4FN275593
Class: CUV - Mid Range
Country of Assembly: United States
Vehicle Age: 4 year(s)

This vehicle is eligible for Buyback Protection



Due to the vehicle's history showing no reported major state title brands. Click here for terms and conditions and to register your vehicle.

YOUR VEHICLE AT A GLANCE

This vehicle's AutoCheck Score: 91

Other comparable 2015 vehicles in the CUV - Mid Range typically score between 87-92.

The AutoCheck Score is based on a vehicle's history such as vehicle class and age, number of owners, accident and damage history, title brands, odometer readings etc. This score is used to compare vehicle's favorability against the entire market of vehicles with the same scoring system.

- ✓ No State Title Brand Reported
- ✓ No Accident Reported
No Air Bag Deployed
- ✓ No Other Damage Reported
- i Other Title Brand or Specific Event Reported
- ✓ No Odometer Problem(s) Reported
- ✓ No Open Recall(s) Reported

ONE OWNER
Calculated Owners: 1

Owner history



Current Owner

Purchased: 2015
Where: IL
Owned from: 11/02/2015 - Present

Vehicle usage



Vehicle Use: There is indication of the below usage(s) for this vehicle

Personal | Fleet | Rental | Lease | Taxi | Livery | Police |
Government | Drivers Ed | Commercial

Major state title brand check



Your Vehicle Checks Out: No major state title brand has been reported by the state Division of Motor Vehicles (DMV). Your vehicle is qualified for the AutoCheck Buyback Protection Program. Terms and conditions. Register here.



0 Problem(s) Reported

-
-
-
-
-
-
-
-

Major State Title Areas Checked

- No fire brand
- No hail, flood brand
- No junk or scrapped brand
- No manufacturer buyback
- No lemon brand
- No salvage brand
- No rebuilt or rebuildable brand
- No odometer brand (EML or NAM)

Accident check



Your Vehicle Checks Out: AutoCheck has not received any accident records from government sources and



independent agencies on this vehicle. Not all accidents are reported to AutoCheck.

Damage check



Your Vehicle Checks Out: AutoCheck has not received a damage-related event from an auction or an independent source. Not all damage events are reported to AutoCheck. It is recommended to have pre-owned vehicles inspected by a third party prior to purchase.



0 Problem(s) Reported

Other Problem Areas Checked



No non-title fire damaged record



No non-title hail or flood damaged record



No auction junk or scrapped record



No auction rebuilt or rebuildable record



No salvage auction record



No damaged or major damage incident record



No frame or structural damage record



No recycling facility record



No crash test record

Other title brand and specific event check



Information Reported: One or more non-major state title brand(s) and/or additional significant event(s) has been reported to AutoCheck. It is recommended to have pre-owned vehicles inspected by a third party prior to purchase.

2 Event(s) Reported

Vehicle Events Checked



No Insurance Loss record



No Titled to an insurance company record



No Auction Lemon/Manufacturer Buyback record



No abandoned title record



No grey market title record



Loan/Lien record(s)



No repossessed record



Corrected title record



No duplicate title record

2 Event(s) Reported



Vehicle Events Checked

No theft record(s)

Odometer check



Your Vehicle Checks Out: No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

- State title odometer check
- Auction odometer check
- Odometer calculation check

0 Problem(s) Reported



Mileage

125

Date Reported

11/03/2015

Open recall check



Your Vehicle Checks Out: AutoCheck found no open recalls reported by the vehicle manufacturer. Not all open recalls are reported to AutoCheck.

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order. Any discrepancies will be in bold text.

Report Run Date: 03/07/2019 20:04:55 EST

Vehicle: 2015 Nissan Murano Platinum / S / SL / SV (5N1AZ2MH4FN275593)

Event Date	Location	Odometer Reading	Data Source	Details
10/09/2015	IL		Independent Source	VEHICLE MANUFACTURED AND SHIPPED TO DEALER
11/02/2015	QUINCY, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
11/03/2015	QUINCY, IL	125	Motor Vehicle Dept.	TITLE(Title #:153076904920) (Lien Reported)
02/25/2016	QUINCY, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
05/26/2016	QUINCY, IL		Motor Vehicle Dept.	TITLE(Title #:161476982270) (Lien Reported) DUPLICATE/CORRECTED TITLE
02/07/2017	QUINCY, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
02/06/2018	QUINCY, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
02/19/2019	QUINCY, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL

This Vehicle's Glossary

Below are the specific definitions for events that appear in this vehicle's report. More information is available in the full AutoCheck glossary.

Term	Section Location	Definition
Loan/Lien	Other Title Brand and Specific Event Check	A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.
Corrected Title	Other Title Brand and Specific Event Check	The State DMV has issued a corrected title for the vehicle.
Personal Use	Vehicle Use	This vehicle was driven for personal use.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to AutoCheck Terms and Conditions. If you obtained the report from a dealer, the dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 955 American Lane Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (5N1AZ2MH4FN275593) qualifies for AutoCheck Buyback Protection. If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 955 American Lane Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.