

Multi-Point Inspection Checklist

RO# 6040010

Customer Name INVENTORY: 969710

Advisor Name Jim Smith

Technician Name KADEN SCHMITZ

Created on 5/19/2026 3:49 PM

Printed on 5/20/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service


-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only) N/A
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 8/32 all
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required
-   Under hood labels and decals
-   Air filter and In-Cabin Air Filter equipped Fail, Cabin and Air
-   Battery cables and mount
-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
-   Dome, courtesy, map and sun visor lights and lighters and power ports


- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 7mm
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager  _____ Date 5.20.26

Used Car Manager  _____ Date 5/20/26

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

LEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2025	NISSAN	ROGUE
Vehicle Identification Number	Color	
5N1BT3BB8SC816144	GRAY	

AWD SV	40306	40308
Jim Smith		

INVENTORY: 969710

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 847/8 0.40hrs @ 195.57 78.23 19432337 : N-OIL (08800-BOPCK) 5@9.60 48.00 1520865F1E : OIL FILTER 1@6.95 6.95 PERFORMED SERVICE	I
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 847/8 1.00hrs @ 178.95 178.95 PERFORMED SERVICE	I
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 847/8 * 0.90hrs 99.00 PERFORMED SERVICE	I
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 847/8 * 1.50hrs 159.95 PERFORMED ALIGNMENT	I
#5 - RECALL: CHECK FOR OPEN RECALLS	I
#6 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage in	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2025	NISSAN	ROGUE
Vehicle Identification Number		Color
5N1BT3BB8SC816144		GRAY

5/19/26	6040010/2
5/21/26	Original
AWD SV	40306
40308	
Jim Smith	

INVENTORY: 969710

Work performed by Tech 847/8 * 0.10hrs 12.00
 CAF15027C : CABIN FILTER 1@29.95 29.95
 REPLACED FILTER

#7 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER I
 REPLACEMENT
 Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00
 Work performed by Tech 847/8 * 0.10hrs 12.00
 165466RA0A : AIR CLEANER ELEMENT 1@49.95 49.95
 REPLACED FILTER

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	540.13				
PARTS	134.85				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	704.97				

This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**
171 Verified Reviews

❤️ **1,443**
Customer Favorites



Report

US \$44.99

2025 Nissan Rogue SV

40,306 mi | VIN: 5N1BT3BB8SC816144 |

4 Door Wagon/Sport Utility | 1.5L I3 F DOHC 12V | Gasoline | All wheel drive



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

CARFAX VALUE \$22,940

🔧 2 Service History Records

1 CARFAX 1-Owner Vehicle

🚗 Rental Vehicle

🌍 Last Owned in Illinois

📄 7 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/23/26 at 9:13:57 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	05/21/2026
🛞 Tires	✓ Tires rotated	05/21/2026



This car has been recently serviced. That's a good thing!

CARFAX History-Based Value Report


\$22,940
CARFAX Retail Value

History events affecting this vehicle's value

- ↑ ✓ No Accidents Reported
- ↑ 1 1-Owner Vehicle

-  Service History
-  Non-Personal Vehicle

CARFAX Additional History Not all accidents / issues are reported to CARFAX	👤 Owner 1
Total Loss No total loss reported to CARFAX.	✔ No Issues Reported
Structural Damage No structural damage reported to CARFAX.	✔ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✔ No Issues Reported
Odometer Check No indication of an odometer rollback.	✔ No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	✔ No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	✔ No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	👤 Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	✔ Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	✔ Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

CARFAX Ownership History The number of owners is estimated	👤 Owner 1
Year purchased	2025
Type of owner	Rental
Estimated length of ownership	1 yr. 3 mo.
Owned in the following states/provinces	Illinois
Estimated miles driven per year	31,570/yr
Last reported odometer reading	40,306

CARFAX Detailed History			
👤 Owner 1 Purchased: 2025		Rental Vehicle 31,570 mi/yr	
Date	Mileage	Source	Comments