

# Multi-Point Inspection Checklist

RO# 6026911

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Customer Name INVENTORY: 500240  
Advisor Name Jim Smith  
Technician Name Matthew Rosenboom  
Created on 3/31/2025 4:33 PM  
Printed on 4/1/2025

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service


-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations front right wheel bearing is making noise
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 fronts-6/32 rears-4/32
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required
-   Under hood labels and decals
-   Air filter and In-Cabin Air Filter equipped
-   Battery cables and mount
-   Coolant level and test -50
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition

- Glass free of cracks, starts and large chips
- Dome , courtesy, map and sun visor lights and lighters and power ports
- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used N/A
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets  
**center console leather is torn**
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position  
**driver's outside door handle lock is missing cover**
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance **liftgate trim is damaged**
- Hood, trunk, and fuel filler door latch **liftgate has a hole in it**
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness **fronts-6mm rears-5mm**
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician

Date

Service Manager



Date

3-31-25

Used Car Manager

Date

Customer

Date

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
FWD PLATINUM	103293	103293
License Number	Service Advisor	
	Jim Smith	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2018	NISSAN	PATHFINDER
Vehicle Identification Number		Color
5N1DR2MNXJC660485		RED

INVENTORY: 500240

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work performed by Tech 404/0                      0.40hrs @ 184.25                      73.70 19432337 : N-OIL (08800-BOPCK)                      6@8.10                      48.60 1520865FOE : OIL FILTER                      1@6.90                      6.90 performed oil change	I
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work performed by Tech 404/0                      1.00hrs @ 169.95                      169.95 962109PFOA : BRACKET-LICENCE PLATE                      1@63.35                      63.35 performed inspection	I
#3 - DIAG: DIAGNOSED AND PRICED REPAIR TO CUSTOMER CHECK REAR GATE Caused by found connector or latch had been shot Corrected by DIAG: DIAGNOSED AND PRICED REPAIR TO CUSTOMER found connector or latch had been shot Work performed by Tech 404/0 *                      1.00hrs                      160.00 Corrected by 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS found connector or latch had been shot Work performed by Tech 404/0                      1.00hrs @ 169.95                      169.95 240713KA2A : HARNESS-BACK DOOR                      1@385.73                      385.73 240513KA1C : HARNESS-BACK DOOR                      1@263.07                      263.07 replaced connectors and now rear hatch works	I
#4 - DIAG: DIAGNOSED AND PRICED REPAIR TO CUSTOMER CHECK FRONT PASSENGER WHEEL BEARING Caused by found right front wheel bearing was bad Corrected by 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS found right front wheel bearing was bad Work performed by Tech 404/0                      1.00hrs @ 169.95                      169.95 G30301 : HUB ASSEMBLY                      1@217.59                      217.59 replaced wheel bearing	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
 200 S Gear Ave  
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
FWD PLATINUM	103293	103293
License Number	Service Advisor	
	Jim Smith	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2018	NISSAN	PATHFINDER
Vehicle Identification Number		Color
5N1DR2MNXJC660485		RED

INVENTORY: 500240

#6 - RECALL: CHECK FOR OPEN RECALLS

#7 \* 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS UPON INSPECTION FOUND DRIVER'S SIDE OUTER DOOR HANDLE COVER MISSING

Corrected by 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS


Work performed by Tech 404/0	0.10hrs @ 201.00	20.10
806453TA1A : ESCUTCHEON-OUTSIDE HANDLE, FRO	1@19.09	19.09
REPLACED LOCK COVER		

I  
I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	763.65				
PARTS	1004.33				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1797.97				

Anya

#500240




# Experian AutoCheck Report

Report run: 03/31/2025 11:25:15 EDT

## 2018 Nissan Pathfinder Platinum / S / SL / SV SUV 4D (3.5L V6 SMPT Gasoline)

VIN:	5N1DR2MNXJC660485
Class:	CUV - Large
Country of Assembly:	United States
Vehicle Age:	7 year(s)
Estimated In Service:	05/03/2018
Last Reported Odometer:	103,293 (03/21/2025)

Owners - 2



Vehicle Usage  
Lease



## AutoCheck Score

Similar vehicles usually range between 85 and 91

### Vehicle History at a Glance



State Title Brand



CLEAN



Auction Brand / Issues



NO ISSUE



Accident / Damage

No Accidents or Damage Reported



NO ISSUE



Open Recall Check



NO OPEN RECALLS



Insurance Loss / Transfer



NO ISSUE



Odometer Check

Last reported odometer:  
103,293 (03/21/2025)



NO ISSUE



Certified Pre-Owned



NO CPO INFO AVAILABLE



Service / Repair

18 Service Record(s) Reported



NO ISSUE



Additional History

Lien Reported



EVENTS REPORTED

06/06/2018 FL Independent Repair Center Multiple Point Vehicle Inspection Tires or Wheels Service Performed

2018

Owner 1

Location: FL Owned From: 06/2018 Usage: Lease

Event Date	Location	Odometer	Data Source	Details
06/23/2018	SEMINOLE, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
06/23/2018	FL	15	Dealer Record	Vehicle in Dealer Inventory
07/18/2018	FL	15	Independent Repair Center	Vehicle Serviced
09/26/2019	SEMINOLE, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
06/30/2020	SEMINOLE, FL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
06/06/2021	SAINT PETERSBURG, FL	31,755	Service Record	Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Wipers Replaced And/Or Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed

2021

Owner 2

Location: FL Owned From: 07/2021 Usage: Personal

Event Date	Location	Odometer	Data Source	Details
07/28/2021	SAINT PETERSBURG, FL	31,812	Motor Vehicle Dept.	Title(Lien Reported)
07/28/2021	SAINT PETERSBURG, FL		Motor Vehicle Dept.	Registration Event/Renewal
10/08/2021	SAINT PETERSBURG, FL	35,846	Service Record	Multiple Point Vehicle Inspection Engine Serviced Recommended Maintenance Performed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
10/18/2021	SAINT PETERSBURG, FL		Motor Vehicle Dept.	Registration Event/Renewal
10/18/2021	SAINT PETERSBURG, FL	36,372	Service Record	Multiple Point Vehicle Inspection Tires or Wheels Service Performed
11/20/2021	SAINT PETERSBURG, FL	39,475	Service Record	Battery Serviced or Replaced Multiple Point Vehicle Inspection
12/04/2021	SAINT PETERSBURG, FL	40,149	Service Record	Multiple Point Vehicle Inspection Engine Serviced Recommended Maintenance Performed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
01/27/2022	SAINT PETERSBURG, FL	44,295	Service Record	Multiple Point Vehicle Inspection Engine Serviced Recommended Maintenance Performed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
02/24/2022	SAINT PETERSBURG, FL	45,318	Service Record	Multiple Point Vehicle Inspection Brakes Serviced Tires or Wheels Service Performed

**Patent Notice**

\* \* \* \* \* Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.