

# Multi-Point Inspection Checklist

RO# 6038621

Customer Name INVENTORY: 1290331

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 4/8/2026 2:29 PM

Printed on 4/9/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

-    Cold Engine start-up Pass
-    Engine operation warm-up Pass
-    Engine at normal operating temperature Pass
-    Brake and parking operation Pass
-    Active seat belt test Pass
-    Clutch and transmission operations Pass
-    Overdrive operation Pass
-    Transfer case operation (4-wheel drive only) Pass
-    Steering operation and off center Pass
-    Front end alignment Pass
-    Tilt steering wheel operation Pass
-    Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-    Speedometer and odometer operation Pass
-    Cruise Control operation, including resume Pass
-    Heater and air condition operation Pass
-    Abnormal noises and vibrations Pass
-    Squeaks and rattles Pass
-    Frame Check Pass
-    Body surface, lower body, and upper body damage requiring body shop repair Pass
-    Tire defects and damage, 5/32 6/32 all
-    Drive shaft, joints, CV's and boots Pass
-    Struts/shock absorbers, leaks and wear Pass
-    Exhaust system leaks and damage, including catalytic converter Pass
-    Fuel, oil, coolant, or other fluid leaks Pass
-    Perform emissions test and/or state inspection if required Pass
-    Under hood labels and decals Pass
-    Air filter and In-Cabin Air Filter equipped Pass
-    Battery cables and mount Pass
-    Coolant level and test Pass
-    Under hood fluid levels, including transmission and transfer case fluids Pass
-    Drive belts and hoses Pass
-    Air conditioning levels, check at sight glass Pass
-    Warning lights (including air bag) gauges & horn Pass
-    Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-    Inside and outside rearview mirror operation, adjustment, and condition Pass
-    Glass free of cracks, starts and large chips Pass
-    Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 7mm all
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician

Date

Service Manager



Date

4-8-26

Used Car Manager

Date

Customer



Date



5N1DR3CC4PC221667


Odometer:58561

### Nissan : Pathfinder : 2023 : All Wheel Drive : except Rock Creek ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.





This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
159 Verified Reviews

♥ **101**  
Customer Favorites




### Report

US \$44.99

## 2023 Nissan Pathfinder SL

58,271 mi | VIN: 5N1DR3CC4PC221667 |  
4 Door Wagon/Sport Utility | 3.5L V6 | Gasoline | Front wheel drive w/ 4X4



- Regular oil changes
- CARFAX 1-Owner vehicle
- Personal vehicle
- Last owned in Iowa
- 19 Detailed records available



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/9/26 at 5:26:31 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

#### Event 1

03/18/2025  
**Damage reported: minor damage**  
- Damage to undercarriage



### CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	04/02/2026

Tires

✓ Tires rotated

04/02/2026




This car has been recently serviced. That's a good thing!



### Reliability Forecast

Based on 2023 Nissan Pathfinder SL with similar mileage

#### 3-Year Reliability Forecast



Good news! This vehicle is expected to have low risk of repair and average repair costs.



#### What makes this vehicle have great reliability?

- Top 50%** compared to similar vehicles
- Average Repair Cost**  
\$290 avg per year
- Oil Changes** performed regularly
- Low Likelihood of Repair**



### Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

#### Total Loss

No total loss reported to CARFAX.

✓ No Issues Reported

#### Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

✓ No Issues Reported

#### Airbag Deployment

No airbag deployment reported to CARFAX.

✓ No Issues Reported

#### Odometer Check

No indication of an odometer rollback.

✓ No Issues Indicated

#### Accident / Damage

Damage reported: 03/18/2025.

Minor Damage

#### Manufacturer Recall

No open recalls reported to CARFAX.

✓ No Recalls Reported

#### Basic Warranty

Original warranty estimated to have expired.

Warranty Expired



### Title History

CARFAX guarantees the information in this section

Owner 1

#### Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

✓ **Guaranteed**  
No Problem

#### Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

✓ **Guaranteed**  
No Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.  
[View Terms](#) | [View Certificate](#)



### Ownership History

The number of owners is estimated

Owner 1

Year purchased

2023

Personal

Type of owner	
Estimated length of ownership	3 years
Owned in the following states/provinces	Iowa
Estimated miles driven per year	19,388/yr
Last reported odometer reading	58,271



**CARFAX Detailed History**

**Owner 1**  
Purchased: 2023 Personal Vehicle  
19,388 mi/yr

Date	Mileage	Source	Comments
Not Reported		Nissan North America, Inc.	<b>Original Window Sticker</b> 
11/15/2022	4	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 159 Verified Reviews ❤️ 101 Customer Favorites	<b>Vehicle serviced</b> - Pre-delivery inspection completed - Oil and filter changed
04/01/2023		Iowa Motor Vehicle Dept. Montrose, IA	<b>Titled or registered as personal vehicle</b>
04/17/2023	266	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 159 Verified Reviews ❤️ 101 Customer Favorites	<b>Vehicle serviced</b>
05/09/2023		Iowa Motor Vehicle Dept. Montrose, IA Title #56AC41190N	<b>Title or registration issued</b> - First owner reported - Vehicle color noted as Silver
07/03/2023		Iowa Motor Vehicle Dept. Montrose, IA Title #56AC41190N	<b>Registration issued or renewed</b> - Vehicle color noted as Silver
07/29/2023	5,812	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 159 Verified Reviews ❤️ 101 Customer Favorites	<b>Vehicle serviced</b> - Recommended maintenance performed
09/29/2023	13,206	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 159 Verified Reviews ❤️ 101 Customer Favorites	<b>Vehicle serviced</b> - Recommended maintenance performed
02/23/2024		Service Facility	<b>Vehicle reconditioned</b>