

Multi-Point Inspection Checklist

RO# 6039431

Customer Name INVENTORY: 1290190A

Advisor Name AMANDA KEPHART

Technician Name JACOB BLAKEMAN








Created on 5/2/2026 10:11 AM


















































Printed on 5/20/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-    Cold Engine start-up
-    Engine operation warm-up
-    Engine at normal operating temperature
-    Brake and parking operation fb 7mm rb 6mm
-    Active seat belt test

-    Clutch and transmission operations
-    Overdrive operation
-    Transfer case operation (4-wheel drive only)
-    Steering operation and off center
-    Front end alignment
-    Tilt steering wheel operation
-    Windshield wiper and washer operation at all speeds, wiper blade condition
-    Speedometer and odometer operation
-    Cruise Control operation, including resume
-    Heater and air condition operation
-    Abnormal noises and vibrations
-    Squeaks and rattles
-    Frame Check
-    Body surface, lower body, and upper body damage requiring body shop repair
-    Tire defects and damage, 5/32 ft 7/32 rt 6/32
-    Drive shaft, joints, CV's and boots
-    Struts/shock absorbers, leaks and wear
-    Exhaust system leaks and damage, including catalytic converter
-    Fuel, oil, coolant, or other fluid leaks
Found the engine oil to be leaking form the valve cover causing a burning oil smell
-    Perform emmissions test and/or state inspection if required
-    Under hood labels and decals
-    Air filter and In -Cabin Air Filter equipped Found the cabin air filter to be dirty.
-    Battery cables and mount
-    Coolant level and test
-    Under hood fluid levels, including transmission and transfer case fluids
-    Drive belts and hoses
-    Air conditioning levels, check at sight glass
-    Warning lights (including air bag) gauges & horn
-    Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-    Inside and outside rearview mirror operation, adjustment, and condition
-    Glass free of cracks, starts and large chips

- Dome , courtesy, map and sun visor lights and lighters and power ports
- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SUV	97341	97341
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2020	HYUNDAI	SANTA FE
Vehicle Identification Number		Color
5NMS5CAA5LH144134		BLUE

INVENTORY: 1290190A

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 329/9 0.40hrs @ 195.57 78.23 19419537 : N-OIL (08800-BOPCKT) 5@9.60 48.00 25161877 : SL-N-FILTER (01836-BOPCKT) 1@14.40 14.40	I				
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 329/9 1.00hrs @ 178.95 178.95	I				
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 99.00	I				
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95	I				
#5 - RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:184.59 Work performed by Tech 329/9 0.00hrs @	I				
#6 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 12.00	I				
	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST

LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SUV	97341	97341
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2020	HYUNDAI	SANTA FE
Vehicle Identification Number		Color
5NMS5CAA5LH144134		BLUE

INVENTORY: 1290190A

CAF1867P : CABIN FILTER	1@49.95	49.95	

#7 * BLADE: REPLACED WIPER BLADES *WIPER BLADE REPLACEMENT FRONT	-		I
Corrected by BLADE: REPLACED WIPER BLADES LRATE:.00			
Work performed by Tech 329/9 * 0.10hrs		10.00	
H326 : REAR BLADE	1@22.95	22.95	
19388165 : SL-N-BLADE (10146-BOPCKT)	1@22.95	22.95	
19388173 : SL-N-BLADE (10146-BOPCKT)	1@22.95	22.95	

#8 * 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS REPLACE VALVE COVER			I
Corrected by DIAG: DIAGNOSED AND PRICED REPAIR TO CUSTOMER LRATE:.00 LRATE:201.55			
Work performed by Tech 329/9 * 1.00hrs		160.00	
Corrected by 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS LRATE:.00 LRATE:201.55			
Work performed by Tech 329/9 2.00hrs @ 201.55		403.10	
VS50892 : VLV CVR GASKET	1@69.31	69.31	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	1101.23				
PARTS	250.51				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1351.74				

This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**
165 Verified Reviews

♥ **1,102**

Customer Favorites

CARFAX Report

US \$44.99

2020 Hyundai Santa FE Limited 2.0T

97,341 mi | VIN: 5NMS5CAA5LH144134 |
4 Door Wagon/Sport Utility | 2.0L I4 F DOHC 16V | Gasoline | All wheel drive

CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION




DAMAGE Minor Damage



Minor Moderate Severe

GOOD VALUE



Fair Good Great

GREAT RELIABILITY



Fair Good Great

9 Service History Records

2 Previous Owners

Types of Owners: Personal Lease, Personal

Last Owned in Nebraska

27 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/12/26 at 6:19:34 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

04/17/2023

Damage reported: minor damage

Damage Severity Scale





Minor Moderate Severe

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	05/08/2026


 Tires	✓ Tires rotated	05/08/2026
 Brakes	✓ Brake fluid flushed/changed	12/03/2025
This car has been recently serviced. That's a good thing!		

CARFAX History-Based Value Report

\$19,420





CARFAX Value

GOOD VALUE



Fair Value Good Value Great Value


What makes this vehicle a good value?

-  Service History
-  Personal Vehicle
-  Prior Certified Pre-Owned
-  Minor Damage

CARFAX Reliability Forecast


Based on 2020 Hyundai Santa FE Limited 2.0T with similar mileage

3-Year Reliability Forecast






Fair Reliability Good Reliability Great Reliability

Good news! This vehicle is expected to have low risk of repair and average repair costs.



What makes this vehicle have great reliability?

-  **Top 25%** compared to similar vehicles
-  **Average Repair Cost**
\$290 avg per year
-  **Low Likelihood of Repair**

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

	👤 Owner 1	👤 Owner 2
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✓ No Issues Reported	✓ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported
Odometer Check No indication of an odometer rollback.	✓ No Issues Indicated	✓ No Issues Indicated
Accident / Damage Damage reported: 04/17/2023.	✓ No Issues Reported	Minor Damage
Manufacturer Recall No open recalls reported to CARFAX.	✓ No Recalls Reported	✓ No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired