

Multi-Point Inspection Checklist

RO# 6039292

Customer Name INVENTORY: 739591

Advisor Name JAKE BACHTTELL

Technician Name JACOB BLAKEMAN

Created on 4/29/2026 8:11 AM

Printed on 5/13/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

- | | | | | | |
|--|---|---|---|---|--|
|  |  |  |  |  | Cold Engine start-up |
|  |  |  |  |  | Engine operation warm-up |
|  |  |  |  |  | Engine at normal operating temperature |
|  |  |  |  |  | Brake and parking operation fb 8mm rb 3mm |
|  |  |  |  |  | Active seat belt test |
|  |  |  |  |  | Clutch and transmission operations |
|  |  |  |  |  | Overdrive operation |
|  |  |  |  |  | Transfer case operation (4-wheel drive only) |
|  |  |  |  |  | Steering operation and off center |
|  |  |  |  |  | Front end alignment |
|  |  |  |  |  | Tilt steering wheel operation |
|  |  |  |  |  | Windshield wiper and washer operation at all speeds, wiper blade condition |
|  |  |  |  |  | Speedometer and odometer operation |
|  |  |  |  |  | Cruise Control operation, including resume |
|  |  |  |  |  | Heater and air condition operation |
|  |  |  |  |  | Abnormal noises and vibrations |
|  |  |  |  |  | Squeaks and rattles |
|  |  |  |  |  | Frame Check |
|  |  |  |  |  | Body surface, lower body, and upper body damage requiring body shop repair |
|  |  |  |  |  | Tire defects and damage, 5/32
<u>ft 3/32 rt 5/32 also found the front tires to be cupped and causing a vibration in the steering wheel</u> |
|  |  |  |  |  | Drive shaft, joints, CV's and boots |
|  |  |  |  |  | Struts/shock absorbers, leaks and wear |
|  |  |  |  |  | Exhaust system leaks and damage, including catalytic converter |
|  |  |  |  |  | Fuel, oil, coolant, or other fluid leaks <u>Found the engine oil filter housing to be leaking</u> |
|  |  |  |  |  | Perform emissions test and/or state inspection if required |
|  |  |  |  |  | Under hood labels and decals |
|  |  |  |  |  | Air filter and In-Cabin Air Filter equipped <u>Found the cabin and engine air filter to be dirty</u> |
|  |  |  |  |  | Battery cables and mount |
|  |  |  |  |  | Coolant level and test |
|  |  |  |  |  | Under hood fluid levels, including transmission and transfer case fluids |
|  |  |  |  |  | Drive belts and hoses |
|  |  |  |  |  | Air conditioning levels, check at sight glass |
|  |  |  |  |  | Warning lights (including air bag) gauges & horn |
|  |  |  |  |  | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
|  |  |  |  |  | Inside and outside rearview mirror operation, adjustment, and condition |
|  |  |  |  |  | Glass free of cracks, starts and large chips |

- Dome , courtesy, map and sun visor lights and lighters and power ports
- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone			R/O Open Date	R/O Number
Home Phone			4/29/26	6039292/1
Body			R/O Close Date	Receipt No.
TRUCK			5/05/26	Original
License Number			Mileage In	Mileage Out
			93836	93836
Year	Make	Model	Service Advisor	
2023	TOYOTA	TUNDRA	JAKE BACHTELL	
Vehicle Identification Number		Color	Account No.	In-Service Date
5TFJA5DB8PX124318		LUNAR ROCK	9/14/23	9/14/23

INVENTORY: 739591

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 329/9 1.00hrs @ 178.95 Performed a 56 point inspection.		I	178.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 329/9 0.40hrs @ 195.57 78.23 19432337 : N-OIL (08800-BOPCK) 8@9.60 76.80 90915-YZZN3 : FILTER, OIL 1@9.53 9.53 Changed the engine oil and filter.		I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.		I	
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 12.00 87139-0C010 : ELEMENT, AIR REFINER 1@49.95 49.95 Replaced the cabin air filter.		I	
#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 12.00		I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
TRUCK	93836	93836

Year	Make	Model	License Number	Service Advisor
2023	TOYOTA	TUNDRA		JAKE BACHTTELL
Vehicle Identification Number		Color	Account No.	Delivery Date
5TFJA5DB8PX124318		LUNAR ROCK		9/14/23
				In-Service Date
				9/14/23

INVENTORY: 739591

17801-YZZ17 : ELEMENT SUB-ASSY, AI Replaced the engine air filter.	2@29.95	59.90		

#7 * 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD Corrected by 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD LRATE:.00 Work performed by Tech 329/9 * 1.20hrs 100.00 19534199 : N-TIRE (05880-BOPCKT) 4@266.82 1067.28 Mounted and balanced 4 new tires.			I	

#8 * BRAKER: REPLACE REAR BRAKE PADS AND RESURFACE ROTORS Corrected by BRAKER: REPLACE REAR BRAKE PADS AND RESURFACE ROTORS LRATE:.00 Work performed by Tech 329/9 * 1.80hrs 215.00 PSP2439M : REAR PADS 1@78.00 78.00 BR9019301-01 : REAR ROTORS 2@95.64 191.28 Replaced the rear brake pads and rotors.			I	

Total Fee Amounts	34.00			

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	756.13				
PARTS	1532.74				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	2352.86				

This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**
 164 Verified Reviews

♥ **521**

Customer Favorites

CARFAX Report

US \$44.99

2023 Toyota Tundra Limited

93,836 mi | VIN: 5TFJA5DB8PX124318 |
 Crew Pickup | 3.4L V6 F DOHC 24V | Gasoline | Rear wheel drive w/ 4X4



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

CARFAX VALUE \$39,760

✂ 11 Service History Records

📄 At Least 1 Open Recall

1 CARFAX 1-Owner Vehicle

🚚 Commercial Vehicle

🌍 Last Owned in Iowa

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/6/26 at 1:45:19 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months









Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	05/05/2026
🛞 Tires	✓ Four tires replaced	05/05/2026
🛞 Brakes	✓ Rear brake pads replaced ✓ Rear brake rotor(s) replaced	05/05/2026







This car has been recently serviced. That's a good thing!





CARFAX History-Based Value Report



\$39,760
 CARFAX Retail Value


History events affecting this vehicle's value








-   No Accidents Reported
-   1-Owner Vehicle
-   Service History
-   Open Recall

CARFAX Additional History Not all accidents / issues are reported to CARFAX		 Owner 1
Total Loss No total loss reported to CARFAX.		No Issues Reported
Structural Damage No structural damage reported to CARFAX.		No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.		No Issues Reported
Odometer Check No indication of an odometer rollback.		No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.		No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Toyota dealer near you to schedule an appointment. View Toyota disclosure		Recall Reported
Basic Warranty Original warranty estimated to have expired.		Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section		 Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon		Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits		Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate		

CARFAX Ownership History The number of owners is estimated		 Owner 1
Year purchased		2023
Type of owner		Commercial
Estimated length of ownership		2 yrs. 5 mo.
Owned in the following states/provinces		Iowa
Estimated miles driven per year		37,390/yr
Last reported odometer reading		93,836

CARFAX Detailed History	
 Owner 1 Purchased: 2023	Commercial Vehicle 37,390 mi/yr

Date	Mileage	Source		Comments
07/31/2023		Toyota Motor Sales, USA, Inc.		Vehicle manufactured and shipped to original dealer Original Window Sticker 
11/01/2023		Iowa Motor Vehicle Dept. Burlington, IA		Titled or registered as commercial vehicle
11/09/2023	5,459	Woodrums Ford Toyota Macomb, IL 309-833-2113 woodrumtoyota.com ★ 4.8 / 5.0 403 Verified Reviews ❤️ 2,595 Customer Favorites		Vehicle serviced - Maintenance inspection completed
12/06/2023		Iowa Motor Vehicle Dept. Burlington, IA Title #29AC68522		Title issued or updated - Title or registration issued - First owner reported - Vehicle color noted as Green
12/29/2023	10,052	Woodrums Ford Toyota Macomb, IL 309-833-2113 woodrumtoyota.com ★ 4.8 / 5.0 403 Verified Reviews ❤️ 2,595 Customer Favorites		Vehicle serviced - Maintenance inspection completed
01/02/2024	10,272	Iowa Motor Vehicle Dept. Burlington, IA Title #29AC69269		Registration issued or renewed - Title or registration issued - Vehicle color noted as Green
01/18/2024	11,873	Woodrums Ford Toyota Macomb, IL 309-833-2113 woodrumtoyota.com ★ 4.8 / 5.0 403 Verified Reviews ❤️ 2,595 Customer Favorites		Vehicle serviced
03/03/2024	16,181	Walmart Auto Care Center Macomb, IL 309-836-2544 https://www.walmart.com ★ 4.4 / 5.0 78 Verified Reviews ❤️ 1 Customer Favorite		Vehicle serviced - Tire(s) replaced
04/12/2024	20,157	Woodrums Ford Toyota Macomb, IL 309-833-2113 woodrumtoyota.com ★ 4.8 / 5.0 403 Verified Reviews ❤️ 2,595 Customer Favorites		Vehicle serviced - Maintenance inspection completed
08/30/2024		Iowa Motor Vehicle Dept. Burlington, IA Title #29AC69269		Registration issued or renewed - Correction to record - Vehicle color noted as Green
12/28/2024	50,564	Walmart Auto Care Center Macomb, IL 309-836-2544 https://www.walmart.com ★ 4.4 / 5.0 78 Verified Reviews		Vehicle serviced - Tire(s) replaced