

Multi-Point Inspection Checklist

RO# 6037913

Customer Name INVENTORY: 968591

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 3/14/2026 7:32 AM

Printed on 3/24/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation fb 8mm rb 7mm
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
Found the front and rear wiper blades to be torn and streaking
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 Ft 4/32 rt 4/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped Found the cabin and engine air filter to be dirty.
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips

- Dome , courtesy, map and sun visor lights and lighters and power ports
- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655			Work Phone	R/O Open Date	R/O Number
			Home Phone	R/O Close Date	Receipt No.
			Body	Mileage In	Mileage Out
			SUV	95809	95809
Year	Make	Model	License Number	Service Advisor	
2020	KIA	TELLURIDE		JAKE BACHTTELL	
Vehicle Identification Number		Color	Account No.	Delivery Date	In-Service Date
5XYP6DHC3LG042454		CHARCOAL			

INVENTORY: 968591

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 169.95 19419537 : N-OIL (08800-BOPCKT) 7@9.60 67.20 S11934 : OIL FILTER 1@6.95 6.95 Performed a 56 point inspection.			I	
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 Changed the engine oil and filter.			I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.			I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 99.00 Balanced all four wheels and tires.			I	
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 12.00 S9C79-AC100 : KIA CABIN FILTER 1@49.95 49.95			I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone

R/O Open Date

R/O Number

3/14/26

6037913/2

Home Phone

R/O Close Date

Receipt No.

3/18/26

Original

Body

Mileage In

Mileage Out

SUV

95809

95809

Year

Make

Model

License Number

Service Advisor

2020

KIA

TELLURIDE

JAKE BACHTTELL

Vehicle Identification Number

Color

Account No.

Delivery Date

In-Service Date

5XYP6DHC3LG042454

CHARCOAL

INVENTORY: 968591

#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER
REPLACEMENT

Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00

Work performed by Tech 329/9 * 0.10hrs 12.00

28113-A9100 : KIA ENGINE AIR FILTER\ 1@29.95 29.95

Replaced the engine air filter.

I

#7 * BLADE: REPLACED WIPER BLADES *WIPER BLADE REPLACEMENT
FRONT

Corrected by BLADE: REPLACED WIPER BLADES LRATE:.00

Work performed by Tech 329/9 * 0.10hrs 10.00

19388166 : SL-N-BLADE (10146-BOPCKT) 1@22.95 22.95

19388173 : SL-N-BLADE (10146-BOPCKT) 1@22.95 22.95

Replaced the front wiper blades.

I

#8 * BLADE: REPLACED WIPER BLADES replace rear blade

Corrected by BLADE: REPLACED WIPER BLADES LRATE:.00

Work performed by Tech 329/9 * 0.10hrs 10.00

H326 : REAR BLADE 1@22.95 22.95

I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	546.60				
PARTS	222.90				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	799.49				



This report provided free of charge by:
Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

★ **4.6 / 5.0**
 155 Verified Reviews

♥ **101**
 Customer Favorites



Report

US \$44.99

2020 Kia Telluride S

95,809 mi | VIN: 5XYP6DHC3LG042454 |
 4 Door Wagon/Sport Utility | 3.8L V6 F DOHC 24V | Gasoline | All wheel drive



🔧 10 Service history records

📄 At least 1 open recall

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

🌍 Last owned in Iowa



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/19/26 at 6:19:31 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1


04/17/2024
Damage reported: minor damage




CARFAX Recent Service Highlights

Key services performed in the last 12 months


Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	03/18/2026

 **Tires** ✓ **Tires rotated** 03/18/2026




This car has been recently serviced. That's a good thing!


CARFAX Additional History <small>Not all accidents / issues are reported to CARFAX</small>	👤 Owner 1
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✓ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✓ No Issues Reported
Odometer Check No indication of an odometer rollback.	✓ No Issues Indicated
Accident / Damage Damage reported: 04/17/2024.	Minor Damage
Manufacturer Recall At least 1 open recall reported.	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired


CARFAX Title History <small>CARFAX guarantees the information in this section</small>	👤 Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	✓ Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	✓ Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

CARFAX Ownership History <small>The number of owners is estimated</small>	👤 Owner 1
Year purchased	2019
Type of owner	Personal
Estimated length of ownership	6 yrs. 6 mo.
Owned in the following states/provinces	Iowa
Estimated miles driven per year	14,638/yr
Last reported odometer reading	95,809



CARFAX **Detailed History**

 **Owner 1**
Purchased: 2019



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
14,638 mi/yr