

# Multi-Point Inspection Checklist

RO# 6033541

Customer Name INVENTORY: 968000

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 10/22/2025 2:33 PM

Printed on 10/23/2025

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation fb 9mm rb 8mm
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 ft 4/32 rt 4/32
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required
-   Under hood labels and decals
-   Air filter and In-Cabin Air Filter equipped Found the cabin air filter to be dirty 
-   Battery cables and mount
-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
-   Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager  \_\_\_\_\_ Date 10.22.25

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
PLATINUM AWD	36199	36199
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2025	TOYO	CROWN PLATINU
Vehicle Identification Number		Color
JTDAFAAF4S3012018		OXYGEN WHI

INVENTORY: 968000

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.	I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 00279-BLK16-01 : GTMO 0W16 BK SP WTY 6@8.10 48.60 90915-YZZN1 : FILTER, OIL 1@8.66 8.66 Changed the engine oil and filter.	I	73.70 48.60 8.66
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs Performed a 4 wheel alignment.	I	159.95
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs Balanced all four wheels and tires.	I	59.95
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 87139-YZZ93 : ELEMENT, AIR REFINER 1@49.95 49.95	I	10.00 49.95

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	473.55				
PARTS	107.21				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	610.75				

Display CARFAX in online listings:



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
144 Verified Reviews

♥ **102**  
Customer Favorites




## Vehicle History Report™

US \$44.99

### 2025 TOYOTA CROWN PLATINUM

VIN: JTDAFAAF4S3012018  
SEDAN 4 DR  
2.4L I4 F DOHC 16V  
HYBRID  
ALL WHEEL DRIVE

This CARFAX Report Provided by:  
**Deery Brothers**  
★ **4.6 / 5.0**  
144 Verified Reviews  
♥ **102** Customer Favorites

**Damage reported: minor damage**  
  
MINOR      MODERATE      SEVERE

 **11** Service history records

 At least 1 open recall

 **1** CARFAX 1-Owner vehicle

 **36,199** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/25/25 at 8:30:14 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

01/14/2025

**Damage reported: minor damage**



**Recent Service Highlights**

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	09/04/2025
Tires	✓ Tires rotated	09/04/2025

This car has been recently serviced. That's a good thing!



**Additional History**

Not all accidents / issues are reported to CARFAX

**Owner 1**

**Total Loss**

No total loss reported to CARFAX.

✓ No Issues Reported

**Structural Damage**

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

✓ No Issues Reported

**Airbag Deployment**

No airbag deployment reported to CARFAX.

✓ No Issues Reported

**Odometer Check**

No indication of an odometer rollback.

✓ No Issues Indicated

**Accident / Damage**

Damage reported: 01/14/2025.

Minor Damage

**Manufacturer Recall**

At least 1 open recall reported. View Toyota disclosure

Recall Reported

**Basic Warranty**


Original warranty estimated to have expired.

Warranty Expired

 <b>Title History</b> CARFAX guarantees the information in this section		<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon		<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits		<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>		

 <b>Ownership History</b> The number of owners is estimated		<b>Owner 1</b>
Year purchased		2024
Type of owner		Rental
Estimated length of ownership		11 months
Owned in the following states/provinces		Iowa
Estimated miles driven per year		34,141/yr
Last reported odometer reading		36,199

 <b>Detailed History</b>			
 <b>Owner 1</b> Purchased: 2024	Rental Vehicle 34,141 mi/yr		
Date	Mileage	Source	Comments
09/12/2024		NICB	<b>Vehicle manufactured and shipped to original dealer</b>
10/31/2024	1	Iowa Motor Vehicle Dept. West Burlington, IA Title #29AC80543	<b>Registration issued or renewed</b> - Title or registration issued - First owner reported - Titled or registered as rental vehicle - Vehicle color noted as White
01/14/2025		Damage Report	 <b>Damage reported: minor damage</b>



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

<p>05/15/2025    19,568</p>	<p>Roberts Tire Center Corporation Burlington, IA 319-753-6586 robertstirecenter.com/ ★ <b>4.9 / 5.0</b> 98 Verified Reviews ❤️ <b>63</b> Customer Favorites</p>	<p> <b>Vehicle serviced</b> - Tire(s) balanced - Tire(s) mounted</p>
<p>05/20/2025    20,671</p>	<p>Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ <b>4.6 / 5.0</b> 144 Verified Reviews ❤️ <b>102</b> Customer Favorites</p>	<p> <b>Vehicle serviced</b></p>
<p>05/30/2025</p>	<p>Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ <b>4.6 / 5.0</b> 144 Verified Reviews ❤️ <b>102</b> Customer Favorites</p>	<p> <b>Vehicle serviced</b> - Maintenance inspection completed - 5,000 mile service performed - Air filter replaced - Cabin air filter replaced/cleaned - Oil and filter changed - Tires rotated</p>
<p>06/25/2025    22,450</p>	<p>Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ <b>4.6 / 5.0</b> 144 Verified Reviews ❤️ <b>102</b> Customer Favorites</p>	<p> <b>Vehicle serviced</b></p>
<p>07/17/2025    25,028</p>	<p>Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ <b>4.6 / 5.0</b> 144 Verified Reviews</p>	<p> <b>Vehicle serviced</b></p>