

**MULTI-POINT INSPECTION REPORT**

Prevention saves time and money

Keep Vehicles Trouble-Free and Fun to Drive!



Customer: \_\_\_\_\_

VIN: **KNMAT2MV0HP550802** License: \_\_\_\_\_

Model: **ROGUE** Color: \_\_\_\_\_ Odometer: **29,161**

**MAINTENANCE SERVICE** Future Attention Immediate Attention **SERVICE RECOMMENDED**

Checked & OK

1 - Cold engine start-up	✓			
2 - Engine operation warm-up	✓			
3 - Engine at normal operating temperature	✓			
4 - Brake and parking brake operation	✓			
5 - Active seat belt test	✓			
6 - Clutch and transmission operation	✓			
7 - Overdrive operation	✓			
8 - Transfer case operation (4-wheel drive only)	✓			NA
9 - Steering operation and off center	✓			
10 - Front end alignment	✓			
11 - Tilt steering wheel operation	✓			
12 - Windshield wiper and washer operation at all speeds, wiper blade condition	✓			
13 - Speedometer and odometer operation	✓			
14 - Cruise control operation, including resume	✓			
15 - Heater and air conditioning operation	✓			
16 - Abnormal noises and vibrations	✓			
17 - Squeaks and rattles	✓			
18 - Frame Check	✓			
19 - Body surface, lower body, and under body damage requiring body shop repair	✓			
20 - Tire defects and damage, 5/32	✓			7/32 REAR 6/32 FRONT
21 - Drive shaft, joints, CV's and boots	✓			
22 - Struts/shock absorbers, leaks and wear	✓			
23 - Exhaust system leaks and damage, including catalytic convertor	✓			
24 - Fuel, oil, coolant, or other fluid leaks	✓			
25 - Perform emissions test and/or state inspection if required	✓			NA
26 - Under hood lables and decals	✓			
27 - Air filter and In - Cabin Air Filter if equipped	✓			
28 - Battery cables and mount	✓			
29 - Coolant level and test	✓			-50
30 - Under hood fluid levels, including transmission and transfer case fluids	✓			
31 - Drive belts and hoses	✓			
32 - Air conditioning levels, check at sight glass	✓			
33 - Warning lights (including air bag) gauges & horn	✓			
34 - Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, backup lights, and license plate light	✓			
35 - Inside and outside rearview mirror opeartion, adjustment, and condition	✓			

**Tech Name :** 18425 KEVIN RANDALL **Date:** 07/12/2019

**Customer Signature** Next Service Due  
34,161 - 12/10/2019

**Your Advisor Info:**  
**Name :** LEVI CAHILL  
**Phone :**  
**e-Mail :** lcahill@deerybrothers.com

MULTI-POINT INSPECTION REPORT

Prevention saves time and money

Keep Vehicles Trouble-Free and Fun to Drive!



Customer:

VIN: KNMAT2MV0HP550802

License:

Model: ROGUE

Color:

Odometer: 29,161

MAINTENANCE SERVICE

Future Attention

Checked & OK

Immediate Attention

SERVICE RECOMMENDED

- 36 - Glass free of cracks, stars, and large chips
- 37 - Dome, courtesy, map and sun visor lights and lighters and power ports
- 38 - Window operation
- 39 - Sunroof or convertible top operation
- 40 - Audio system and clock (set if required)
- 41 - Factory-installed alarm system functional
- 42 - Cigarette lighter operation, replace element if used
- 43 - Headliner, sun visors, dash pad, upholstery, consle, cup holders, trim panels, carpets
- 44 - Truck bed, bed liner, tailgate, rear bumper
- 45 - Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
- 46 - Seats and seat belt operation for every position
- 47 - Rear defogger, check with test lights
- 48 - Headlight aim
- 49 - Trunk light and trunk trim appearance
- 50 - Hood, trunk, and fuel filler door latches
- 51 - Spare tire pressure, jack and tire wrench match vehicle and work properly
- 52 - Wheel covers and caps
- 53 - Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes, inspect rotors/drums for minimum thickness
- 54 - Differential oil level
- 55 - Engine oil and filter changed using genuine replacement parts
- 56 - CHECK AND COMPLETE ALL OPEN RECALLS
- 57 - OTHER
- 58 - Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- 59 - With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- 60 - Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- 61 - Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- 62 - Customer Acknowledgement:



NA

NA

7MM

X

Tech Name : 18425 KEVIN RANDALL

Date: 07/12/2019

Your Advisor Info:

Name : LEVI CAHILL

Phone :

e-Mail : lcahill@deerybrothers.com

Customer Signature

Next Service Due

34,161 - 12/10/2019

Customer Number:  
Unit Number: **1124490**

Invoice No: **688062**  
ACCOUNTING



200 S. GEAR · P.O. BOX 1 · W. BURLINGTON, IOWA 52655  
319-752-6000 · 888-752-6000  
SERVICE HOTLINE: (319) 752-6600  
FAX: (319) 752-1100  
www.deerybrothers.com

**DEERY BROTHERS, INC.**  
200 S GEAR AVE.  
W. BURLINGTON IA 52655  
Home: Bus: Cell:  
Email:

COLLISION CENTER: (319) 758-6900

SERVICE ADVISOR: **18187 LEVI CAHILL**

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
	17	NISSAN ROGUE	KNMAT2MVOHP550802		29161 / 29161	T02
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
			11:00 12JUL19		110.88 CASH	12JUL19
R.O. OPENED	READY	OPTIONS: STK:1128171 DLR:2931 ENG:2.5_LITER TRN:AT				
09:47 12JUL19	15:18 12JUL19					

LINE	OPCODE	TECH	TYPE	A/HRS	S/HRS	COST	SALE	COMP	LIST	NET	TOTAL
A	56		POINT INSPECTION								
4	56		POINT INSPECTION								
		18425	IUT	0.48	1.00	864	10300			103.00	103.00
VERSION 1 (EMP# 18425,12JUL19 10:42): 29161 TEST DRIVE AND INSPECTION COMPLETED											
B	CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS										
1	CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS										
		18425	IUT	0.02	0.40	36	4120			41.20	41.20
5	88865701 OIL					1445	3100	0	6.20	6.20	31.00
1	15208-65FOE OIL FILTER					512	587	0	5.87	5.87	5.87
VERSION 1 (EMP# 18425,12JUL19 10:43): 29161 SERVICE COMPLETED											
EPA COMPLIANCE AND SHOP SUPPLIES											20.55

R.O.#: 688062

VIN.#: KNMAT2MVOHP550802

FOR QUICK, CONVENIENT SERVICE, RESERVATIONS FOR YOUR NEXT SCHEDULED MAINTENANCE IS NOT NEEDED BUT RECOMMENDED. CALL 319-752-6600 FOR YOUR NEXT SERVICE RESERVATION. WE WELCOME ALL WALK-IN CUSTOMERS.

WE WANT OUR CUSTOMERS 100% SATISFIED!

DATE	START	FINISH	DURATION	TYPE	TECH	LINE(S)	CHG
07-12-19	10:13	10:42	0.48	W	18425	A	
	10:42	10:43	0.02	W	18425	B	

  

ACCOUNT	SALE	COST	CONTROL	ACCOUNT	SALE	COST	CONTROL
46301	14420	900		48100	3687	1957	
66900	2055	0		24100	18107	*****	
24100	2055	*****	1128171				

COST, SALE, & COMP TOTALS 2857 20162 0

<b>WE HONOR OUR COMPETITORS COUPONS</b>	<b>WE HAVE COLLISION REPAIR</b>	<b>EXPRESS LUBE SERVICE</b>
<b>PARTS &amp; SERVICE HOURS MON. - FRI. 7:00 AM - 6:00 PM SAT. 7:00 AM - 5:00 PM</b>	<b>DISCOUNT RENTALS AVAILABLE</b>	

STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOR AMOUNT	\$ 0.00	
	PARTS AMOUNT	\$ 0.00	
	GAS, OIL, LUBE	\$ 0.00	
	SUBLET AMOUNT	\$ 0.00	
	MISC. CHARGES	\$ 0.00	
	TOTAL CHARGES	\$ 0.00	
	LESS	\$ 0.00	
	SALES TAX	\$ 0.00	
	CUSTOMER SIGNATURE		
	<b>PLEASE PAY THIS AMOUNT</b>	<b>\$ 0.00</b>	



# Your AutoCheck Vehicle History Report

Report run: 07/13/2019 17:08:11 EDT



2017 Nissan Rogue S / SL / SV  
SUV 4D (2.5L I4 MPI)

VIN: KNMAT2MV0HP550802  
Class: CUV - Entry Level  
Country of Assembly: South Korea  
Vehicle Age: 2 year(s)

This vehicle is eligible for Buyback Protection



Due to the vehicle's history showing no reported major state title brands. Click here for terms and conditions and to register your vehicle.

## YOUR VEHICLE AT A GLANCE

This vehicle's AutoCheck Score: 94

Other comparable 2017 vehicles in the CUV - Entry Level typically score between 89-94.

The AutoCheck Score is based on a vehicle's history such as vehicle class and age, number of owners, accident and damage history, title brands, odometer readings etc. This score is used to compare vehicle's favorability against the entire market of vehicles with the same scoring system.

- No State Title Brand Reported
- No Accident Reported  
*No Air Bag Deployed*
- No Other Damage Reported
- No Specific Event Reported
- No Odometer Problem(s) Reported  
*Last Odometer Reading: 3*
- No Open Recall(s) Reported

**ONE OWNER**  
Calculated Owners: 1

Owner History

Current Owner

Purchased: 2017  
 Where: IL  
 Owned from: 04/20/2017 - Present

Vehicle Usage



**Vehicle Use:** There is indication of the below usage(s) for this vehicle

Personal | Fleet | Rental | Lease | Taxi | Livery | Police | Government | Drivers Ed | Commercial

Major State Title Brand Check



**Your Vehicle Checks Out:** No major state title brand has been reported by the state Division of Motor Vehicles (DMV). Your vehicle is qualified for the AutoCheck Buyback Protection Program. Terms and conditions. Register here.



0 Problem(s) Reported

Major State Title Areas Checked



No fire brand



No hail, flood brand



No junk or scrapped brand



No manufacturer buyback



No lemon brand



No salvage brand



No rebuilt or rebuildable brand



No odometer brand (EML or NAM)

Accident Check



**Your Vehicle Checks Out:** AutoCheck has not received any accident records from government sources and independent agencies on this vehicle. Not all accidents are reported to AutoCheck.



**NO ACCIDENT**  
FOUND ON RECORD

Damage Check



**Your Vehicle Checks Out:** AutoCheck has not received a damage-related event from an auction or an independent source. Not all damage events are reported to AutoCheck. It is recommended to have pre-owned vehicles inspected by a third party prior to purchase.



**NO DAMAGE**  
FOUND ON RECORD

0 Problem(s) Reported

Other Problem Areas Checked



No non-title fire damaged record



No non-title hail or flood damaged record



No auction junk or scrapped record



No auction rebuilt or rebuildable record

0 Problem(s) Reported	Other Problem Areas Checked
<input checked="" type="checkbox"/>	No salvage auction record
<input checked="" type="checkbox"/>	No damaged or major damage incident record
<input checked="" type="checkbox"/>	No frame or structural damage record
<input checked="" type="checkbox"/>	No recycling facility record
<input checked="" type="checkbox"/>	No crash test record

**Other Title Brand And Specific Event Check**

**Your Vehicle Checks Out:** No Non-major state title brand(s) and/or additional significant event(s) has been reported to AutoCheck.

0 Event(s) Reported	Vehicle Events Checked
<input checked="" type="checkbox"/>	No Insurance Loss record
<input checked="" type="checkbox"/>	No Titled to an insurance company record
<input checked="" type="checkbox"/>	No Auction Lemon/Manufacturer Buyback record
<input checked="" type="checkbox"/>	No abandoned title record
<input checked="" type="checkbox"/>	No grey market title record
<input checked="" type="checkbox"/>	No loan/lien record(s)
<input checked="" type="checkbox"/>	No repossessed record
<input checked="" type="checkbox"/>	No corrected title record
<input checked="" type="checkbox"/>	No duplicate title record
<input checked="" type="checkbox"/>	No theft record(s)

**Odometer Check**

**Your Vehicle Checks Out:** No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

- State title odometer check
- Auction odometer check
- Odometer calculation check

0 Problem(s) Reported	Mileage	Date Reported
<input checked="" type="checkbox"/>	3	04/25/2017

**Open Recall Check**

**Your Vehicle Checks Out:** AutoCheck found no open recalls reported by the vehicle manufacturer. Not all open recalls are reported to AutoCheck.

**Detailed Vehicle History**

Below are the historical events for this vehicle listed in chronological order. Any discrepancies will be in bold text.

Report Run Date: 07/13/2019 17:08:11 EDT

Vehicle: 2017 Nissan Rogue S / SL / SV (KNMAT2MV0HP550802)

Event Date	Location	Odometer Reading	Data Source	Details
01/26/2017	IA		Independent Source	VEHICLE MANUFACTURED AND SHIPPED TO DEALER

Event Date	Location	Odometer Reading	Data Source	Details
04/20/2017	LOMAX, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
04/25/2017	LOMAX, IL	3	Motor Vehicle Dept.	TITLE(Title #:171156992540)
09/22/2017	LOMAX, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
11/07/2017	LOMAX, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
10/01/2018	LOMAX, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL

**This Vehicle's Glossary**

Below are the specific definitions for events that appear in this vehicle's report. More information is available in the full AutoCheck glossary.

Term	Section Location	Definition
Personal Use	Vehicle Use	This vehicle was driven for personal use.

**AutoCheck Terms and Conditions**

This report, and any reliance upon it, is subject to AutoCheck Terms and Conditions. If you obtained the report from a dealer, the dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at [www.autocheck.com/terms](http://www.autocheck.com/terms) or by writing to Experian Automotive C/O AutoCheck Customer Service 955 American Lane Schaumburg, IL 60173.

**Buyback Protection Terms and Conditions**

This vehicle (KNMAT2MV0HP550802) qualifies for AutoCheck Buyback Protection. If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at [www.autocheck.com/bbpterm](http://www.autocheck.com/bbpterm) or by writing to Experian Automotive C/O AutoCheck Customer Service 955 American Lane Schaumburg, IL 60173.

**About AutoCheck**

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

**Patent Notice**

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.